

Sheet1

ZEN WERKZ LLP

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK
SINGAPORE 415935
Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

ZHENG YONGSHUN
Blk 3 Kaki Bukit Road 1
#03-04 Eunos Technolink
Singapore 415935

TP Direct Asia

7th December 2017

Xiao Tony

JMSRCY2A84003912

Accident date: 05th DECEMBER 2017
Estimated repair cost for vehicle no: SJC7719E MITSUBISHI LANCER 1.5

S/n	Qty	Items	U/price	Amount
				\$593.00 X
1	1	Rear Boot Lid <i>Repair</i>		\$43.00 ✓
2	1	Rear boot lid Emblem logo		\$30.00 ✓
3	1	Rear Boot Lid Lancer Logo		\$55.00 ✓
4	1	Rear Boot Lid MIVEC Logo		\$28.00 ✓
5	1	Rear Boot Lid C&C Logo		\$50.00 ✓
6	1	Rear Boot Lid Number Plate		\$197.00 X 150
7	2	Rear Boot Lid Number Plate <i>hamp</i>	\$98.50	\$165.00 ✓
8	1	Rear Boot lid Inner lock		\$158.00 ✓
9	1	Rear boot lid inner rubber		\$516.00 X
10	2	Rear boot lid side reflector	\$258.00	\$778.00 X
11	2	Rear Tail Lamp	\$389.00	\$32.00 X
12	4	Rear tail lamp clips	\$8.00	\$250.00 X
13	2	Rear Tail Lamp Panel	\$125.00	\$674.00 ✓
14	1	Rear Bumper		\$134.00 ✓
15	2	Rear Bumper Side Bracket	\$67.00	\$198.00 ✓
16	1	Rear Bumper Center Beam		\$176.00 ✓
17	2	Rear Bumper side reflector	\$88.00	\$65.00 30
18	10	Rear Bumper Clips	\$6.50	\$350.00 20 (50)
19	1	Rear Bumper Reverse Sensor		\$285.00 ✓
20	1	Rear Bumper reinforcement		\$398.00 ✓
21	1	Rear End Panel		\$181.00 ✓
22	1	Rear End Panel Top Garnish		\$65.00 X
23	10	Rear Fender Inner Trim Board Clips	\$6.50	\$225.00 X
24	1	Rear Spare Tyre Panel Top Cover		

2004
180360

S.N. 220

Subtotal :-

\$5,646.00

Labour charges

To remove & refix cushion

~~\$120.00~~ 40

To Remove & refix reverse sensor

~~\$100.00~~ 50

Tuff kote

~~\$120.00~~ 30

To check wiring

~~\$80.00~~ 30

Panel beating

1350

~~\$1,000.00~~ 600

Spray painting

~~\$1,000.00~~ 600

Subtotal :- \$2,420.00

Total:- \$8,066.00

total: 3373.60

h/s: 2.7K
05 days

2.7K
05 days