

SERVICE ESTIMATE

89968 - C00001
 Mr Ng Wei Gee
 3 Bishan Street 15
 #31-18

SL: SERVICE SALES - PC

Singapore 573911

Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Mr Ng Wei Gee

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 01/12/2017
 WIP No. . : 32362
 Veh.In/Out:
 *Tel.No. . : Mobile: 92384369
 Reg.No. . : SGW24C
 Reg.date . : 31/05/2017
 Mileage .. : 0
 Chassis No: YV1PS10BDH1011170

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER , TOW COVER, LH REAR FENDER REVESTING SENSOR LH REAR, TAILLAMP LH REAR	0	2400.00	0		2,400.00 S	800
800	TO PUTTY & SPRAY FRONT BUMPER LH REAR FENDER ,	0	2100.00	0		2,100.00 S	700
280	TO CHECK WIRING INCLUDING RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	
	BUMPER COVER REAR S9	1.0 EA	1412.30			1,412.30 S	DF
	TOW COVER REAR S90 1	1.0 EA	62.40			62.40 S	X
	PROTECTING PLATE REA	1.0 EA	253.30			253.30 S	?
	BUMPER BRACKET LHR S	1.0 EA	46.70			46.70 S	rec
	BUMPER BRACKET RHR S	1.0 EA	46.70			46.70 S	X
	BUMPER BRACKET REAR	1.0 EA	79.20			79.20 S	?
	BUMPER RETAINER LHR	1.0 EA	28.60			28.60 S	rec
	BUMPER RETAINER RHR	1.0 EA	28.60			28.60 S	X

SERVICE ESTIMATE

89968 - C00001
 Mr Ng Wei Gee
 3 Bishan Street 15
 #31-18

Singapore 573911

Closed by : Mandy Neo
 Svc Consultant :
 Remarks : Mr Ng Wei Gee

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 01/12/2017

WIP No. . : 32362

Veh.In/Out:

*Tel.No. . : Mobile: 92384369

Reg.No. . : SGW24C

Reg.date. : 31/05/2017

Mileage . : 0

Chassis No: YV1PS10BDH1011170

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAILLAMP LH S90 17-	1.0 EA	420.40			420.40	S <i>CRA</i>
	SENSOR	1.0 EA	130.30			130.30	S <i>?</i>
	PARKING AID REAR OUT	1.0 EA	175.20			175.20	S <i>?</i>
	BUMPER RAIL	1.0 EA	1304.80			1,304.80	S <i>?</i>
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00	S <i>ne</i>
	BUMPER CLIP	10.0 EA	4.80			48.00	S <i>ne</i>
	PLASTIC RIVET P/W RA	10.0 EA	6.90			69.00	S <i>ne</i>
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S <i>ne</i>
	EXTERIOR ADHESIVE GL	1.0 EA	142.20			142.20	S <i>ne</i>

RASUL
Hp 90010068
3 days
19/12/17 @ 1210

Reg sep part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour Total 4,950.00
 Parts Total 4,361.10
 Package Total 0.00
 Date:

Gross Total. 9,311.10
 Net..... 9,311.10
 GST @ 7.0% 651.78
 Total..... 9,962.90
 Paid..... 0.00
 Please Pay.. 9,962.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated