

ASS. REC. BY:

REF: CS/FCU7023297/Ribon2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): CWS Karen Tan of FCL Date/Time: 07-12-2017 3:18pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 9944K Insured: SHD 3776J

at Workshop m/s Cycle & Carriage Klu Tel: 9144 9137

of 209 Pandan Garden

Policy No: Claim No: D170 11288MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 06/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 12.12.2017 @ 11am H.O.D. Endorsement:

Date/Time: 07-12-2017 3:31pm Person Contacted: Andre Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 9944K - X
	SHD 3776J - CS/FCU15013321 / Ribon1 DA: 030815
	Confirm \$2284.00 @ 3 day
	Red: \$4309.00, 65%

P. P. P.

REF: FCL

04814

ASSIGNMENT

From: _____ Date: 12/2/2017

Estimated Cost: _____

OD / P WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 9944K

at Workshop m/s: Cycle & Carriage

of: 209 Pandan Garden

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Amal

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: SLQ 9944K Yr Regn: 2017 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA CARENS 1.7 DCR C.C. 1628

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 7268 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA HU815 VH 7177679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/452R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ROADSTONE

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 06/12/17 D.O.I. 12/12/17

Survey held at: C8C C/P

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 04 JUN 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) Accepted ☒ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format: 1P

Lump Sum / 121: (\$ 2284.00)

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Photos: _____

Charts: _____

Total: 278

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023297/R1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3776J	Veh. Inspected	SLQ 9944K
Policy No.		Coverage (\$)	0.00
Claim No.	D17011288MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	07/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2017	Inspection Date	12/12/2017
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-12-2017	Our Ref No. D17011288MFSH
Accident Date	06-12-2017	Claim Type. Third Party
Insured Vehicle	SHD3776J	Third Party Vehicle. SLQ9944K
Survey Location	209 PANDAN GARDENS	
Contact Person.	ANDRE CHOW	
Contact No.	65684555/ 91449137	Fax No. 65691056
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231563)



PRI Documents



Close X

PRI Header Details

Claim No	D17011288MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CY LTD
Workshop Name	CYCLE & CARRIAGE KIA PTE LTD (Contact Person : ANDRE CHOW)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 91449137 , Phone: 65684555 , Fax: EmailId: ANDRE.CHOW@CYCLECARRIAGE.CO		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3776J	TP Vehicle No	SLQ99
PRI Recieved Date	06-12-2017 09:40:26 PM	Surveyor Appointed Date	07-12-2017 03:18:08 PM	Surveyor Accept Date	07-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-12-2017	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Janice Lee (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, May 28, 2018 10:21 AM
To: Lauro Araos Songcuan Jr; Rasul (LKKAUTO); Janice Lee (LKKAUTO)
Cc: Andre Chow En De; Loi Ai Ting; Cheng Jo Jo; Yusof Bin Hashim; Admin A
Subject: FW: Finalisation SLQ9944K (CCK)
Attachments: DSCF5671.JPG; DSCF5672.JPG; DSCF5673.JPG; [Untitled].pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CS/FCI17023297/R1rb	Rasul / Janice

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr [mailto:lauro.songcuan@cyclecarriage.com.sg]

Sent: Friday, 25 May 2018 11:32 AM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>

Subject: FW: Finalisation SLQ9944K (CCK)

Dear Sir/Madam,

Can we have your confirmation on the finalized amount of \$ **2,284.00** before Gst.

Thank you so much for your kind understanding on this matter.

Best regards,

Larry Songcuan

Customer Service

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339

T: +65 6568 4658 • F: +65 6565 1240 • www.cyclecarriage.com.sg

-----Original Message-----

From: Andre Chow En De

Sent: 26 March 2018 09:56

To: Rasul (LKKAuto)

Cc: Loi Ai Ting; Lauro Araos Songcuan Jr

Subject: Finalisation SLQ9944K (CCK)

Dear Rasul,

Pls. refer to attached files.

Kindly confirm finalised amount of \$2,284.00 before GST for SLQ9944K.

Best Regards,

Andre Chow

Asst Manager – Aftersales Operations

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339

T: +65 6568 4501 • F: +65 6565 1240 • H: +65 9144 9137 • www.cyclecarriage.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR TAN SAY YAM JOSIAH	Cust No/Name	/MR TAN SAY YAM JOSIAH
BLK 79B TOA PAYOH CTRL #34-17 SINGAPORE 312079	Reg No/Reg Date	SLQ9944K / 28/07/201
Contact No Mobile: 90883524	Date In/Mileage	/ 0
	Chassis No	KNAHU815VH7177679
	Engine No	D4FDHH102741
	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim	9H BLACK CHERRY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	06/12/2017/ 15:33	QUA	265 / AndreChow	19273
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REMOVE AND INSTALL REVERSE SENSORS				60 150.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 100.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
E PNT88000	RENEW REAR BUMPER, REAR BUMPER REINFORCEMENT, REPAIR REAR END PANEL (Chuk) AND REALIGN TO THE SAME				550 2750.00
E PNT98000	RESpray REAR BUMPER, REAR END PANEL AND OTHER AFFECTED PORTIONS				420 1260.00
M SUNDRY	SUNDRIES				30 50.00
M SUNDRY	SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS				40 80.00
M COVER-RR BUMPER,UPR		1.00	576.00	00.00	576.00
P COVER-RR BUMPER LWR		1.00	189.00	00.00	189.00
M BEAM-RR BUMPER		1.00	367.00	00.00	367.00
M STAY-RR BUMPER LH		1.00	159.00	00.00	159.00
M STAY-RR BUMPER RH		1.00	159.00	00.00	159.00
M BRACKET ASSY-RR BUMPER SIDE,LH		1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE,RH		1.00	25.00	00.00	25.00
M SKID PLATE-RR BUMPER		1.00	179.00	00.00	179.00
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	162.00	00.00	162.00
M ULTRASONIC SENSOR ASSY-P.A.S		1.00	162.00	00.00	162.00

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

Confirm & accepted by

REMARKS :

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party supply must be resurveyed
- No illegal modification(s) is allowed
- Supplemental parts must be resurveyed

7% GST on 6593.00 Without Prejudice 461.51

Total Payable 7054.51

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

VEHICLE NO : SLQ9944K

MODEL : Carens

WIP : 19273

Material	:	\$	<u>994.00</u>
Labour	:	\$	<u>1290.00</u>
Sub-Total	:	\$	<u>2284.00</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2284.00</u>
GST 7%	:	\$	<u>159.88</u>
Grand Total	:	\$	<u>2443.88</u>
Finalise By/Date	:	<u>Andre 26/3/18</u>	




REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK _____ WORKING DAYS



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR TAN SAY YAM JOSIAH	Cust No/Name /MR TAN SAY YAM JOSIAH
BLK 79B TOA PAYOH CTRL	Reg No/Reg Date SLQ9944K / 28/07/2017
#34-17	Date In/Mileage 12/12/2017/ 7268
SINGAPORE 312079	Chassis/Package KNAHUB15VH7177679 /KC17S3
Contact No *Mobile: 90883524	Engine No D4FDHH102741
12/12/	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim 9H BLACK CHERRY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	26/03/2018/ 09:49	TLA	265 / AndreChow	19273			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								60.00
REMOVE AND INSTALL REVERSE SENSORS								30.00
A 54900099								200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								550.00
A 10028901								420.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								30.00
USING HI-SCAN PRO TEST								
E PNT88000								576.00
RENEW REAR BUMPER AND REALIGN TO THE SAME								189.00
E PNT98000								25.00
RESPRAY REAR BUMPER AND OTHER AFFECTED PORTIONS								25.00
M SUNDRY								179.00
SUNDRIES								
X	COVER-RR BUMPER,UPR				1.00	576.00	00.00	576.00
X	COVER-RR BUMPER LWR				1.00	189.00	00.00	189.00
X	BRACKET ASSY-RR BUMPER SIDE,LH				1.00	25.00	00.00	25.00
X	BRACKET ASSY-RR BUMPER SIDE,RH				1.00	25.00	00.00	25.00
X	SKID PLATE-RR BUMPER				1.00	179.00	00.00	179.00
"Guarantee your warranty, maintain with Cycle & Carriage."								
Parts	994.00					Nett		2,284.00
Labour	1,260.00					7% GST on	2284.00	159.88
Standard Menu	0.00							
Specialist Job	0.00					Total Payable		2,443.88
Diagnostics Job	0.00							
Sundry/Others	30.00							
Total(w/o GST)	2,284.00							

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023297/R1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3776J	Veh. Inspected	SLQ 9944K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011288MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	07/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS 1.7 DCT	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAHU815VH7177679	Colour	BLACK	
Odometer	7268	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 ZR17	ROADSTONE	6 mm	
L/H Front Tyre	225/45 ZR17	ROADSTONE	6 mm	
R/H Rear Tyre	225/45 ZR17	ROADSTONE	6 mm	
L/H Rear Tyre	225/45 ZR17	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2017	Inspection Date	12/12/2017	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9944K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER,UPR (SN)	DEFORMED	576.00	576.00
1	COVER-RR BUMPER,LWR (SN)	SCRATCHED	189.00	189.00
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	367.00	-
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	159.00	-
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	159.00	-
1	BRACKET ASSY-RR BUMPER SIDE,LH (SN)	NECESSARY	25.00	25.00
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	NECESSARY	25.00	25.00
1	SKID PLATE-RR BUMPER (SN)	SCRATCHED	179.00	179.00
1	ULTRASONIC SENSOR ASSY-P.A.S (SN)	NOT NECESSARY	162.00	-
1	ULTRASONIC SENSOR ASSY-P.A.S (SN)	NOT NECESSARY	162.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			2,053.00	1,024.00
LABOUR				
	REMOVE AND INSTALL REVERSE SENSORS.		150.00	60.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		100.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	RENEW REAR BUMPER,REAR BUMPER REINFORCEMENT,REPAIR REAR END PANEL AND REALIGN TO THE SAME.		2,750.00	550.00
	RESPRAY REAR BUMPER,REAR END PANEL AND OTHER AFFECTED PORTIONS.		1,260.00	420.00
	SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS.	NOT NECESSARY	80.00	-
			4,540.00	1,260.00
GRAND TOTAL			6,593.00	2,284.00
RECOMMENDED COST OF REPAIRS				2,284.00

Report Ref No. CS/FC117023297/R1rnb2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.