

15/5/2010

CC 6 / CTI1702 3298, A W352

LKK:  
IDAC:

INS. CASE OWNER:

## ASSIGNMENT

Surveyor:

Adnan

DOI:


9/12/18

Date / Time:

9/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

8KJ 9127B

Name of Insured:

M YONG TENG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

05/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN HIEW PENH

Driver Tel No.:

(V/L/YES/NO)

Claim No.:

SNM1700697202

Policy No.:

DMP6SN157001702

Make / Model:

AUDI

Place of Accident:

ENTERING UP OF SANTEC LENS.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

CEB 59372



INSRS:

WSP:

Tel:

Liability:

RMKS:

mg solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

14/11/18  
LTC8KJ 9127B - 14/11/18  
8KJ 9127B - X  
- REQ. TP CCTV  
- PINKUSO.  
- SMALL LIABILITY UNCLER.

16/01/18

- TP REPORT MUST.  
- REPORT DONE.  
- TP CCTV IN. V. DRIVE / VIC / 8KJ 59372  
- TO LOW IN THE SMALL  
- 2018 SMALL TO OI UNCLER APPROVAL

27/03/18

29/03/18

12/04/18

18/04/18

- OI APPROVED UNCLER.  
- SEND SET OFFER TO TP  
- TP ACCEPTED OFFER.  
- RECEIVED ORIG. DOCS.  
- ALL IN ORDER.  
- TO CLOSE.

## STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

27/03/18 - OK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation to Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

## PRELIMINARY ADVICE

Date/Time:

16/01/18

Sent By:

VIC

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L9

SS

3,600.00

4 days

Reduction:

60 %

Email

Call

## FINAL SETTLEMENT

Date/Time:

16/04/18

Confirm with

50

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

(w/gar)

SS

3,905.50

Loss of Rental (LOR):

SS

-

( days)

Loss of Use (LOU):

SS

360.00

(S 60 x 6 days)

Loss of Income (LOI):

SS

-

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

LTA Search

SS

5.35

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow / Independent)

Legal Cost

SS

-

Total:

SS

4,270.00

Global Sum SS:

4,270.00

Email

Call

## FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,270.00

Name 1:

MG SOLUTION

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4400.00

COPY SENT  
14/4/18

REF:

## ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 10 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKB5937Z Yr Reg: 06 1/Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Cruze C.C. 1598Colour: Beige A/C Insured / Std / NI / NASp. Reading: 138515 T. Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KL1JA69E9B K174439Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SCORPA

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 07/12/17Survey held at M& Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China.Wb \$3,650.00 with 4 days(K&B: \$5,101.93 / 60%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Phone: \_\_\_\_\_

Photo: \_\_\_\_\_

Others: \_\_\_\_\_

Add Fee: ☐ Site Insp. (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI17023298/Ahb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 07-12-2017	
			Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKJ 9127B	Veh. Inspected	SKB 5937Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	05/12/2017	Inspection Date	07/12/2017	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM17D06973C02  
Our ref: CC6/CTI17023298/Ahb3

Date: 16.01.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SKB 5937Z**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.12.2017 at the premises of M/s MG SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	9,051.93
Revised Estimate Amount	: S\$	4,575.43
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Front N/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

ADRIAN LING  
Licensed Appraiser

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : CHINA TAIPING DATE : 6-Dec-17  
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM  
ESTIMATE REPORT :

## VEHICLE DETAILS

VEHICLE NO : SKB 5937Z  
MODEL : CHEVROLET CRUZE 1.6L A *Vic*

CHASSIS NO

ACCIDENT DETAILS DATE : 5-Dec-17  
TIME : 11:50HRS

THIRD PARTY REQUESTOR / CONTACT : DEON

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deformed</i>	1	\$ 930.00	\$ 930.00 ✓
2	FRONT BUMPER SIDE RETAINER <i>new</i>	1	\$ 72.50	\$ 72.50 ✓
3	HEADLAMP LH <i>cracked</i>	1	\$ 711.20	\$ 711.20 ✓
4	HEAD LAMP LOWER BRACKET LH <i>new</i>	1	\$ 60.00	\$ 60.00 +
5	FRONT FENDER LH <i>Dented.</i>	1	\$ 912.00	\$ 912.00 ✓
6	FRONT FENDER INNER COWLING LH <i>ton</i>	1	\$ 133.00	\$ 133.00 ✓
7	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 375.00	\$ 375.00 +
8	FRONT WHEEL HUB LH <i>Damaged.</i>	1	\$ 517.00	\$ 517.00 ✓
9	FRONT LOWER ARM LH <i>gap</i>	1	\$ 647.00	\$ 647.00 +
10	FRONT KNUCKLE ARM LH <i>gap</i>	1	\$ 303.00	\$ 303.00 +
11	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 197.00	\$ 197.00 ✓

347270

312543

TOTAL PRICE \$ 4,857.70

LESS 10% \$ 485.77

SUB TOTAL PRICE \$ 4,371.93

## SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
2	FRONT FENDER SEALANT <i>Not New</i>	1	\$ 120.00	\$ 120.00 ✗

3	FRONT FENDER INNER COWLING CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	FRONT WHEEL TYRE (SET) <i>Not New</i>	1	\$ 550.00	\$ 550.00	+
5	FRONT WHEEL RIM (SET) <i>lit</i>	1	\$ 800.00	\$ 800.00	400

440

TOTAL \$ 1,510.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	<del>\$1,200.00</del>	400	
2	SPRAY PAINTING TO AFFECTED AREA	<del>\$1,200.00</del>	400	
3	WIRING CHECK	<del>\$100.00</del>	30	
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	<del>\$550.00</del>	100	
5	FOUR WHEEL ALIGNMENT	<del>\$120.00</del>	80	

TOTAL

\$3,170.00

1010

#### ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,881.93

TOTAL LABOUR COST : \$ 3,170.00

TOTAL REPAIR COST : \$ 9,051.93

#### APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian L  
L/s 07/12/17.

04 days

total: 4575.43

r/s: 3650

3650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Shu Pei (LKKAUTO)**

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 13 December, 2017 11:33 AM  
**To:** Shu Pei (LKKAUTO)  
**Subject:** CTP REF NO.SNM17D06973C02 LKK REF NO. CC6/CT117023298 - ACCIDENT INVOLVING SKJ9127B AND SKB5937Z ON 05 DECEMBER 2017  
**Attachments:** TayHP\_CLCR95.979.pdf; GIA REPORT SKJ9127B.pdf

**WITHOUT PREJUDICE**

Dear Sir/Mdm,

We refer to the above matter and your email dated 11 December 2017.

We enclosed herewith a copy of our Insured GIA Report & Letter to our Insured for your attention.

Regards,

**Irene Tay**

Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389-6192  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM17D06973/C02/7**

Date : **13 DECEMBER 2017**

via Ordinary & Registered Mail

**NG YONG TENG  
6 ENG KONG GARDEN**

**SINGAPORE 599223**

Dear Sir / Madam

**ACCIDENT INVOLVING SKJ9127B AND SKB5937Z ON 05 DECEMBER 2017  
ALONG SUNTEC CITY ENTRANCE CARPARK**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKB5937Z**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : VIC

Ref : CC6/CTI17023298

Contact No : 68412096

via Email : SHUPEI@LKKAUTO.COM

CC : Agent - (AN0412A) - SAFE HARBOUR ENSURANCE

F01/LKKDS-2013



## Vic (LKKAUTO)

---

**From:** MG Solution <mg3solution@gmail.com>  
**Sent:** Tuesday, 17 April, 2018 3:32 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A; Asher Sng (LKKAUTO)  
**Subject:** Re: Your Ref: SKB 5937Z\_ACCIDENT INVOLVING VEHICLES SKJ 9127B AND SKB 5937Z ON 05/12/2017 LKK REFCC6/CTI17023298/Ahb3s2  
**Attachments:** DV for SKB5937Z.pdf; TI189096 for SKB5937Z (SMG188034).pdf

Your Ref: **CC2/CTI17023298/Ahb3 (SKJ9127B)**  
Our Ref: **SKB5937Z**

Dear Vic,

Please find attached **TAX INVOICE** and our duty signed **DV** by our client for your kind onward action.  
Original copy will sent to you by post.

Best Regards,

**Su Wong**  
**MG SOLUTION PTE LTD**  
No 23 Kaki Bukit Avenue 4  
AAS Kaki Bukit Centre  
#02-03B Singapore 415933  
Tel: 6243 1373 | Fax: 6243 1376

On Thu, Mar 29, 2018 at 12:04 PM, Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)> wrote:

Without Prejudice

Dear Su Wong,

We refer to your below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we offer a global sum of **\$4,270.00** (all in) to settle your client's claim.

If agreeable, kindly let the owner sign the enclosed DV then forward to us a the original hard copy together with the LOD, Authorization to Act Letter, Final Repair Invoice and all supporting documents for payment processing.

The above amount is to be made payable to **MG SOLUTION PTE LTD.**

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Tuesday, 27 March, 2018 11:33 AM

**To:** MG Solution

**Cc:** Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)

**Subject:** RE: Your Ref: SKB 5937Z\_ACCIDENT INVOLVING VEHICLES SKJ 9127B AND SKB 5937Z ON 05/12/2017 LKK REFCC6/CTI17023298/Ahb3s2

Without Prejudice

Dear Su Wong,

We refer to your below email.

Please be informed that we are in the midst of seeking mandate approval to our principal.

We will expedite and will get back to you for an update.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** MG Solution [<mailto:mg3solution@gmail.com>]

**Sent:** Tuesday, 27 March, 2018 9:15 AM

**To:** Vic (LKKAuto)

**Cc:** Admin A; Asher Sng (LKKAuto)

**Subject:** Re: Your Ref: SKB 5937Z\_ACCIDENT INVOLVING VEHICLES SKJ 9127B AND SKB 5937Z ON 05/12/2017

Your Ref: **CC2/CTI17023298/Ahb3 (SKJ9127B)**

Our Ref: **SKB5937Z**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17023298/Ahb3s2

3 ANSON ROAD #16-00

SPRINGLEAF TOWERSINGAPORE 079909

Date : 19-04-2018

Code : CTI



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 9127B	Veh. Inspected	SKB 5937Z
Policy No.	DMPCSN1520071702	Coverage (\$)	0.00
Claim No.	SNM17D06973C02/7	Excess (\$)	0.00
Assign From		Assign Date	07/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KL1JA69E9BK174439	Colour	BEIGE
Odometer	138515	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	ECOPIA	6 mm
L/H Front Tyre	205/60R16	ECOPIA	6 mm
R/H Rear Tyre	205/60R16	ECOPIA	6 mm
L/H Rear Tyre	205/60R16	ECOPIA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	05/12/2017	Inspection Date	07/12/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 5937Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	930.00	930.00
1	FRONT BUMPER SIDE RETAINER	NECESSARY	72.50	72.50
1	HEADLAMP LH	CRACKED	711.20	711.20
1	HEAD LAMP LOWER BRACKET LH	NOT NECESSARY	60.00	-
1	FRONT FENDER LH	DENTED	912.00	912.00
1	FRONT FENDER INNER COWLING LH	TORN	133.00	133.00
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	375.00	-
1	FRONT WHEEL HUB LH	DAMAGED	517.00	517.00
1	FRONT LOWER ARM LH	NOT NECESSARY	647.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	303.00	-
1	FRONT KNUCKLE ARM BEARING LH	NECESSARY	197.00	197.00
	LESS 10% DISCOUNT		-485.77	-347.27
			4,371.93	3,125.43
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT FENDER SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET FRONT FENDER INNER COWLING CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT WHEEL TYRE (SN)	NOT NECESSARY	550.00	-
1	SET FRONT WHEEL RIM (SN)	CUT	800.00	400.00
			1,510.00	440.00
<b><u>LABOUR</u></b>				
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,200.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	400.00
	WIRING CHECK.		100.00	30.00
	REMOVE AND REFIX FRONT UNDERCARRIAGE.		550.00	100.00
	FOUR WHEEL ALIGNMENT.		120.00	80.00
			3,170.00	1,010.00
<b>GRAND TOTAL</b>			<b>9,051.93</b>	<b>4,575.43</b>

Report Ref No. CC6/CTI17023298/Ahb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00
---	--	--	----------

Report Ref No. CC6/CTI17023298/Ahb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.