

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 20 Dec 2017

## **Preliminary Advice**

Insured Vehicle No : SKH3074U

TP Vehicle No : SJZ9009L

Make : MERCEDES-BENZ A200

Date of Inspection : 19/12/2017

Inspection At : CYCLE & CARRIAGE INDUSTRIES (1986) PL

Accident Date : 05/12/2017

Assignment Date : 19/12/2017

Est. Duration of Repair : 4/Days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...O/S Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,367.04
Revised Amount	:S\$	2,562.89
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,562.89

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.