



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SJZ9009L

Lee Zhen Jesica (li Zhen Jesica)

6 Whampoa East  
#08-12 Eight Riversuites  
Singapore 338519

### Vehicle & Document Information

WIP No **19389**  
Reg No/Reg Date **SJZ9009L / 20/03/2017**  
Date In/Mileage **/ 0**  
Chassis No **WDD1760432J510399**  
Engine No **27091031066066**  
Make/Model **MB/MB A 200 (W176) "STYLE"**  
Colour/Trim **026 650 Cirrus Whit/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator				
WCV29307	CRDVCH	06/12/2017/ 15:37	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A BPIRES								<del>1200 1800.00</del>
RESPRAY ON RIGHT REAR FENDER, REAR BUMPER								<del>760 1920.00</del>
A BPILAB								
PANEL BEATING ON RIGHT REAR FENDER, REAR BUMPER								
M BPNSUN								
POLICY NO/ACC DATE : 2100503923 // 05.12.17								
DRIVE IN/EXCESS : 06.12.17 // TP CAR NO.:SKH3074U-FWD INS.								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB							0.10	380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
M RIGHT REAR MOUNTING RAIL					1.00	22.89	00.00	22.89
M REAR BUMPER					1.00	1244.15	00.00	1244.15

ESTIMATE

Rasul  
Hy 90010068  
4 days  
19/12/17 P1440  
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett **5,367.04**  
7% GST on **5367.04** **375.69**  
**Total Payable 5,742.73**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg