



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



LONPAC INSURANCE BHD		NAME :	MS TAN SZE LING	WIP :	14984
100 BEACH ROAD		ADDRESS :	19A NALLUR ROAD	EXCESS :	
#19-00, SHAW TOWER			SINGAPORE 456636	DATE:	6-Dec-17
SINGAPORE 189702					
ATTN. :	MOTOR CLAIMS	TEL :	98363977		
FAX :					

VEH NO :	SLN3665X	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWYS920703B64844	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COUNTRYMAN F60	DATE REG.:	24-Aug-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
		QTY			
1	REAR BUMPER ✓ Deform	1	M51.12.7.389.377		\$ 2,038.74
2	REAR BUMPER TOW COVER ✓ MS	1	M51.12.7.389.350		\$ 107.46
3	REAR BUMPER SPOILER ✓ Cut	1	M51.12.7.391.199		\$ 286.68
4	REAR BUMPER SPOILER GARNISH ✓ MS	1	M51.12.7.411.083		\$ 222.72
5	REAR BUMPER MOUNT CENTRE ✓ CRK	1	M51.12.7.401.870		\$ 42.84
6	REAR BUMPER MOUNT HOLDER ✓ NEC	1	M51.12.7.482.914		\$ 22.32
7	REAR BUMPER GUIDE LH ✓ NEC Deform	1	M51.12.7.389.357		\$ 236.94
8	REAR BUMPER GUIDE RH ✓ NEC CRK	1	M51.12.7.389.358		\$ 236.94
9	REAR BUMPER BLIND RIVET ✓ NEC	2	B51.24.8.226.003		\$ 9.36
10	REAR BUMPER FASTENER ✓ NEC	4	B51.12.7.461.407		\$ 14.64
11	REAR BUMPER RIVET ✓ NEC	4	M07.14.9.807.127		\$ 4.32
12	REAR BUMPER COMBINATION CLIP ✓ NEC	10	B07.14.7.305.178		\$ 16.80
13	REAR BUMPER REINFORCEMENT ✓ DT	1	M51.12.7.389.375		\$ 483.30
14	REAR BUMPER REINFORCEMENT GASKET ✓ NEC	2	B51.12.7.300.789		\$ 10.56
15	HEAT INSULATOR REAR ✓ Deform	1	M51.48.7.391.380		\$ 59.46
16	HEAT INSULATOR ✓ Deform	1	M51.48.7.392.646		\$ 127.20
17	ULTRASONIC SENSOR GASKET ✓ NEC	4	B66.20.9.283.203		\$ 23.76
18	ULTRASONIC SENSOR ✓ DMC	2	B66.20.9.274.428		\$ 582.36
19	REAR EXHAUST ✓ BT (Rear)	1	M18.30.8.627.279		\$ 1,012.32
20	REAR EXHAUST CHROME ✓ SCR	2	M18.30.8.654.203		\$ 213.84
21	EXHAUST PIPE (Centre) ✓ BT	1	B18.30.8.627.213		\$ 1,252.38
22	EXHAUST GASKET ✓ NEC	1	B18.30.8.632.362		\$ 50.16
23	EXHAUST CLAMP ✓ NEC	1	B18.30.7.536.426		\$ 72.72
24	EXHAUST MOUNT ✓ NEC	2	B18.30.7.616.850		\$ 40.92
25	EXHAUST BRACKET ✓ NEC	2	M18.30.8.673.214		\$ 133.92
TOTAL PARTS					\$ 7,302.66
					\$ -
TOTAL PARTS COST					\$ 7,302.66

Labour Description				
1	TO REPLACE REAR BUMPER. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	840/day		\$ 2,520.00
				2100

2	TO RESPRAY REAR BUMPER AND REAR END PANEL. 800 / panel		\$ 1,800.00	
			1200	
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	250 ?	\$ 350.00	
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00	
			150	
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 500.00	X
6	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 2,100.00	
			1680	
7	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00	X
8	TO TRANSFER THE REVERSE SENSORS.		\$ 500.00	
			420	
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00	
			180	
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00	
			280	
11	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 200.00	✓
12	SUNDRIES.	NETT	\$ 100.00	
			50	

TOTAL LABOUR	\$ -	\$ 9,480.00
TOTAL PARTS	\$ -	\$ 7,302.66
TOTAL	\$ -	\$ 16,782.66
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian.
8/12/2017.

- Part by part repair.

- Photo Before Paint

90036121

sebastianyeang@lkkauto.com.

7 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--