

Date : 06/12/2017

Asher.

TO: **AIG Asia Pacific Insurance Pte Ltd**  
AIG Building  
78 Shenton Way #07-16  
Singapore 068811

Our Customer : Ng Hock Guan  
Vehicle No : SLM894B  
Model : Toyota Altis 1.6 CVT

Manufacture Year : 2016

Date of Accident : 05/12/2017

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claims Department  
Fax : 6415 3727

Re: Repair Estimate For Third Party Claim against GBE7517E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Rear door RH <i>Ryis</i>	1	\$1,185.00	\$1,185.00	X.
2	Rear door weatherstrip RH <i>new</i>	1	\$174.00	\$174.00	X
3	Rear fender RH <i>Ryis</i>	1	\$1,095.00	\$1,095.00	+
4	Rocker panel RH <i>new</i>	1	\$367.00	\$367.00	+
5	Rear absorber RH <i>new</i>	1	\$200.00	\$200.00	+
6	Rear wheel bearing RH <i>new</i>	1	\$670.00	\$670.00	+
7	Rear axle <i>new</i>	1			+
	<b>Total</b>			<b>\$3,691.00</b>	
	Less 25%			<b>\$922.75</b>	
	<b>Sub Total 1</b>			<b>\$2,768.25</b>	
<b>A.</b>	<b>Spare Parts (S/Nett)</b>				
1	Rear tyre RH <i>new</i>	1	\$550.00	\$550.00	+
2	Rear sports rim RH <i>450</i>	1	\$450.00	\$450.00	✓
3	Selant <i>new</i>	1	\$60.00	\$60.00	+
	<b>Sub-Total 2</b>			<b>\$1,060.00</b>	
	<b>Total for Parts</b>			<b>\$3,828.25</b>	
<b>B.</b>	<b>Labour</b>				
1	To check wiring.			\$50.00	X.
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	200
3	Spray painting all affected parts & areas.			\$800.00	400
4	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repair.			\$250.00	X.
5	To remove and replace rear undercarriage RH.			\$250.00	+
6	To check and align wheels with computerized wheel alignment.			\$120.00	80
7	To remove and refit rear windscreen glass.			\$120.00	+
8	To remove and refit rear door glass RH.			\$100.00	+
9	To spray anti-rust undercoat.			\$60.00	+
	<b>Total Labour</b>			<b>\$2,550.00</b>	
	<b>Total Repair Cost</b>			<b>\$6,378.25</b>	

680



Co. Reg. No.: 201416720C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel : 6636 9100 Fax : 6636 9113

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
2/s 07/12/17.  
03 Days

total: 1130  
2/s: 800 ✓

Yours faithfully,

\_\_\_\_\_  
Aun Teng  
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No