

ECICS-4Sum

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305095702
 REGN NO : SHC7818B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 18.07.2013
 DATE/TIME IN : 07.12.2017 11:45
 ACCIDENT DATE : 06.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0001-G	REAR BUMPER	1	578.40	20.00	462.72	X Repair
0002 04-01-0101-0014-G	REAR BUMPER UNDER COVER	1	185.80	20.00	148.64	X
0003 04-01-0101-0111-A	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	X
0004 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	2.00	135.70	X

SUB-TOTAL : 764.66

JOB NATURE

0000 L	PANEL BEATING	280.00	100
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	180
0002 L	R/I REVERSE SENSOR	120.00	X

SUB-TOTAL : 600.00

TOTAL : 1,364.66

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hereby notify the Repairer in the following:

- To reserves before repair spray painting
- To display damaged parts during resurvey
- Parts prices are not for information
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplier of the items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K. Lim LKK

7/12/17 1520hrs

2 days

45

After Repair photo