

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 9933G

DATE 5/12/2017 10:46

MAKE :

MODEL : HYUNDAI IONIC

Chang

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 459.40
	Rear Bumper Reinforcement <i>X</i>			\$ 294.80
	Rear Bumper Clip			\$ 138.10
	Rear Bumper Stay LH/RH <i>X</i>			\$ 270.00
	Rear Bumper Under Cover <i>X</i>			\$ 33.10
	Rear Bumper BRACKET(LH/RH) <i>X</i>			
	SUB TOTAL			\$ 1,115.40
	LESS 20%			\$ 223.08
	DISCOUNTED TOTAL			\$ 892.32
	Rear Bumper Rubber Mat <i>/</i>			\$ 50.00
				\$ 50.00
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 1,612.32

Kalan 16/12/17
7/12/17 10:15hr
2 Pys
P.P
After Repair photo

8/12

LKK Auto Consultants Ltd. notify the Repairer and to advise:
 • To resolve any insurance claim
 • To display damaged parts and to advise
 • Parts prices and to advise information
 • Third party claims and to advise information
 • To advise modification and to advise information
 • To advise modification and to advise information
 • To advise modification and to advise information

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.