

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH

Attention : Motor Claim Department

Contact : 91002955

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	BONNET <i>bt</i> ✓		463.25
2.	2 PCS	BONNET HINGE <i>RV</i>	26.00	52.00
3.	2 PCS	HEADLAMP <i>LH-va-1EH-?</i>	335.15	670.30
4.	1 PC	BONNET LOCK <i>bt</i> ✓		51.80
5.	1 PC	FRONT GRILLE <i>cu</i> ✓		69.55
6.	1 PC	FRONT GRILLE LOGO <i>neu</i> ✓		19.68
7.	1 PC	RADIATOR AUTO <i>vt</i> ✓		732.25
8.	1 PC	RADIATOR SUPPORT PANEL (COMPLETE) <i>bt</i> ✓		500.15
9.	1 PC	RADIATOR FAN ASSY <i>dis</i> ✓		558.15
10.	1 PC	AIRCON CONDENSER <i>bt</i> ✓		1,465.05
11.	1 PC	RADIATOR FAN COWLING <i>dis</i> ✓		69.75
12.	1 PC	FRONT BUMPER <i>de</i> ✓		628.15
13.	1 PC	FRONT BUMPER TOP REINFORCEMENT <i>bt</i> ✓		172.75
14.	1 PC	FRONT BUMPER LOWER GRILLE <i>de</i> ✓		60.75
15.	1 PC	FRONT BUMPER FOG GARNISH <i>?</i>		18.05
16.	2 PC	FRONT BUMPER RETAINER <i>ne</i> ✓	25.05	50.10
17.	2 PC	FRONT FENDER <i>bt</i> ✓	235.65	471.30
18.	2 PC	FRONT FENDER UNDERSHIELD <i>de</i> ✓	63.95	127.90
19.	1 PC	FRONT SHOCK ABSORBER <i>vt</i> ✓		282.70
20.	2 PC	FRONT KNUCKLE ARM <i>bt</i> ✓	248.15	496.30
21.	1 PC	TOP REINFORCEMENT GARNISH <i>de</i> ✓		92.65
22.	1 PC	LOWER REINFORCEMENT <i>bt</i> ✓		148.70

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH

Attention : Motor Claim Department

Contact : 91002955

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	LOWER REINFORCEMENT GARNISH <i>de</i>		92.65
24.	1 PC	FRONT LOWER ARM <i>bt</i>		180.10
25.	1 PC	DRIVESHAFT LH ?		968.40
26.	1 PC	GEARBOX MOUNTING ?		105.55
27.	1 PC	RADIATOR TOP HOSE <i>bt</i>		20.00
28.	1 PC	RADIATOR LOWER HOSE ?		18.15
29.	1 PC	STABILIZER BAR LINK <i>bt</i>		48.75
30.	2 PC	SPORTS RIM <i>bt</i>	633.45	1,266.90
31.	2 PC	FRONT WHEEL BEARING <i>ne</i>	146.05	292.10
32.	1 PC	ENGINE UNDERCOVER SIDE <i>ms</i>		38.10
List TotalS\$:				10,231.98
20.00% Discount S\$:				2,046.40
				8,185.58
SPECIAL NETT ITEMS :				
1.	1 PC	BATTERY <i>de</i>		120.00
2.	1PC	GEARBOX (AUTO) <i>bt</i>		5,000.00
3.	2 PC	TYRE <i>pu</i>	80% 180.00	360.00
4.	1	GEARBOX AUTO OIL <i>ne</i>		100.00
Special Nett Total S\$:				5,580.00
LABOUR :				
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				✓ 30.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH
Attention : Motor Claim Department
Contact : 91002955

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TOWING CHARGES (4 WHEELS)
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS
COMPUTERISED WHEEL ALIGNMENT
TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS
PANEL BEATING, MECHANICAL WORKS
TO REMOVE/ REWELD/ RESEAL WHEEL END PLATE

120.00 ✓
1,400.00 1200 ✓
100.00 ✓
120.00 100 ✓
1,200.00 1000 ✓
120.00 80 ✓

Labour Total S\$:

3,090.00

Tanpin 97495749
up
7/12/17 @ 3pm
Rising after repair
Limit Repair 9 days

E. & O.E.

Total S\$: 16,855.58

Lumpsum

for FALCON AIR AUTO SERVICES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg