

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 6278B

MAKE :

MODEL : HYUNDAI SONATA

DATE 7/12/2017 10:52

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|--|
| | Rear Bumper ✓ | | | \$ 578.40 |
| | Rear Bumper Reinforcement ? | | | \$ 483.30 |
| | Rear Bumper Clip ✓ | | | \$ 22.00 |
| | Rear Bumper Sponge ? | | | \$ 137.40 |
| | Rear Bumper Under Cover X | | | \$ 185.80 |
| | Rear Bumper Protector (LH/RH) X Repair | | \$ 38.00 | \$ 76.00 |
| | SUB TOTAL | | | \$ 1,482.90 |
| | LESS 20% | | | \$ 296.58 |
| | DISCOUNTED TOTAL | | | \$ 1,186.32 |
| | Rear Bumper Reverse Sensor X | | | \$ 135.70 Nett |
| | Rear Bumper Advertisement Logo ✓ | | | \$ 50.00 Nett |
| | Rear Fender Advertisement Logo (LH/RH) ✓ | | \$ 100.00 | \$ 200.00 Nett |
| | | | | \$ 385.70 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 350.00 ²⁰⁰ |
| | Spray Painting Charge | | | \$ 180.00 ^{200.00} |
| | Wiring Charge | | | \$ 50.00 |
| | Remove/Refix Reverse Sensor | | | \$ 20.00 ^{120.00} |
| | TOTAL LABOUR | | | \$ 720.00 |
| | ESTIMATE TOTAL | | | \$ 2,292.02 |

Kalvin LUK
 7/12/17 1135hrs
 2 days
 4s
 After Rep. photo

LKK Auto Consultants hereby notify the Reparer of the following:

- To resurvey the repair work.
- To supply detailed repair estimate.
- Part of the estimate is subject to insurance company approval.
- Third party survey is on a "no fault" basis.
- No legal liability is accepted.
- Supplemental work must be supervised and is subject to final approval by insurance company.

Accepted by: _____
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.