

PDI TUAS

PDI TUAS

TAN HUAN BOON
(CHEN HUANWEN)
49 TELOK BLANGAH DRIVE
#16-05
Singapore, 100049
Singapore

Tangshu 97495749
11/12/17 2pm
3 days
Sur@lkhauto.com

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033042
Quote No. SER/QUO/1702032
QuoteDate 08/12/17
Salesperson MARCUS LIU
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)	10,429	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLA8219L	WVWZZZAUZGW081657	17/03/16	MARCUS LIU
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 415025	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P MACP PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		bt 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		✓ 280.00
	Sum Labor				5,760.00
P 5G6807417APGRU	REAR BUMPER	1	Pieces		des 1,149.75
P 5G6807568D 9B9	Predecessor 5G6807417ARGRU REAR SPOILER	1	Pieces		? 322.86
	Use Predecessor 5G6807568D Sum Item				1,472.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Explanations

P = Proportionately Charged

Sum Labor	5,760.00
Sum Item	1,472.61
Total SGD	7,232.61
7% GST	506.28
Total SGD Incl. GST	7,738.89

Payment Terms No Credit

Payments to: - BBN: - Acc.-No...