

Chai Motor Workshop Sdn Bhd (Co.Reg.No.599246-K)

No 3, Jalan Bertam 8, Taman Daya,
81100 Johor Bahru, Johor Darul Takzim
Tel: +607 3556862 Fax: +607 3547335 Email: chaimotorwks@yahoo.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	52081217-OD
Policy No:	DMPCSN1747191700	Date of Loss:	05/12/2017
Vehicle Reg. No.:	SGG3938E	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COSCO-FEOSO (SINGAPORE) PTE LTD	Contact No:	+6591133461
Driver:	XIN CHUNAN		

Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	15/09/2011
Vehicle Colour:	METALLIC BLACK	Gen Condition:	GOOD
Engine No:	27186030279498	Chassis No:	WDD2120472A471953
Odometer:	63498 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair 7
(day)

Description of Accident/Loss: DAMAGED WHILST PARKED
Present Location: CHAI MOTOR WORKSHOP SDN BHD (HQ)

COST OF CLAIMS

	Amount
Parts	13,902.00
Miscellaneous Items	80.00
Paintwork Materials	280.00
Labour	780.00
Paintwork Labour	1,600.00
Towing	300.00
Nett Amount (S\$)	16,942.00

This claim is handled by: NGU ZHAO LING

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Dec 2017)
 Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGG3938E)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Headlamp LH <i>cut</i>	0.00	0.00	*2,380.00 F
2	1		*Headlamp RH <i>over</i>	0.00	0.00	*2,380.00 F
3	1		*Side Mirror LH <i>cut</i>	0.00	0.00	*1,600.00 F
4	1		*Rear Door Glass LH <i>cut</i>	0.00	0.00	*490.00 F
5	1		*Rear Door Glass RH <i>cut</i>	0.00	0.00	*490.00 F
6	1		*Rear Door Glass Outer Moulding LH <i>dt</i>	0.00	0.00	*300.00 F
7	1		*Rear Door Glass Outer Moulding RH <i>cut</i>	0.00	0.00	*300.00 F
8	1		*Quarter Panel Lamp LH <i>over</i>	0.00	0.00	*830.00 F
9	1		*Quarter Panel Lamp RH <i>over</i>	0.00	0.00	*830.00 F
10	1		*Front Windscreen <i>over</i>	0.00	0.00	*2,250.00 F
11	1		*Front Windscreen Moulding <i>over</i>	0.00	0.00	*110.00 F
12	1		*Boot Lid Lamp LH <i>over</i>	0.00	0.00	*640.00 F
13	1		*Boot Lid Lamp RH <i>over</i>	0.00	0.00	*640.00 F

F=Franchise part.

Sub Total (\$\$)	13,240.00
+ Margin on L,N Items 5.00% (\$\$)	662.00
Total Parts (\$\$)	13,902.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Materials

1 1 Paintwork Materials

280.00

Miscellaneous Items

2 1 Front Windscreen Sealant

60 60.00

Sub Total (S\$)

360.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 To Spray Painting On Bonnet, Door Mirror LH, Front/Rear Door LH, Rear Bumper Cover, Rear Door RH

New

1200 1,600.00

Labour Items

2 To Knock Bonnet

New

80.00 80.00

3 To Remove & Refix All Accident Parts

New

300.00 300.00

4 To Remove & Refix Front Windscreen

New

100 200.00

5 To Remove & Refix Rear Door Glass LH

New

60 100.00

6 To Remove & Refix Rear Door Glass RH

New

60 100.00

Gross Labour Cost (S\$)

2,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Report
L/S Repair
After paint photo
HKB Auto (ms)
8/12/2017.

EXCESS AMOUNT.

6w/ days

MR POK