

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 11 Dec 2017

## **Preliminary Advice**

Vehicle No	: SKS599J	Accident Date	: 26/11/2017
Make	: MERCEDES-BENZ S400L	Policy No.	: DMHCSN1607561701
Assignment Date	: 04/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 08/12/2017	Est. Duration of Repair	: 0.00
Inspection At	: 8 KAKI BUKIT AVE 4 #03-32/34 AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## **Point of Impact / General Description of Damages**

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	280,000.00
COE / PARF Rebate	:S\$	164,723.00
Salvage Value	:S\$	
Margin for Repair	:S\$	115,277.00

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :