

D/S CASE OWNER:

Irene

CC6 / CTI17023344 / A423

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

08/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKP 7484B

Claim No.:

SNM17D04902C00

Name of Insured:

LAU TSZ WING (LIU ZIRONG)

Policy No.:

DMPCSN 3011061700

Insured Tel No.:

HP:

Make / Model:

TOYOTA COROLLA ALTIS 1.6L CVT

Excess Sec II :SS

D.O.A.:

08/05/17

Place of Accident:

STILL ROAD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

9693 8287

(V/L YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SKX 510M



INSRS:

WSP: New Hock Teck

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

11/12/17 (Jas)

SKX 510M - X ; SKP 7484B - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

21/12/17

After call ltr to OI:

21/12/17 @ 4:20

Contacted OI, No response.
Sent official letter to OI.

29/01/18 @ 10:09

Aldy sent PIA to CT - Pending LOD

Documentation Checklist: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 2230.40 (3 days) Reduction: 78 %

Email

Call

FINAL SETTLEMENT

Date/Time:

05/03/18 Confirm with Sulegi

Email

Call

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2,230.40

Loss of Rental (LOR):

SS (days)

Loss of Use (LOU):

SS 300.00 x 100 x 3 (days)

Loss of Income (LOI):

SS (\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 535

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 2,535.75

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 2,535.75

Name 1:

New Hock Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 08 MAR 2018

COMMENT
8/3/18

Ref: 17023344/Ayaz

100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI17023344/Aya3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 08-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 7484B	Veh. Inspected	SKX 510M	
Policy No.	DMPCSN3011061700	Coverage (\$)	0.00	
Claim No.	SNM17D04902C00	Excess (\$)	0.00	
Assign From		Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damage				
5. General Information				
Accident Date	08/05/2017	Inspection Date	18/12/2017	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

NG SOY CHENG

20/12/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China

For

Accident date: 08/05/2017

Estimated repair cost for vehicle no: SKX510M SUBARU FORRESTER 2.0 A '15

CHASSIS: JF1SJ5KC5FG059548

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid Repair		\$1,272.80
2	1	Rear Boot Lid Emblem Logo		\$60.30
3	1	Rear Boot Lid Subaru Logo		\$71.80
4	1	Rear Boot Lid Forester Logo		\$80.30
5	1	Rear Boot Lid Inner Lock		\$196.30
6	1	Rear Boot Lid Inner Rubber		\$120.30
7	1	Rear Boot Lid Inner Trim Board		\$318.20
8	1	Rear Boot Lid Windscreen Seal		\$105.00
9	2	Rear Tail Lamp	\$487.00	\$974.00
10	2	Rear Tail Lamp Lower Bracket	\$30.00	\$60.00
11	1	Rear Bumper Deformed		\$690.30
12	8	Rear Bumper Clip	\$6.50	\$52.00
13	2	Rear Bumper Side Retainer	\$30.30	\$60.60
14	2	Rear Bumper Side Reflector	\$34.30	\$68.60
16	1	Rear Bumper Reinforcement		\$380.30
17	1	Rear Bumper Reverse Sensor		\$480.00
18	1	Rear End Panel		\$320.80
19	1	Rear End Panel Top Garnish		\$110.60
20	1	Rear Exhaust		\$701.20
21	1	Rear Exhaust Chrome Pipe		\$119.20
22	1	Rear Centre Exhaust		\$820.60

Subtotal:- \$7,063.20

1313

105040

* Labour charges

To remove & refit rear windscreen	\$120.00 x
Gum	\$50.00 x
To remove & refit cushion	\$280.00 x
To remove & refit reverse sensor	\$100.00 50
To remove & refit camera	\$180.00 x
To remove & refit rear & centre exhaust	\$380.00 x
To check wiring	\$100.00 30
Tuff kote	\$150.00 x
Panel beating	980 \$950.00 300
Spray painting	\$950.00 600

Subtotal:- \$3,260.00

Total:- \$10,323.20

2230.40

total: 2230.40(P/P)

030mm

→ notify

☐ Notify
☐ Notify
☐ Notify
☐ Parts
☐ Third party
☐ No illegal modification
☐ Supplementary item
 is subject to final approval

Acknowledged by Repairer

Signature: _____

Date: _____



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0432A

Vehicle Details

Vehicle No.:	SKX510M
Vehicle to be Exported:	No
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	FB20Y081871
Chassis No.:	JF1SJ5KC5FG059548
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,528.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$14,528.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$10,896.00

Intended COE Rebate Details

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPLT1802-0027/ SKX510M
Your Ref : SKP7484B
Date : 24th February 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sirs,

**RE: ACCIDENT INVOLVING SKX510M & SKP7484B AT JUNCTION AT EUNOS ON 08.05.2017,
11:55HRS**

We are instructed by **NG SOY CHENG** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SKX510M** damaged by vehicle **SKP7484B** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 2,230.40
2) Loss of Use for 03 days	\$ 300.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 2,537.85</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$2,537.85** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/CTI17023344/Aya3

21 DECEMBER 2017

LAU TSZ WING (LIU ZIRONG)
BLK 250 BT BATOK EAST AVE 5
#04-160
SINGAPORE 650250

Dear Sir/Madam,

**ACCIDENT INVOLVING SKP 7484B & SKX 510M ALONG/AT STILL ROAD
ON 08/05/2017**

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Jas Khine
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jaskhine@lkkauto.com

*c.c. China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)*

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SKX 570 M and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 18 day of 12 2017.

Signature : [Signature]
Name : Ng Lay Chee
ID No. : 516604329
Address : _____

Witness Signature : [Signature]
Witness Name : Chen Yue Yin
Witness ID : SP200194
Witness Address : 1 Kaki Bukit Avenue 6 #01-43
Singapore 417883

WITHOUT PREJUDICE
is not an admission of liability
in any circumstances
and is not binding on the insured

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN3011061700

Claim No : SNM17D04902C00

Claimant : NG SOY CHENG

Amount : S\$2,535.75

SINGAPORE DOLLARS TWO THOUSAND FIVE HUNDRED THIRTY FIVE AND CENT
SEVENTY FIVE ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SKX 510M

Insured Vehicle No. : SKP 7484B

Date of Loss : 08/05/2017

Place of Accident : STILL ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : LAU TSZ WING (LIU ZIRONG)

Driver Name : LAU TSZ WING (LIU ZIRONG)

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) General Damages	S\$	
(2) Cost of Repair/Excess	S\$	2,230.40
(3) Loss of Use/Rental/Earning/Income	S\$	300.00
(4) CIA/Police Report Investigation Results/Search Fees	S\$	5.35
(5) Medical Reports/Expenses	S\$	
(6) Survey Fees/P.T. Fees	S\$	
(7) Cost including Disbursement	S\$	
TOTAL	S\$	2,535.75

Claimant Name : Ng Soy cheng NRIC No : S1660432A

Signature :  Date : 5/3/18



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Client: NG SOY CHENG

Invoice No : NPL1802-0027

Date : 24-Feb-18

Date of Accident : 8-May-17

Vehicle No. : SKX510M

Model Type : Subaru Forester

Descriptions		Amount
Lump Sum Repair Cost		2,230.40
Total		: 2,230.40

SIN DOLLARS: TWO THOUSAND TWO HUNDRED THIRTY AND CENTS FORTY ONLY



Enquire Vehicle & Owner Information (Vehicle No. SKP7484B As At 08 May 2017 / 11:55:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: NEWHOCKTECK

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7577258J

Owner Name: LAU TSZ WING (LIU ZIRONG)

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 122

Registered Street Name: WOODLANDS AVENUE 5

Registered Unit No.: # 05 - 47

Registered Building Name: -

Registered Postal Code: 739021

Current Vehicle Details

Vehicle No.: SKP7484B

Make Description/Model: TOYOTA / TOYOTA COROLLA ALTIS 1.6L CVT

Insurance Company Name: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17023344/Aya3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 7484B	Veh. Inspected	SKX 510M
Policy No.	DMPCSN3011061700	Coverage (\$)	0.00
Claim No.	SNM17D04902C00	Excess (\$)	0.00
Assign From		Assign Date	18/12/2017

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JF1SJ5KC5FG059548	Colour	BLACK
Odometer	37707	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/05/2017	Inspection Date	18/12/2017
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 510M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,272.80	-
1	REAR BOOT LID EMBLE LOGO	NECESSARY	60.30	60.30
1	REAR BOOT LID SUBARU LOGO	NECESSARY	71.80	71.80
1	REAR BOOT LID FORESTER LOGO	NECESSARY	80.30	80.30
1	REAR BOOT LID INNER LOCK	NOT NECESSARY	196.30	-
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	120.30	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	318.20	-
1	REAR BOOT LID WINDSCREEN SEAL	NOT NECESSARY	105.00	-
2	REAR TAIL LAMP @\$487.00	NOT NECESSARY	974.00	-
2	REAR TAIL LAMP LOWER BRACKET @\$30.00	NOT NECESSARY	60.00	-
1	REAR BUMPER	DEFORMED	690.30	690.30
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$30.30	NOT NECESSARY	60.60	-
2	REAR BUMPER SIDE REFLECTOR @\$34.30	NOT NECESSARY	68.60	-
1	REAR BUMPER REINFORCEMENT	BENT	380.30	380.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	320.80	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	110.60	-
1	REAR EXHAUST	NOT NECESSARY	701.20	-
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	119.20	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	820.60	-
	LESS 20% DISCOUNT		-	-262.60
			6,583.20	1,050.40
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	480.00	200.00
			480.00	200.00
LABOUR				
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM .	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT CUSHION.	NOT NECESSARY	280.00	-

Report Ref No. CC6/CT117023344/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT CAMERA	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .	NOT NECESSARY	380.00	-
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE	NOT NECESSARY	150.00	-
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR END PANEL .		950.00	300.00
	SPRAY PAINTING.		950.00	600.00
			3,260.00	980.00
GRAND TOTAL			10,323.20	2,230.40
RECOMMENDED COST OF REPAIRS				2,230.40

Report Ref No. CC6/CT117023344/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.