

ASS. REC. BY:

REF:

CS / ALG / 7023357 / Avb/2

Special Instruction:

SURVEYOR

Adrian

ASSIGNMENT (Office)

From (Person):

Ashley Chan

of

ALG

Date/Time:

18/12/17 10:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 5069 R

Insured:

SLP 64014C

at Workshop m/s

159 Tick Hai Motor

Tel:

6842 9089

of

Blk 1 Kaki Bukit Ave 6 #01-20

Policy No:

Claim No:

7715 5726511SG00B.

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29.11.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

08/12/2017 10:50am

Person Contacted:

Connie

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 5069 R X
	SLP 64014C - X
8/3/18	Adrian confirmed LS \$4200 (Red 4515.27, 527)

Signature:

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL45069R. Regn: 2011 August.
 Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 523i cc 2497
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading: 106611 T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: WBAFP32030C866288.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim STD A/Rim or
 Tyre Size: F: 245/40 R19.
 R: 245/40 R19.
 BS / DUN / EXNOVA / GY / FS / LIZA MIC / QHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 01/12/17.
 Survey held at Tick Hai.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front o/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPA16.

RECEIVED: 2018

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time: File Return to?

2) 9/3- typist

Report Format: merimen

Lump Sum / I.B.I. (\$) 4500p

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp. (\$) _____

☐ : Interview (\$) _____

☐ : Tech. Insp. (\$) _____

☐ : Weekend (\$) _____

Survey Fee

Transportation

_____ \$ - P.S. (\$) _____

Photos

Copies

TOTAL

250

20

270

Survey Department Check List (Case Handler)

Reference No. : CS/ A1917623357/ Avb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 9/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS/AIG17023357/Avb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 08-12-2017	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 6404C	Veh. Inspected	SLG 5069R	
Policy No.		Coverage (\$)	0.00	
Claim No.	7715572654SG003	Excess (\$)	0.00	
Assign From	ASHLEY CHAN	Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/11/2017	Inspection Date		
Survey held at	159 TICK HAI MOTOR BLK C KAKI BUKIT AVE 6 #01-20/22/54 & #02-59 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

- Pre repair inspection request - SLG5069R VS SLP6404C (OI) DOA 29/11/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang
Sent: Friday, 8 December, 2017 10:17:54 AM
Attachments:  07122017142445.pdf

Hi,

Please refer to the enclosed request from **Aridas & Associates**.

Claim no : 7715572654SG003
Case Owner : LOH CHEE HENG

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Aridas & Associates [mailto:aridasv@singnet.com.sg]
Sent: Friday, December 08, 2017 9:57 AM
To: Chan, Yoke Shi
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP6404C AND SLG5069R ON 29/11/2017

Dear Sirs

ACCIDENT INVOLVING MOTOR VEHICLE SLG 5069 R & SLP 6404 C AT THE CARPARK INFRONT OF BLOCK 858, TAMPINES AVENUE 5 ON 29.11.2017

We refer to your fax of 7 December, 2017.

We wish to inform you that our client wishes to appoint your surveyor, **Mr Marcus Chua**, from **M/s LKK Auto Consultants Pte. Ltd.**, to do the pre-repair survey as a single joint expert.

Thank you.

Yours faithfully

Mr Vincent Kee
M/s Aridas & Associates
Telephone No. : 6337 6359
Fax No. : 6338 2713
Email : aridasv@singnet.com.sg

From: Chan, Yoke Shi [mailto:yokeshi.chan@aig.com]

Sent: Thursday, 7 December 2017 2:48 PM

To: Aridas & Associates

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP6404C AND SLG5069R ON 29/11/2017

Without Prejudice

Your Reference : AA.21446.17.159

Our Reference : 7715572654SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Virus-free. www.avg.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ARIDAS & ASSOCIATES

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #05-18, BOON SIEW BUILDING, SINGAPORE 229833
TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713
E-mail : aridasv @ singnet.com .sg

VYILINGAM ARIDAS

LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

*Service of Court Documents
By Fax
Is Not Acceptable*

Our Ref : AA.21446.17.159

Your Ref : Please advise

6 December, 2017

BY FAX ONLY

M/s AIG Asia Pacific Insurance Pte Ltd

FAX NO. : 6835 7416

Dear Sirs


**ACCIDENT INVOLVING MOTOR VEHICLES SLG 5069 R & SLP 6404 C AT
THE CARPARK INFRONT OF BLOCK 858, TAMPINES AVENUE 5 ON
29.11.2017**

We are instructed by Mr Tan Ming Huat to notify you of a road traffic accident on 29 November, 2017 at about 8.00 a.m. at the carpark in front of Block 858, Tampines Avenue 5 involving our client's vehicle registration number **SLG 5069 R** and vehicle registration number **SLP 6404 C** driven by you at the material time. Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

We wish to inform you that our client's motor vehicle **SLG 5069 R** can be inspected at M/s 159 Tick Hai Motor at Block 1, Kaki Bukit Avenue 6, #01-20, AutoBay @ Kaki Bukit, Singapore 417883. Please contact **Ms Connie See** at her office telephone number : **6842 9089**.

Yours faithfully



encs

cc Mr Tjai Wing Song
Block 858A, Tampines Avenue 5
#02-553
Singapore 521858

Enquire Vehicle & Owner Information (Vehicle No. SLP6404C As At 29 Nov 2017 / 08:00:25)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: 159THM

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S0163657Z
Owner Name: TJAI WING SONG
Registered Address Type: HDB / HUDC
Registered Block/House No.: 858A
Registered Street Name: TAMPINES AVENUE 5
Registered Unit No.: # 02 - 553
Registered Building Name: -
Registered Postal Code: 521858

Current Vehicle Details

Vehicle No.: SLP6404C
Make Description/Model: MAZDA / MAZDA3 SEDAN 1.5 AT EU6
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

SINGAPORE ACCIDENT STATEMENT

159 Tick Hai Motor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 29/11/2017 17:11
Date Of Accident 29/11/2017 08:00
Exact Location Of Accident TAMPINES AVE 5
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG5069R
Insured Policyholder
Name Of Registered Owner TAN MING HUAT
NRIC No S2550025C
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97570600
Alternative Phone No OFFICE-97570600

Vehicle Particulars
Manufacturer BMW
Model 523I

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5084637959-01
Cover Note Number

Driver
Name of Driver TAN YI LOON ERNEST
NRIC No S8402311F
Date Of Birth 19/01/1984
Occupation INDOOR
Date Of Driving Pass 26/12/2013
Driving Experience 3 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90494340
Fax Number
Contact Number
Email Address NOEMAIL

Address	BLK 858 TAMPINES AVE 5 #10-531
Postcode	520858
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - -
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20171129/2055.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP6404C
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	TASHA
Phone Number	94503433
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature :
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171129/2055

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

1 of 3

Report No. T/20171129/2055

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/11/2017 12:46		Vide Report No.:		Station Diary No.: 7
Informant's Particulars				
Name of Informant: TAN YI LOON, ERNEST		Address: APT BLK 858 TAMPINES AVENUE 5 #10-531 SINGAPORE 520858		
ID Type / ID No.: NRIC NO / S8402311F		Contact No.: Home/Office: Mobile: 90494340		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 33	Date of Birth: 19/01/1984	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Engineer		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/11/2017 08:00	Type of Location: Car Park
Location: Along Road 1 TAMPINES AVENUE 5 Open carpark in-front of Blk 858 Tampines Ave 5				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of vehicle involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLG5069R	Car	BMW	523	White	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Start Date	Exp. Date
SLG5069R	NTUC Income Insurance Co-Operative Limited	5084637959-01	03/10/2017	14/08/2018



**SINGAPORE
POLICE FORCE**



T/20171129/2055

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

Report No. T/20171129/2055

CONTINUATION OF REPORT

Brief Details.

I am the above mentioned person and I am the owner of the Vehicle SLG5069R(white BMW 523)

On 28/11/2017 at about 1800hrs,i have parked my vehicle at the open car park located in-front of block 858 Tampines Avenue 5 #10-531. I wished to inform that before I left, the vehicle was intact and there was no damages on the vehicle.I have parked on lot number 351.

On 29/11/2017 at about 0910hrs,i have came back to my vehicle and noticed that there was some damages on the front right bumper of my vehicle. I have observed front right headlight to have some crack. As I am taking some photos of my car, a lady by the name of Tasha(Hp:94503433) have came towards me and told me that she have earlier on saw one car which might have knocked onto my car. Tasha informed that on 29/11/2017 at about 0800hrs,she have heard a loud bang at the parking lot and went to have a look. Tasha informed me that the left side of a vehicle SLJ6404(Grey Toyota Altis) which was parked at lot number 350, have came into contact with the right front bumper of my vehicle when the driver was attempting to exit the lot. Tasha told me that the driver of vehicle was believed to be a male Chinese driver. The driver did not came down of his vehicle when the incident took place and just drive away his vehicle from the location.

I wished to inform that I have saw the vehicle SLJ6404 before and believed the male driver is staying in my neighborhood. There is CCTV in my vehicle but however the CCTV does not record when the vehicle engine was off. I have estimated the price to repair the damages to be about 3k to 4k.



**SINGAPORE
POLICE FORCE**



T/20171129/2055

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No.: 1800-3459999

3 of 3

Report No. T/20171129/2055

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Staff Sgt TAY WEI SIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 29/11/2017 12:46
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No.: 65476079	Classification Of Case:
Authentication Stamp NP168	

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 411883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

TPA LG
Ver 2.0

Vehicle Number: SLG5069R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N.	Item Description	Amount (\$)
1	Front Bumper <i>Dehorned</i>	\$ 1,524.75
2	Front Bumper Sponge <i>cauled</i>	\$ 56.18
3	Front Bumper Side Bracket (RH) <i>new</i>	\$ 16.05
4	Front Bumper Sensor <i>new</i>	\$ 240.75
5	Front Fender (RH) <i>Repair</i>	\$ 802.50
6	Front Fender Inner Garnish (RH) <i>torn</i>	\$ 288.90
7	Front Fender Inner Garnish (RH) (Front Small Portion) <i>new</i>	\$ 80.25
8	Front Foglamp (RH) <i>cauled</i>	\$ 240.75
9	Front Foglamp Cover (RH) <i>Dehorned</i>	\$ 72.25
10	Front Headlamp (RH) <i>cauled</i>	\$ 2,327.25
11	Front Headlamp Side Bracket (RH) <i>cauled</i>	\$ 234.00
	Total :	\$ 5,883.63
	Less 10%:	\$ 588.36
	Amount :	\$ 5,295.27

4760.13
4284.11

S/N	Special Nett Item	Amount (\$)
1	Front Headlamp Solar Film x 2 pcs <i>new</i>	\$ 150.00
2	Front Bumper Sticker <i>new</i>	\$ 80.00
	Amount :	\$ 230.00

Labour	Amount (\$)
To use computer diagnostic and resetting	\$ 380.00
To check front electrical wiring system and focus headlamp	\$ 180.00
To remove and reinstall front bumper sensors	\$ 80.00
To apply anti-rusting coating on new and affected areas	\$ 200.00
Labour to remove, cut, change & panel beating	\$ 1,400.00
To putty and respray affected areas	\$ 950.00
Labour Total :	\$ 3,190.00
Total (Parts & Labour)	\$ 8,715.27

100
30
50
980
350
450
total: 5264.11
A/S: 42K
04 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2017 Edit Reg		08 Dec 2017 00:00 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

Insured:

TJAI WING SIONG, ID: S0163657Z

Main Claimant:

TAN MING HUAT, ID: S2550025C

Vehicle Reg. No.:

SLG5069R

Date of Loss:

29/11/2017 08:00 - :59

Claim Type:

TP / 7715572654SG

Policy/Cover Note No.:

2100510389 (Comprehensive)

Vehicle Reg. No. (Insured):

SLP6404C

Policy No. (Claimant):

Excess:

Repairer:

159 Tick Hai Motor (HQ) 1 Kaki Bukit Avenue 6, #01-20 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 4676 / 6842 9089

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/12/2017]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

AIG_SG (12/12/2017): TP GIA REPORT

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

*SLG5069R (7715572654SG)
[SLP6404C]
TP
TAN MING HUAT
Nov 29 2017 8:00AM
[TJAI WING SIONG]
159 Tick Hai Motor

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/12/17 12:15	Accident Statement From:SC - Reg. No: SLP6404C, Claimant: TJAI WING SIONG	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 08:30	General View	Load JPG	<input checked="" type="checkbox"/>
16	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	08/03/18 18:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

31	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	08/03/18 18:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					<div>1 per page ▾</div> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/03/18 09:08	Singapore Accident Statement		Load PDF	
2	09/03/18 09:09	Police Report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<div>Reset</div> <div>Save</div> <div>Print</div>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17023357/AVBE2
Date: 13/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. **Policy No:** 2100510389
Claimant Vehicle No : SLG5069R **Insured Vehicle No :** SLP6404C
Date of Loss: 29/11/2017 **Nature of Claim:** TP **Claim No:** 7715572654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG5069R
Make & Model: BMW 523i, 2.5 (A) **Engine No:** 09267751N52B25AF
Reg. Date: 15/08/2011 (Man. Year: 2011) **Chassis No:** WBAFP32030C866288
Colour: White **Odometer:** 106611 km
Engine Capacity: 2497 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 **Rear Tyre Size:** 245/40 R19
Front Left Side: Michelin 6 mm **Rear Left Side:** Michelin 6 mm
Front Right Side: Michelin 6 mm **Rear Right Side:** Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,525.27	4,284.12	1,241.15	22.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	980.00	2,210.00	69.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,715.27	5,264.12	3,451.15	39.60
Approved Total (Overridden) (\$\$)		4,200.00		
Nett Amount (\$\$)	8,715.27	4,200.00	4,515.27	51.81

INSPECTION

Date of Assignment: 08/12/2017
Date Inspected: 11/12/2017 **Inspected At:** 159 Tick Hai Motor (HQ)
1 Kaki Bukit Avenue 6, #01-20 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,524.75 FL	*1,524.75 FL
2	1	*FRONT BUMPER SPONGE	Cracked	56.18 FL	*56.18 FL
3	1	*FRONT BUMPER SIDE BRACKET (RH)	Necessary	16.05 FL	*16.05 FL
4	1	*FRONT BUMPER SENSOR	Not Necessary	240.75 FL	*- FL
5	1	*FRONT FENDER (RH)	Repair	802.50 FL	*- FL
6	1	*FRONT FENDER INNER GARNISH (RH)	Torn	288.90 FL	*288.90 FL
7	1	*FRONT FENDER INNER GARNISH (RH) (FRONT SMALL PORTION)	Not Necessary	80.25 FL	*- FL
8	1	*FRONT FOGLAMP (RH)	Cracked	240.75 FL	*240.75 FL
9	1	*FRONT FOGLAMP COVER (RH)	Deformed	72.25 FL	*72.25 FL
10	1	*FRONT HEADLAMP (RH)	Cracked	2,327.25 FL	*2,327.25 FL
11	1	*FRONT HEADLAMP SIDE BRACKET (RH)	Cracked	234.00 FL	*234.00 FL
12	2	*FRONT HEADLAMP SOLAR FILM	Not Necessary	150.00 FS	*- FS
13	1	*FRONT BUMPER STICKER	Not Necessary	80.00 FS	*- FS
Sub Total (\$\$)				6,113.63	4,760.13
- List Item Discount on L Items 10.00/10.00% (\$\$)				588.36	476.01
Total Parts (\$\$)				5,525.27	4,284.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO USE COMPUTER DIAGNOSTIC AND RESETTNG	New	380.00	100.00
2	TO CHECK FRONT ELECTRICAL WIRING SYSTEM AND FOCUS HEADLAMP	New	180.00	30.00
3	TO REMOVE AND REINSTALL FRONT BUMPER SENSORS	New	80.00	50.00
4	TO APPLY ANTI-RUSTING COATING ON NEW AND AFFECTED AREAS	New	200.00	0.00
5	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING	New	1,400.00	350.00
6	TO PUTTY AND RESPRAY AFFECTED AREAS	New	950.00	450.00
Gross Labour Cost (\$\$)			3,190.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >