



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 08.12.2017

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2167Z TOYOTA VELL FIRE (2016)

To Supply

1)	1pc	front bumper <i>de ✓</i>	\$	1,785.00
2)	1pc	front bumper left retainer <i>nei ✓</i>	\$	120.35
3)	1set	front bumper clip <i>nei ✓</i>	\$	60.00
4)	1pc	left front fender <i>bt ✓</i>	\$	1,447.70
5)	1pc	left front fender cowling <i>de ✓</i>	\$	249.30
6)	1set	left front fender cowling clip <i>nei ✓</i>	\$	20.00
7)	1pc	left front fender "Hybrid" emblem <i>nei ✓</i>	\$	69.00

Sub total parts	\$	3,751.35
Less: 25% discount	\$	(937.83)
	\$	2,813.52

To supply S.Nctt parts

1)	1pc	"Prime Royal" sticker <i>nei ✓</i>	\$	60.00
-----	-----	------------------------------------	----	-------

L/charges

1)	To remove front bumper, left head lamp left front fender. Replace front bumper, left front fender & etc. Refit left head lamp. Knock & adjust left front door	\$	300 500.00
-----	---	----	---------------

- 2) To putty, respray painting front bumper, left front door in pearl and sport rim

\$ 500
900.00

Sub total L/charges	\$ 1,400.00
Estimated Total	\$ 4,273.52

Tanpin 974 95744
J- WP' 8/12/17 C 1125

3 days

Lumpsum

Resurvey after repair

surc / 11/11/2017

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: