



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 08.12.2017

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Dept

RE: SUPPLEMENTARY COST OF REPAIR TO SHD2167Z TOYOTA VELLFIRE (2016)

To Supply

1) 1pc Left front head lamp

CMA ✓
\$ 3,257.00

Less: 25% discount \$ (814.25)

Sub total parts \$ 2,442.75

L/charges

1) Towing charges (use king trolley)

\$ ✓ 75.00

Estimated total

\$ 2,517.75



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1164975

Date: 6/12/17

M/S:

Prime

Vehicle No: SHD 2167Z

Model :

Toyota Vellfire

From: Marina Blvd X Bayfront Ave

Time Start:

22:55

To: 6, Bend Pk.

Time End:

23:37

Remarks:

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 75

GST S\$

TOTAL S\$

Received By

bizSAFE₃

Important Note:

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 08.12.2017

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2167Z TOYOTA VELLFIRE (2016)

To Supply

1)	1pc	front bumper <i>de ✓</i>	\$	1,785.00
2)	1pc	front bumper left retainer <i>ue ✓</i>	\$	120.35
3)	1set	front bumper clip <i>ue ✓</i>	\$	60.00
4)	1pc	left front fender <i>bt ✓</i>	\$	1,447.70
5)	1pc	left front fender cowling <i>de ✓</i>	\$	249.30
6)	1set	left front fender cowling clip <i>ue ✓</i>	\$	20.00
7)	1pc	left front fender "Hybrid" emblem <i>ue ✓</i>	\$	69.00

Sub total parts	\$	3,751.35
Less: 25% discount	\$	(937.83)
	\$	2,813.52 ✓

To supply S.Nctt parts

1)	1pc	"Prime Royal" sticker <i>AM ✓</i>	\$	60.00 ✓
-----	-----	-----------------------------------	----	---------

L/charges

1)	To remove front bumper, left head lamp left front fender. Replace front bumper, left front fender & etc. Refit left head lamp. Knock & adjust left front door	\$	300 500.00
-----	---	----	---------------

2) To putty, respray painting front bumper, left front door in pearl and sport rim

\$ 500
900.00

Sub total L/charges	\$	1,400.00	500.00
Estimated Total	\$	4,273.52	3673.52

+ Supplementary + 2517.75

6191.27
less: 20% - 1238.25

4953.02

↓

4950/-

Tanjum 97495744
WP' 8/12/17C 1125

3days

lumpsum

Resumy after repair

surC/Manufactory