

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY #24-01
 AXA TOWER
 S068811

ATTN: Motor Claim Department
Your Ref No: OD 1217-6257
Claim Type: Own Damage
Accident Date: 05-12-2017

Estimate No: EST1503055
Date: 06 Dec 2017
Policy No: CN825708
Veh Reg No: SBR9138J
Make/Model: MERCEDES BENZ S280
Chassis No: WDB2200632A483952
Engine No: 11292232001116
Reg. Date: 30-05-2006

Estimate Repair Cost to Vehicle No :SBR9138J

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
1 FRONT NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	35.00
Spare Parts				
2 FRONT BUMPER - NO STOCK	870.0000	1 PC	870.00	870.00
3 FRONT BUMPER CLIPS	2.8000	10 PCS	28.00	28.00
4 FRONT BUMPER SIDE HOLDER - LH - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
5 FRONT BUMPER SIDE HOLDER - RH - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
6 FRONT BUMPER SENSOR - NO STOCK	88.0000	310/5 PCS	528.00	528.00
7 FRONT BUMPER INNER FRAME - NO STOCK	92.0000	1 PC	92.00	92.00
8 FRONT BUMPER FOAM - NO STOCK	110.0000	1 PC	110.00	110.00
9 FRONT BUMPER REINFORCEMENT - NO STOCK	1,770.0000	1 PC	1,770.00	1,770.00
10 FRONT BUMPER LOWER GRILLE CHROME - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
11 FRONT BRAKE PAD W/CHROME MOULDING - LH - NO STOCK	240.0000	1 PC	240.00	240.00
12 FRONT BRAKE PAD W/CHROME MOULDING - RH - NO STOCK	240.0000	1 PC	240.00	240.00
13 FRONT BUMPER NOZZLE COVER & BRACKET - LH - NO STOCK	50.0000	1 PC	50.00	50.00
14 BONNET - NO STOCK	2,050.0000	1 PC	2,050.00	2,050.00
15 BONNET LOGO WITH STAR	35.0000	1 PC	35.00	35.00
16 BONNET INSULATOR - NO STOCK	215.0000	1 PC	215.00	215.00
17 BONNET INSULATOR CLIPS	2.8000	21 PCS	58.80	58.80
18 BONNET TOP SPRING - LH & RH	11.0000	2 PCS	22.00	22.00
19 BONNET BOTTOM LOCK - LH & RH - NO STOCK	50.0000	1/2 PCS	50.00	50.00
20 BONNET TOP LOCK - CENTRE - NO STOCK	60.0000	1 PC	60.00	60.00
21 BONNET ABSORBER - LH - NO STOCK	72.0000	1 PC	72.00	72.00
22 BONNET ABSORBER - RH - NO STOCK	72.0000	1 PC	72.00	72.00
23 BONNET GRILLE ASSY - NO STOCK	430.0000	1 PC	430.00	430.00
24 GRILLE BRACKET - NO STOCK	96.0000	1 PC	96.00	96.00
25 TOP PANEL - NO STOCK	220.0000	1 PC	220.00	220.00
26 HEAD LAMP PANEL - LH - NO STOCK	116.0000	1 PC	116.00	116.00
27 HEAD LAMP SIDE PANEL - LH - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
28 HEAD LAMP UNIT - LH - NO STOCK	850.0000	1 PC	850.00	850.00
29 HEAD LAMP TOP RUBBER - LH - NO STOCK	70.0000	1 PC	70.00	70.00
30 HEAD LAMP TOP RUBBER - RH - NO STOCK	70.0000	1 PC	70.00	70.00
31 ABS PUMP - NO STOCK	2,870.0000	1 PC	2,870.00	2,870.00
32 ABS PIPE - NO STOCK	250.0000	1 SET	250.00	250.00
33 POWER STEERING PUMP - NO STOCK	1,020.0000	1 PC	1,020.00	1,020.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
S068811

ATTN: Motor Claim Department
Your Ref No: OD 1217-6257
Claim Type: Own Damage
Accident Date: 05-12-2017

Estimate No: EST1503055
Date: 06 Dec 2017
Policy No: CN825708
Veh Reg No: SBR9138J
Make/Model: MERCEDES BENZ S280
Chassis No: WDB2200632A483952
Engine No: 11292232001116
Reg. Date: 30-05-2006

Estimate Repair Cost to Vehicle No :SBR9138J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
34 FAN BELT - NO STOCK	92.0000	1 PC	92.00	92.00
35 GRILLE ASSY - NO STOCK	400.0000	1 PC	400.00	400.00
36 GRILLE LOGO - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
37 FRONT FENDER - LH - NO STOCK	800.0000	1 PC	800.00	800.00
38 FRONT FENDER PROTECTOR & CHROME - LH - NO STOCK	66.0000	1 PC	66.00	66.00
39 AIR CLEANER END HOSE - NO PRICE & NO STOCK	0.0000	1 PC	0.0000	0.0000
40 RADIATOR - NO STOCK	850.0000	1 PC	850.00	850.00
41 AIRCON CONDENSER - NO STOCK	860.0000	1 PC	860.00	860.00
42 AIRCON FAN MOTOR ASSY - NO STOCK	1,550.000	1 PC	1,550.00	1,550.00
			17,222.80	17,222.80
Labour				
43 TO KNOCK OUT DENTS, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	900.0000	1 JOB	900.00	900.00
44 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,000.000	1 JOB	1,000.00	1,000.00
45 TO CHECK WIRING	20.0000	1 JOB	20.00	20.00
46 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00	100.00
47 TO REMOVE, REPLACE ABS PUMP, PIPES, BELT, POWER STEERING PUMP AND RELATED PARTS	400.0000	1 JOB	400.00	400.00
48 TO RESET CHECK LIGHT	60.0000	1 JOB	60.00	60.00
			2,480.00	2,480.00
			Total	S\$ 19,737.80
			Add GST @ 7%	1,381.65
			Total Amount Payable	S\$ 21,119.45

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND ONE HUNDRED NINETEEN AND CENTS FORTY FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

Handwritten notes:
7 days
P/P
08/12/17 @ 1545
EXCESS: 1000
REPAIR
Resurvey by paint