

INS. CASE OWNER:

shann

CC 4/AIG1702

2277, K. K. K.

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

8/17/17

Date / Time:

8/17/17

Registered in Merimen:

8/17/17

Pre-assign / CCU / FTE

SDG 929L



Insured Vehicle No.:

Claim No.:

055528068754

Name of Insured:

UW SUSHITO @ 44/TW

Policy No.:

170004394

Insured Tel No.:

HP:

8860949

Make / Model:

ANDI

Excess Sec II : \$5

D.O.A.:

07/17/17

Place of Accident:

KLANI AIRPORT T2 4P

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SUSHITO 2001 @ 17M 16 T 20E

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) YES / NO

Insured Liability:

%

Final ? Yes / No

866 6289E



INSRS:

WSP:

Tel:

Liability:

RMKS:

UW SUSHITO
1602

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

11/17/17
8AM

866 6289E - 10

SUSHITO - 4

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 7/1/17 7:50 PM HAWA

After call ltr to OI: 12/10/17 - 10:00 AM

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

RECEIVED 08 MAY 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

FINAL SETTLEMENT

Date/Time:

29-5-18

Confirm with:

8/17/17

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

N/A

Repair Cost:

GST

SS

5,350.00

Loss of Rental (LOR):

GST

SS

727.60

(8 days)

X 85

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS

8.X

Medical:

SS

Disbursement:

SS

X

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

6,085.60

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6,085.60

Name 1:

CHENG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY:

REF:

A/G/

7

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

OF days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

11/12

File pass to Carhous

11/12 8 500d Carhous Ehide

Panel

C7+1 X 85+G57

R (\$2,266.84/31%)

Veh No: _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mercedes 6 SP

c.c

1999

Colour: _____

M.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading: _____

253286

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Jm 666101-200 524076

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

3

mm

L/Bal. _____

6

mm

L/Bal. _____

3

mm

D.O.A. _____

7/12/17

D.O.I. _____

8/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Prell. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee: _____

Transportation: _____

\$ - RS - SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 07/12/2017

TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK

Date: 08 Dec 2017

Policy No: 5084512564-01

Veh Reg No: SGL5289E

Make/Model: MAZDA 6 2.0 SP A

Chassis No: JM6GG10F200524076

Engine No: LF768853

Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT RH FENDER ✓	398.00	1 PC	398.00	✓
2 FRT RH FENDER INNER SHIELD ✓	135.00	1 PC	135.00	✓
3 FRONT RH FENDER INNER SHIELD CLIP ✓	4.80	6 PC	28.80	✓
4 FRONT RH DOOR ✓	869.00	1 PC	869.00	✓
5 FRONT RH DOOR TOP HINGE ✗	98.00	1 PC	98.00	✗
6 FRONT RH DOOR BOTTOM HINGE ✓	98.00	1 PC	98.00	✓
7 FRONT RH DOOR CHECKER 1	83.00	1 PC	83.00	✗
8 FRONT RH DOOR FRAME STICKER ✓	133.00	1 SET	133.00	✓
9 FRONT RH DOOR INNER RUBBER ?	135.00	1 PC	135.00	50.00 67.50
10 FRONT RH DOOR POWER WINDOW REGULATOR ?	215.00	1 PC	215.00	✓
11 FRONT RH DOOR OUTER PROTECTOR ✓	92.00	1 PC	92.00	✓
12 REAR RH DOOR OUTER PROTECTOR ✓	83.00	1 PC	83.00	✓
13 FRONT RH KNUCKLE ARM ?	535.00	1 PC	535.00	✓
14 FRONT RH KNUCKLE BEARING ?	298.00	1 PC	298.00	✓
15 FRONT RH LOWER ARM ?	421.00	1 PC	421.00	✓
16 FRONT RH SHOCK ABSORBER ?	316.00	1 PC	316.00	✓
17 FRONT RH STAY LINKAGE ?	89.00	1 PC	89.00	✗
			3756.80	4026.80
			Less 20% 751.36	805.66
				3221.44
Special Net				
18 FRONT RH RIM ✓	380.00	1 PC	380.00	320.00
19 REAR RH RIM ✓	380.00	1 PC	380.00	320.00
20 DOOR VISOR ✓	180	1 SET	180.00	✓
			940.00	940.00 ✓
Labour				
21 REMOVE & REFIX FRT BUMPER, HEADLAMP, GRILLE, FRT RH FENDER, FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR REAR RH DOOR, REAR RH FENDER & RH DOOR PILLAR & REALIGN THE SAME	900	1 LA	900.00	800
22 PUTTY & RESPRAY FRT & REAR BUMPER, BOTH RH FENDERS, BOTH RH DOORS & FRT DOOR PILLAR & ALL AFFECTED AREAS	1300	1 LA	1300.00	1200
23 REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	180	1 LA	180.00	160
24 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60	1 PC	60.00	✓
25 REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	100	1 LA	100.00	✓
26 RUSTPROOFING	90	1 LA	90.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/12/2017
TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK
Date: 08 Dec 2017
Policy No: 5084512564-01
Veh Reg No: SGL5289E
Make/Model: MAZDA 6 2.0 SP A
Chassis No: JM6GG10F200524076
Engine No: LF768853
Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			2,630.00	2,630.00
				2410
			Total	SS 6,791.44
			Add GST @ 7%	475.40
			Total Amount Payable	SS 7,266.84

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

PARTS: 3005.44

SN : 940

L : 2410

6355.44

L3 : 5000/- (20%)

PLS CHECK & CONFIRM

Cor-
Revised - 727.60 (87485.141)
LTA - 8

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 07/12/2017

TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK

Date: 08 Dec 2017

Policy No: 5084512564-01

Veh Reg No: SGL5289E

Make/Model: MAZDA 6 2.0 SP A

Chassis No: JM6GG10F200524076

Engine No: LF768853

Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT RH FENDER <i>As</i>		1 PC		
2 FRT RH FENDER INNER SHIELD <i>DI</i>		1 PC		
3 FRONT RH FENDER INNER SHIELD CLIP <i>new</i>		6 PC		
4 FRONT RH DOOR <i>As</i>		1 PC		
5 FRONT RH DOOR TOP HINGE <i>R X</i>		1 PC		
6 FRONT RH DOOR BOTTOM HINGE <i>As</i>		1 PC		
7 FRONT RH DOOR CHECKER		1 PC		
8 FRONT RH DOOR FRAME STICKER <i>As</i>		1 SET		
9 FRONT RH DOOR INNER RUBBER		1 PC		
10 FRONT RH DOOR POWER WINDOW REGULATOR		1 PC		
11 FRONT RH DOOR OUTER PROTECTOR <i>As</i>		1 PC		
12 REAR RH DOOR OUTER PROTECTOR <i>As</i>		1 PC		
13 FRONT RH RIM <i>DI</i>		1 PC		
14 FRONT RH KNUCKLE ARM		1 PC		
15 FRONT RH KNUCKLE BEARING		1 PC		
16 FRONT RH LOWER ARM		1 PC		
17 FRONT RH SHOCK ABSORBER		1 PC		
18 FRONT RH STAY LINKAGE		1 PC		
19 REAR RH RIM <i>As</i>		1 PC		
			0.00	0.00
Special Net				
20 DOOR VISOR	180	1 SET	180.00	180.00
			180.00	180.00
Labour				
21 REMOVE & REFIX FRT BUMPER, HEADLAMP, GRILLE, FRT RH FENDER, FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR REAR RH DOOR, REAR RH FENDER & RH DOOR PILLAR & REALIGN THE SAME	900	1 LA	900.00	900.00
22 PUTTY & RESPRAY FRT & REAR BUMPER, BOTH RH FENDERS, BOTH RH DOORS & FRT DOOR PILLAR & ALL AFFECTED AREAS	1,300	1 LA	1,300.00	1,300.00
23 REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	180	1 LA	180.00	180.00
24 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60	1 PC	60.00	60.00
25 REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	100	1 LA	100.00	100.00
26 RUSTPROOFING	90	1 LA	90.00	90.00

Let Auto Consultants hence notify the Repairer of the following:

- To receive immediate spray painting
- To display damaged parts during delivery
- Parts price are subject to confirmation
- Third party survey is to a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary survey report to be submitted and is subject to final approval from the Insurance Company

Acknowledged by Repairer:
Signature:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/12/2017
TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK
Date: 08 Dec 2017
Policy No: 5084512564-01
Veh Reg No: SGL5289E
Make/Model: MAZDA 6 2.0 SP A
Chassis No: JM6GG10F200524076
Engine No: LF768853
Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			2,630.00	2,630.00
			Total	SS 2,810.00
			Add GST @ 7%	196.70
			Total Amount Payable	SS 3,006.70

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	3095X

Vehicle Details

Vehicle No.	SGL5289E
Vehicle to be Exported	Yes
Intended De-registration Date	07 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	M6 SP20 SDN
Primary Colour	White
Manufacturing Year	2006
Engine No.	LF768853
Chassis No.	JM6GG10F200524076
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$19,721.00
Original Registration Date	20 Sep 2006
First Registration Date	20 Sep 2006
Transfer Count	2
Actual ARF Paid	\$21,694.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	19 Sep 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	5
PQP Paid	\$28,418.00
COE Rebate Amount	\$21,502.00
Total Rebate Amount	\$21,502.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG17023377/Kzb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDG 929L	Veh. Inspected	SGL 5289E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/12/2017	Inspection Date
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

3372

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: SDG929L
Claimant Vehicle No.	: SGL5289E
Date of Accident	: 07/12/2017
Traffic Accident involving vehicle/s No.	: CHANGI AIRPORT T2 CARPARK COMPOUND (LEVEL 1)

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 5,350.00	
2	Loss of Rental	\$ 727.60	\$85 X 8 days + GST
3	LTA Search	\$ 8.00	
TOTAL		\$ 6,085.60	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4AIG17023377/Kzb3

11 JANUARY 2018

LILY SUSANTO @ LILY TAN
40 WHITE HOUSE PARK
SINGAPORE 257616

Dear Sir/Madam,

ACCIDENT INVOLVING SDG 929L AND SGL 5289E ON 7.12.17

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

I, AKS Success Services (the third party claimant) of Blk 962 Hougang Ave 9 #14-584 Singapore 530962 (address), owner of SGL5289E (vehicle no.) hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SGL5289E that was damaged pursuant to the accident which occurred on 7/12/2017 (date) along Changi Airport T2 Carpark Compound (level 1) (location) involving vehicle no/s SDG929L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 7 (day) of December (month) 2017 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS\$350.00 (Repair Cost), SS\$727.60 (Loss of Rental), SS\$8.00 (Disbursement), for vehicle no SGL5289E that was damaged pursuant to the accident which occurred 7/12/2017 (date) along Changi Airport T2 Carpark compo und (Level 1) (location) involving vehicle no/s SDG929L. This is pursuant to the inspection conducted on 8/12/2017 (date) at "the workshop". We/I confirm that we/I are/am authorized by the owner AK88 Success Services ("the third party claimant") of vehicle no. SGL5289E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SGL5289E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 7 (day) of MAY (month) 2018 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/12/2017
TP Veh Reg No: SDG929L

NO: CL8180263
Date: 29 Mar 2018
Policy No: 5084512564-01
Veh Reg No: SGL5289E
Make/Model: MAZDA 6 2.0 SP A
Job No: JC1597112

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 5,000.00	SS 5,000.00

Total	SS 5,000.00
Add GST @ 7%	350.00
Total Amount payable	SS 5,350.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

38 WOODLANDS IND PARK E1
#05-05 SINGAPORE 757700
(ROC/GST NO. 53068927L)

OPERATING HOURS
MONDAY TO SATURDAY
(9AM TO 6PM)

Hirer's Name AK88 Success Services				Date of Birth		Passport/ Nrc No. 53323095X		Nationality			
Address B1K 962 Honggang Ave 9 #14-584				Occupation		Driving License No.		Date Obtained/Expiry			
				Postal Code 530962		Contact No.		Mobile Phone No.			
Joint Hirer's/Guarantor's Name Kunk Zhi Yuan				Date of Birth 22/11/1983		Passport/ Nrc No. 583383576		Nationality S'PUREAN			
Ad. as above				Occupation		Driving License No. — — —		Date Obtained/Expiry 18/07/2003			
				Postal Code		Contact No.		Mobile Phone No. 90628944			
VEHICLE NO. SGK4563A				MODEL Toyota ALTIS							
FROM				RETURN *Estimated Date For actual return see CHECK IN							
CHECK OUT	Date	07/12/2017	Time	1625	Mileage	KM	E	¼	½	¾	F
	Date	15/12/2017	Time	1315							
CHECK IN					Mileage	KM	Remarks				

- 1) This vehicle is restricted to SINGAPORE use only
- 2) Only Persons above 26 years of age with more than 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- 3) The hirer shall be liable to pay the first S\$2000 insurance policy excess for damage to vehicle plus loss of earnings while damaged vehicle is under repairs.
- 4) Third party Liability is the first \$2000.00 in any accident involving Third Party Claims
- 5) Hirer is responsible for all parking fines & traffic summon
- 6) Vehicle should be returned at the same time as collection except on Saturday ie return time is before 12pm
- 7) Hourly extension is charged at 1/5 of the daily rate
- 8) As preventive maintenance, please check water & engine oil daily.
- 9) For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge S\$100 will be imposed for smoky or dirty vehicle
- 10) Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings.
- 11) The vehicle is NOT covered by a motor insurance policy covering personal accident insurance for the hirer, his passengers or authorised driver.
- 12) No replacement of vehicle in any accident

[illegible]

1/We declare that all information given on this form is true and accurate.

Hire:

Joint Borrower's/Guarantor's Signature _____

38 WOODLANDS IND PARK E1
#05-05, SINGAPORE 757700
TEL : 64595278

TAX INVOICE NO. : 170298

GST Reg No. : 53068927L

Bill to : AK88 SUCCESS SERVICES

DATE: 15-Dec-17

S/NO.	DESCRIPTIONS	UNIT	RATE	AMOUNTS
1)	SGK4563A	8	\$85.00	680.00
	(7/12/2017 - 15/12/2017)			
			NETT	680.00
			GST (7%)	47.60
			TOTAL	727.60

E & O.E.

TOTAL

PERFECT DRIVING & SERVICE



A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B002 / 2018																																																																																																					
YOUR REF:																																																																																																							
OUR REF : ACS.CH.LTA.2017 (DEC 2017)		DATE : 8/1/18																																																																																																					
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.																																																																																																							
LTANET SEARCHES FOR THE MONTH DEC 2017 <table border="1"><thead><tr><th>S/NO</th><th>TP NO.</th><th>CHM</th><th>DOA</th></tr></thead><tbody><tr><td>1</td><td>1/12/2017</td><td>GBG3823L</td><td>SJU3797K 29/11/2017</td></tr><tr><td>2</td><td>1/12/2017</td><td>SJT91M</td><td>SKN357S 30/11/2017</td></tr><tr><td>3</td><td>2/12/2017</td><td>YN6113Z</td><td>YN2388Z 1/12/2017</td></tr><tr><td>4</td><td>4/12/2017</td><td>SLG5214M</td><td>SDASJ 24/11/2017</td></tr><tr><td>5</td><td>4/12/2017</td><td>FBC8213K</td><td>SJR3697G 2/12/2017</td></tr><tr><td>6</td><td>5/12/2017</td><td>GBE8369J</td><td>GBB7769K 2/12/2017</td></tr><tr><td>7</td><td>5/12/2017</td><td>SJP2944K</td><td>SCM6686C 1/12/2017</td></tr><tr><td>8</td><td>6/12/2017</td><td>SKX8464K</td><td>SLQ6616C 5/12/2017</td></tr><tr><td>9</td><td>6/12/2017</td><td>SFB831L</td><td>GBB9262S 5/12/2017</td></tr><tr><td>10</td><td>6/12/2017</td><td>SLB4524B</td><td>SGF3179J 1/12/2017</td></tr><tr><td>11</td><td>7/12/2017</td><td>SDG929L</td><td>SGL5289E 7/12/2017</td></tr><tr><td>12</td><td>11/12/2017</td><td>C8F7E</td><td>SFF9955H 11/12/2017</td></tr><tr><td>13</td><td>11/12/2017</td><td>SKV8470C</td><td>SLQ7869H 9/12/2017</td></tr><tr><td>14</td><td>12/12/2017</td><td>FBF1127G</td><td>SJJ5460B 10/12/2017</td></tr><tr><td>15</td><td>12/12/2017</td><td>SJN516L</td><td>PC3871C 8/11/2017</td></tr><tr><td>16</td><td>13/12/2017</td><td>GBD779S</td><td>SGG4564T 9/12/2017</td></tr><tr><td>17</td><td>13/12/2017</td><td>PA3272S</td><td>DORIS 13/12/2017</td></tr><tr><td>18</td><td>13/12/2017</td><td>SLJ9014G</td><td>SJC7483J 8/12/2017</td></tr><tr><td>19</td><td>18/12/2017</td><td>SJG2804D</td><td>SLS7439E 14/12/2017</td></tr><tr><td>20</td><td>18/12/2017</td><td>YL6855B</td><td>SLQ41A 18/12/2017</td></tr><tr><td>21</td><td>18/12/2017</td><td>SKH2332G</td><td>SJV7558C 12/12/2017</td></tr><tr><td>22</td><td>18/12/2017</td><td>SLF4450J</td><td>SKR6436L 13/12/2017</td></tr><tr><td>23</td><td>18/12/2017</td><td>SJU1190Z</td><td>SFQ3603E 14/12/2017</td></tr><tr><td>24</td><td>18/12/2017</td><td>SJE9485E</td><td>SLP1178M 11/12/2017</td></tr></tbody></table>				S/NO	TP NO.	CHM	DOA	1	1/12/2017	GBG3823L	SJU3797K 29/11/2017	2	1/12/2017	SJT91M	SKN357S 30/11/2017	3	2/12/2017	YN6113Z	YN2388Z 1/12/2017	4	4/12/2017	SLG5214M	SDASJ 24/11/2017	5	4/12/2017	FBC8213K	SJR3697G 2/12/2017	6	5/12/2017	GBE8369J	GBB7769K 2/12/2017	7	5/12/2017	SJP2944K	SCM6686C 1/12/2017	8	6/12/2017	SKX8464K	SLQ6616C 5/12/2017	9	6/12/2017	SFB831L	GBB9262S 5/12/2017	10	6/12/2017	SLB4524B	SGF3179J 1/12/2017	11	7/12/2017	SDG929L	SGL5289E 7/12/2017	12	11/12/2017	C8F7E	SFF9955H 11/12/2017	13	11/12/2017	SKV8470C	SLQ7869H 9/12/2017	14	12/12/2017	FBF1127G	SJJ5460B 10/12/2017	15	12/12/2017	SJN516L	PC3871C 8/11/2017	16	13/12/2017	GBD779S	SGG4564T 9/12/2017	17	13/12/2017	PA3272S	DORIS 13/12/2017	18	13/12/2017	SLJ9014G	SJC7483J 8/12/2017	19	18/12/2017	SJG2804D	SLS7439E 14/12/2017	20	18/12/2017	YL6855B	SLQ41A 18/12/2017	21	18/12/2017	SKH2332G	SJV7558C 12/12/2017	22	18/12/2017	SLF4450J	SKR6436L 13/12/2017	23	18/12/2017	SJU1190Z	SFQ3603E 14/12/2017	24	18/12/2017	SJE9485E	SLP1178M 11/12/2017
S/NO	TP NO.	CHM	DOA																																																																																																				
1	1/12/2017	GBG3823L	SJU3797K 29/11/2017																																																																																																				
2	1/12/2017	SJT91M	SKN357S 30/11/2017																																																																																																				
3	2/12/2017	YN6113Z	YN2388Z 1/12/2017																																																																																																				
4	4/12/2017	SLG5214M	SDASJ 24/11/2017																																																																																																				
5	4/12/2017	FBC8213K	SJR3697G 2/12/2017																																																																																																				
6	5/12/2017	GBE8369J	GBB7769K 2/12/2017																																																																																																				
7	5/12/2017	SJP2944K	SCM6686C 1/12/2017																																																																																																				
8	6/12/2017	SKX8464K	SLQ6616C 5/12/2017																																																																																																				
9	6/12/2017	SFB831L	GBB9262S 5/12/2017																																																																																																				
10	6/12/2017	SLB4524B	SGF3179J 1/12/2017																																																																																																				
11	7/12/2017	SDG929L	SGL5289E 7/12/2017																																																																																																				
12	11/12/2017	C8F7E	SFF9955H 11/12/2017																																																																																																				
13	11/12/2017	SKV8470C	SLQ7869H 9/12/2017																																																																																																				
14	12/12/2017	FBF1127G	SJJ5460B 10/12/2017																																																																																																				
15	12/12/2017	SJN516L	PC3871C 8/11/2017																																																																																																				
16	13/12/2017	GBD779S	SGG4564T 9/12/2017																																																																																																				
17	13/12/2017	PA3272S	DORIS 13/12/2017																																																																																																				
18	13/12/2017	SLJ9014G	SJC7483J 8/12/2017																																																																																																				
19	18/12/2017	SJG2804D	SLS7439E 14/12/2017																																																																																																				
20	18/12/2017	YL6855B	SLQ41A 18/12/2017																																																																																																				
21	18/12/2017	SKH2332G	SJV7558C 12/12/2017																																																																																																				
22	18/12/2017	SLF4450J	SKR6436L 13/12/2017																																																																																																				
23	18/12/2017	SJU1190Z	SFQ3603E 14/12/2017																																																																																																				
24	18/12/2017	SJE9485E	SLP1178M 11/12/2017																																																																																																				
		sub-total c/f	S 192.00																																																																																																				
M/s. A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.																																																																																																							

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2017 Edit Reg		08 Dec 2017 00:00 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Lily Susanto @ Lily Tan, ID: 57132340D		
Main Claimant:	AK88 SUCCESS SERVICES, Co. Reg. No.: 53323095X		
Vehicle Reg. No.:	SGL5289E	Date of Loss:	07/12/2017 00:00 - :59 [134 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 05552806895G	Policy/Cover Note No.:	1700014794
Vehicle Reg. No. (Insured):	SDG929L	Policy No. (Claimant):	5084512564-01
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijie.Wui@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (11/12/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGL5289E (0555280689SG)
[SDG929L]
TP
AK88 SUCCESS SERVICES
Dec 7 2017 12:00AM
[Lily Susanto @ Lily Tan]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page ☐ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports			1 per page ☐ ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/12/17 10:04	Accident Statement From: SC - Reg. No: SDG929L, Claimant: LILY SUSANTO @ LILY TAN	 Load HTM	
Photos/Images			3 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 14:59	General View	 Load JPG	☒
2	07/05/18 14:59	General View	 Load JPG	☒
3	07/05/18 14:59	General View	 Load JPG	☒
4	07/05/18 14:59	General View	 Load JPG	☒
5	07/05/18 14:59	General View	 Load JPG	☒
6	07/05/18 14:59	General View	 Load JPG	☒
7	07/05/18 14:59	General View	 Load JPG	☒
8	07/05/18 14:59	General View	 Load JPG	☒
9	07/05/18 14:59	General View	 Load JPG	☒
10	07/05/18 14:59	General View	 Load JPG	☒
11	07/05/18 14:59	General View	 Load JPG	☒
12	07/05/18 14:59	General View	 Load JPG	☒
13	07/05/18 14:59	General View	 Load JPG	☒
14	07/05/18 14:59	General View	 Load JPG	☒
15	07/05/18 14:59	General View	 Load JPG	☒
16	07/05/18 14:59	General View	 Load JPG	☒
17	07/05/18 14:59	General View	 Load JPG	☒
18	07/05/18 14:59	General View	 Load JPG	☒
19	07/05/18 14:59	General View	 Load JPG	☒
20	07/05/18 14:59	General View	 Load JPG	☒
21	07/05/18 14:59	General View	 Load JPG	☒
22	07/05/18 14:59	General View	 Load JPG	☒
23	07/05/18 14:59	General View	 Load JPG	☒
24	07/05/18 14:59	General View	 Load JPG	☒
Documentation			1 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/12/17 16:05	EMAIL FROM AIG DD 08122017	 Load PDF	
2	11/12/17 10:14	TP GIA REPORT	 Load PDF	
3	11/12/17 18:46	TP ESTIMATE- MARKED	 Load PDF	
4	11/01/18 12:00	LETTER TO OI	 Load PDF	

Letters / Correspondences			1 per page	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
5	09/05/18 08:42	WORKSHOP INVOICE	 Load PDF	
6	09/05/18 08:42	AUTHORISATION TO ACT FORM	 Load PDF	
7	09/05/18 08:42	Release Voucher	 Load PDF	
8	09/05/18 08:42	RENTAL RECEIPT	 Load PDF	
9	09/05/18 08:42	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDG929L (Insd veh)	Model:	MAZDA 6 2.0 SP (A)
	SGL5289E (TP veh)		
Date of Accident:	07/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	7,266.84
Final Repair Cost	:	\$	5,350.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	727.60 8 days
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,085.60

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 6,085.60
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17023377/KJB3Q2

Date: 09/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700014794
Claimant Vehicle No : SGL5289E **Insured Vehicle No :** SDG929L
 Date of Loss: 07/12/2017 Nature of Claim: TP Claim No: 0555280689SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGL5289E**
 Make & Model: MAZDA 6, 2.0 SP (A) Engine No: LF768853
 Reg. Date: 20/09/2006 (Man. Year: 2006) Chassis No: JM6GG10F200524076
 Colour: Metallic Pearl White Odometer: 253266 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 3 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,161.44	3,784.94	376.50	9.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	2,410.00	220.00	8.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,791.44	6,194.94	596.50	8.78
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	6,791.44	5,000.00	1,791.44	26.38
+ GST 7.00/7.00% (S\$)	475.40	350.00	125.40	26.38
Nett Amount (S\$)	7,266.84	5,350.00	1,916.84	26.38
+ Car Rental (8.0 x S\$85.00/day + 7.00% GST) (S\$)		727.60		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,085.60		

INSPECTION

Date of Assignment: 08/12/2017
 Date Inspected: 08/12/2017 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	398.00 FL	*398.00 FL
2	1		*FRT RH FENDER INNER SHIELD	Distorted	135.00 FL	*135.00 FL
3	6		*FRONT RH FENDER INNER SHIELD CLIP	Necessary	28.80 FL	*28.80 FL
4	1		*FRONT RH DOOR	Bent	869.00 FL	*869.00 FL
5	1		*FRONT RH DOOR TOP HINGE	Repair	98.00 FL	*- FL
6	1		*FRONT RH DOOR BOTTOM HINGE	Bent	98.00 FL	*98.00 FL
7	1		*FRONT RH DOOR CHECKER	Serviceable	83.00 FL	*- FL
8	1		*SET FRONT RH DOOR FRAME STICKER	Necessary	133.00 FL	*133.00 FL
9	1		*FRONT RH DOOR INNER RUBBER (50%)	Cut	108.00 FS	*67.50 FS
10	1		*FRONT RH DOOR POWER WINDOW REGULATOR	Distorted	215.00 FL	*215.00 FL
11	1		*FRONT RH DOOR OUTER PROTECTOR	Dented	92.00 FL	*92.00 FL
12	1		*REAR RH DOOR OUTER PROTECTOR	Dented	83.00 FL	*83.00 FL
13	1		*FRONT RH KNUCKLE ARM	Bent	535.00 FL	*535.00 FL
14	1		*FRONT RH KNUCKLE BEARING	Necessary	298.00 FL	*298.00 FL
15	1		*FRONT RH LOWER ARM	Distorted	421.00 FL	*421.00 FL
16	1		*FRONT RH SHOCK ABSORBER	Bent	316.00 FL	*316.00 FL
17	1		*FRONT RH STAY LINKAGE	Serviceable	89.00 FL	*- FL
18	1		*FRONT RH RIM	Dented	380.00 FS	*320.00 FS
19	1		*REAR RH RIM	Dented	380.00 FS	*320.00 FS
20	1		*SET DOOR VISOR	Necessary	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,939.80	4,509.30
- List Item Discount on L Items 20.00/20.00% (S\$)	778.36	724.36
Total Parts (S\$)	4,161.44	3,784.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ,HEADLAMP,GRILLE ,FRT RH FENDER ,FRT RH DOOR & ATTACHMENTS ,KNOCKING & REPAIR REAR RH DOOR ,REAR RH FENDER & RH DOOR PILLAR & REALIGN THE SAME	New	900.00	800.00
2	PUTTY & RESPRAY FRT & REAR BUMPER,BOTH RH FENDERS ,BOTH RH DOORS & FRT DOOR PILLAR & ALL AFFECTED AREAS	New	1,300.00	1,200.00
3	REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	New	180.00	160.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	New	100.00	100.00
6	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			2,630.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >