

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 07/12/2017

TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK

Date: 08 Dec 2017

Policy No: 5084512564-01

Veh Reg No: SGL5289E

Make/Model: MAZDA 6 2.0 SP A

Chassis No: JM6GG10F200524076

Engine No: LF768853

Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT RH FENDER <i>Bl</i>		1 PC		
2 FRT RH FENDER INNER SHIELD <i>Dil</i>		1 PC		
3 FRONT RH FENDER INNER SHIELD CLIP <i>neu</i>		6 PC		
4 FRONT RH DOOR <i>Bl</i>		1 PC		
5 FRONT RH DOOR TOP HINGE <i>R X</i>		1 PC		
6 FRONT RH DOOR BOTTOM HINGE <i>Bl</i>		1 PC		
7 FRONT RH DOOR CHECKER		1 PC		
8 FRONT RH DOOR FRAME STICKER <i>neu</i>		1 SET		
9 FRONT RH DOOR INNER RUBBER		1 PC		
10 FRONT RH DOOR POWER WINDOW REGULATOR		1 PC		
11 FRONT RH DOOR OUTER PROTECTOR <i>neu</i>		1 PC		
12 REAR RH DOOR OUTER PROTECTOR <i>neu</i>		1 PC		
13 FRONT RH RIM <i>neu</i>		1 PC		
14 FRONT RH KNUCKLE ARM		1 PC		
15 FRONT RH KNUCKLE BEARING		1 PC		
16 FRONT RH LOWER ARM		1 PC		
17 FRONT RH SHOCK ABSORBER		1 PC		
18 FRONT RH STAY LINKAGE		1 PC		
19 REAR RH RIM <i>neu</i>		1 PC		
			0.00	0.00
Special Net				
20 DOOR VISOR	180	1 SET	180.00	180.00
Labour				
21 REMOVE & REFIX FRT BUMPER, HEADLAMP, GRILLE, FRT RH FENDER, FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR REAR RH DOOR, REAR RH FENDER & RH DOOR PILLAR & REALIGN THE SAME	900	1 LA	900.00	900.00
22 PUTTY & RESPRAY FRT & REAR BUMPER, BOTH RH FENDERS, BOTH RH DOORS & FRT DOOR PILLAR & ALL AFFECTED AREAS	1,300	1 LA	1,300.00	1,300.00
23 REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	180	1 LA	180.00	180.00
24 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60	1 PC	60.00	60.00
25 REMOVE & REFIX BOTH RH DOOR WINDOW GLASSES & RESET CENTRAL LOCKING	100	1 LA	100.00	100.00
26 RUSTPROOFING	90	1 LA	90.00	90.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be submitted and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/12/2017
TP Veh Reg No: SDG929L

Estimate No: ES1791379/AMK
Date: 08 Dec 2017
Policy No: 5084512564-01
Veh Reg No: SGL5289E
Make/Model: MAZDA 6 2.0 SP A
Chassis No: JM6GG10F200524076
Engine No: LF768853
Reg. Date: 20/09/2006

Estimate Repair Cost to Vehicle No :SGL5289E

Description	U/Price	Quantity	List Price S\$	Amount S\$
			2,630.00	2,630.00
			Total	S\$ 2,810.00
			Add GST @ 7%	196.70
			Total Amount Payable	S\$ 3,006.70

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE