



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

MARITEAM TRANSPORT SERVICES PTE LTD

01/12/2017

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP AXA-

Thin Thin.

Accident date: 30/11/2017

Estimated repair cost for vehicle no: PC4536P NISSAN NV350 2.5 4DR '16

CHASSIS: JN1UC4E26Z0002195

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear L/H Tail Lamp <i>NHT</i>		\$209.80 X
2	1	Rear Bumper <i>Rpr</i>		\$690.60 X
3	8	Rear Bumper Clip <i>NHT</i>	\$6.50	\$52.00 X
4	1	Rear L/H Bumper Side Retainer <i>NHT</i>		\$22.10 X
5	1	Rear L/H Fender <i>Rpr</i>		\$2,241.80 X
6	1	Rear L/H Fender Glass Seal <i>NHT</i>		\$155.50 X
7	1	Rear L/H Sliding Door <i>Dented</i>		\$1,718.90 ✓
8	1	Rear L/H Sliding Door Glass Seal <i>NHT</i>		\$155.50 X
9	1	Rear L/H Door Rear Pillar <i>Rpr</i>		\$641.00 X
10	1	Rear L/H Tyre Hub Cap <i>LT</i>		<del>\$151.20</del> 70(SW)

1718.90 SN: 70  
120323

Subtotal :- \$6,038.40

S/n	Qty	Items / Special Nett	U/price	Amount
11	1	Rear L/H Sliding Door Excursion Bus Sticker <i>NHT</i>		\$30.00 ✓
12	1	Rear L/H Axle Bearing <i>NHT</i>		\$154.70 X
13	1	Body Logo <i>NHT</i>		<del>\$380.00</del> 120

150

Subtotal :- \$564.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Labour charges

To remove & refit body logo	\$150.00 x
To remove & refit seat cushion & carpet	\$750.00 X
To remove & refit roof lining	\$550.00 X
To remove & refit L/H fender glass	\$240.00 x
Gum	\$100.00 x
To remove & refit L/H sliding door <i>fitting</i>	<del>\$120.00</del> 100
Gum	\$50.00 x
To remove & refit rear L/H axle bearing	\$180.00 x
To remove & refit reverse sensor	\$100.00 x
To check wheel alignment	1580 <del>\$150.00</del> 80
To check wiring	\$100.00 x
Tuff kote	\$150.00 x
Panel beating	<del>\$2,200.00</del> 400
Spray painting	<del>\$1,800.00</del> 1000

Subtotal :- \$6,640.00

Total:- \$13,243.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 2003.23  
n/s: 24K.  
05 days

24K

05 days