

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

5/12/2017

M/S AIG

ESTIMATE REPAIR COST FOR SGY3244D TOYOTA SIENTA
CHASSIS : NCP81-5037242

S/N	QTY	DESCRIPTION
1	1 PC	FRONT BUMPER
2	1 PC	FRONT BUMPER CLIPS
3	1 PC	FRONT BUMPER LH SIDE RETAINER
4	1 PC	FRONT LH FENDER
5	1 PC	FRONT LH HEADLAMP

D.S	\$	1,280.50	✓
ner	\$	30.00	✓
but	\$	68.10	✓
n	\$	708.90	✓
scr/cr	\$	515.70	✓
	\$	2,603.20	1894.3
LESS 25%	\$	(650.80)	1420.72
	\$	1,952.40	
	\$	450.00	400
	\$	450.00	300
	\$	25.00	✓
	\$	2,877.40	2145.72

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: