

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S2688302D
BASIL ALI OMER UQBA
BLK 183 BEDOK NORTH ROAD
20-52
SINGAPORE 460183
TEL : FAX :
PH : 97824745
ATTN :

ESTIMATE BILL

Number : EB00004686
Date : 11/12/2017
Case No : AD00009440
Vehicle No : SJB2154Y
Chassis : RN61048055
Year of Mfr : 2007
Policy No : 5081364342
Model : HONDA STREAM
1.8A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE	1.0	903.20	20	722.56
2	TAILGATE INNER LOCK	1.0	189.20	20	151.36
3	TAILGATE EMBLEM	1.0	24.90	20	19.92
4	TAILGATE LOGO (STREAM)	1.0	31.60	20	25.28
5	REAR BUMPER	1.0	588.90	20	471.12
6	REAR BUMPER CLIP	2.0	3.70	20	5.92
7	REAR BUMPER SIDE RETAINER LH	1.0	24.10	20	19.28
8	REAR BUMPER SIDE RETAINER RH	1.0	24.10	20	19.28
List Price - Parts Sub Total					1,434.72
9	REAR NUMBER PLATE	1.0	30.00	0	30.00
10	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
11	REAR BUMPER REVERSE SENSOR LH	1.0	280.00	0	280.00
12	REAR BUMPER REVERSE SENSOR RH	1.0	280.00	0	280.00
13	REAR REVERSE CAMERA	1.0	580.00	0	580.00
14	WINDSCREEN SEALANT	2.0	24.00	0	48.00
15	REAR END PANEL - REPAIR	1.0			
Special Nett Price - Parts Sub Total					1,248.00
Parts Total					2,682.72
16	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
17	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
18	ANTI-RUST COATING	1.0	100.00	0	100.00
19	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
20	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,630.00
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED FOURTEEN AND CENTS SIXTY-ONE ONLY				Less Excess	0.00
				SUBTOTAL	4,312.72
				GST 7.00%	301.89
				TOTAL	4,614.61

Date of accident : 02/12/2017 01:40 PM Place : AYE MCE NEAR WEST COAST

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD



AUTHORISED SIGNATURE