

Messrs Grab Rentals Pte Ltd

Estimate To Repair Mazda 3-1.5 4 Door Sedan
Vehicle No : SLN2102L
Chassis No : JM6BN22A8H0150945

*not April
LKK
2/5 \$1900/-
3 dy.
the other repair
11/12/17*

Third Party Insurer : AIG
Insured's Veh No : GBE5672C
Date of accident : 08.12.2017

Date : 09.12.2017

*L44-Marus
11/12/17 c/w*
Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	n/s rear door <i>6.5/50</i>	\$ 1,006.00	\$ 1,006.00 ✓
2	1 pc	n/s rear door weatherstirp <i>10.1</i>	\$ 121.00	\$ 121.00 ✓
3	1 pc	n/s rear door window glass channel weatherstirp <i>11</i>	\$ 117.00	\$ 117.00 ✓
4	1 pc	n/s rear door outer weatherstirp moulding <i>key</i>	\$ 140.00	\$ 140.00 ✓
5	1 pc	n/s rear door window frame garnish top <i>11</i>	\$ 71.40	\$ 71.40 ✓
6	1 pc	n/s rear door window frame garnish front <i>11</i>	\$ 108.00	\$ 108.00 ✓
7	1 pc	n/s rear door 1/4 glass pillar <i>11</i>	\$ 110.00	\$ 110.00 ✓
8	1 pc	n/s rear door 1/4 glass pillar weatherstirp <i>11</i>	\$ 41.00	\$ 41.00 ✓
9	1 pc	n/s rear door inner lock <i>2w/5h/6</i>	\$ 180.00	\$ 180.00 ✓
10	1 pc	n/s rear door inner lock striker <i>11</i>	\$ 26.00	\$ 26.00 ✓
11	1 pc	n/s rear door inner trimboard <i>10.1</i>	\$ 424.00	\$ 424.00 ✓
12	1 pc	n/s rear door power window motor <i>2w/5h/6</i>	\$ 290.00	\$ 290.00 ✓
13	1 pc	n/s rear door regulator <i>2w</i>	\$ 120.70	\$ 120.70 ✓
14	1 pc	n/s rear door hinge <i>11</i>	\$ 58.00	\$ 58.00 ✓
15	1 pc	n/s rear door checker <i>11</i>	\$ 34.00	\$ 34.00 ✓
				\$ 2,847.10
Less 20%				\$ 569.42
				\$ 2,277.68
LABOUR & MISC. CHARGES				
1		To transfer of door fittings and perform water seepage test. <i>60</i>		\$ 180.00
2		Panel beating, knocking and straighten the necessary portion, <i>180</i>		\$ 250.00
3		remove and renewal of parts, adjust and realign the same. <i>320</i>		\$ 400.00
		Putty and spray painting of the affected portion. <i>2385.36</i>		\$ 830.00
Grand Total				\$ 3,107.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216