

ASS. REC. BY:

REF: CS/SMD17023431/Dvb

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Grace Teo of SMD Date/Time: 11-12-2017 10:18am

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 5669G * Insured: SGL 3535J

at Workshop m/s Teamwork Tel: 6844 2479

of 53 Ubi Ave 1 * 01-2B

Policy No: Claim No: CMTD1704428 / NSW

Sum Insured: Excess:

Make of Veh: D.O.A. 06-12-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: /

Date/Time: 11-12-2017 11:30am Person Contacted: Mrs Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJL 5669G - NA / INC 17023275 / KH
	SGL 3535J - X
20/12/17	Email preli revised to Grace Teo

DOA: 06/12/17

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time Action / Instruction

Sompo 8GG 3535J
MV 161C
LTA 10.81C
HL 5.2K

RECEIVED 22 JAN 2019

21/01/2019 Finance 2/3 3550/- with 5 days of rep (Red 5333.00, 60%)

Veh No: SSL5669G Reg No: Dec 2008
 Type: MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Sc22 No: 1339
 Colour: Yellow Insured / Std / Nil / NA
 Sp Reading: 176007 T-Radio Insured / Std / Nil / NA
 Eng No: L13E11010108
 O No: JHMGEG85098210033

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or
 Brake: In Order / Jammed / Leaked / Burnt or
 Mod: Nil / SC / STD AIR Im or

Tyre Size: F: 195/50R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone

Front: _____ Rear: _____
 R.Bal: 5 mm L.Bal: 5 mm
 D.O.A: 06/12/2017 D.O.L: 11/12/2017

Survey held at: Teamwork Pyc Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Return: ☐ : Prelim. Report
☐ : Final Report

Date/Time File Return: 21/1- typist

Report Format: TP
 Lump Sum / L.B: 3550/2

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Test drive: \$
☐ Cleaning: \$

Survey Fee

Interconnection

1-1-1-1

Print

Print

Print

Print



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO17023431/Dvb	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623			Date : 11-12-2017	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGG 3535J	Veh. Inspected	SJL 5669G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1704428/NSW	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/12/2017	Inspection Date	11/12/2017	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1704428/NSW
Our ref: CS/SMO17023431/Dvb

Date: 20/12/2017

The Motor Claims Department
M/s Sompo Insurance Singapore Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SJL 5669G


We thank you for your instruction on 11/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/12/2017 Teamwork Garage Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,449.00
Revised Estimate Amount	: S\$	3,747.82
"Check" Items Amount	: S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang

Automotive Assessor / Investigator

Survey Department Check List (Case Handler)

Reference No.: CS/SM017023431/DVB
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 21/1/19
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 20 December, 2017 9:21 AM
To: 'Teo, Grace'
Cc: 'Ngo, Sau Wei Shawn'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017
Attachments: SJL 5669G PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SJL 5669G
Date of survey: 11/12/2017
Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 December, 2017 11:27 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Monday, 11 December, 2017 10:18 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: TEAMWORK GARAGE CLAIMS <claims@teamworkgarage.com>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Hi,

Please make arrangement to conduct the survey for SJL5669G.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TEAMWORK GARAGE CLAIMS [<mailto:claims@teamworkgarage.com>]

Sent: Monday, December 11, 2017 10:05 AM

To: Teo, Grace

Cc: Ngo, Sau Wei Shawn; Henry, Irene James; claims@teamworkgarage.com

Subject: RE: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS PTE LTD

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

**Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.*

Darren Ng

Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park

Singapore 408934

Tel: 68442475

Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Friday, December 08, 2017 1:14 PM

To: claims@teamworkgarage.com

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Importance: High

Our Reference: CMTD1704428/NSW

Your Reference: SJL5669G

Without Prejudice

Date: 8th December 2017

Attention:

M/S Teamwork Garage Pte Ltd

Dear Sirs,

We refer to your Notice of Accident dated 08/12/2017.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teamwork Garage Pte Ltd [<mailto:claims@teamworkgarage.com>]

Sent: Friday, December 08, 2017 11:58 AM

To: Claims - Motor Survey; claimsreport; Henry, Irene James

Cc: claims@teamworkgarage.com

Subject: CMTD1704428/NSW PRE-REPAIR INSPECTION NOTIFICATION FOR SLG5669G

Importance: High

WITHOUT PREJUDICE

OUR REF: 1712-13

YOUR REF: SGG3535J

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SJL5669G

ACCIDENT INVOLVING SJL5669G AND SGG3535J ON 06.12.17

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Thank you.

Regards,

Alison

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 2475
Fax: 6844 2474

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 11 December, 2017 10:18 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: TEAMWORK GARAGE CLAIMS; Ngo, Sau Wei Shawn; Henry, Irene James
Subject: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Hi,

Please make arrangement to conduct the survey for SJL5669G.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TEAMWORK GARAGE CLAIMS [mailto:claims@teamworkgarage.com]

Sent: Monday, December 11, 2017 10:05 AM

To: Teo, Grace

Cc: Ngo, Sau Wei Shawn; Henry, Irene James; claims@teamworkgarage.com

Subject: RE: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017

Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS PTE LTD

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

**Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.*

Darren Ng
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Friday, December 08, 2017 1:14 PM
To: claims@teamworkgarage.com
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1704428/NSW - Accident involving SGG3535J & SJL5669G on 06.12.2017
Importance: High

Our Reference: CMTD1704428/NSW
Your Reference: SJL5669G

Without Prejudice

Date: 8th December 2017

Attention:
M/S Teamwork Garage Pte Ltd

Dear Sirs,

We refer to your Notice of Accident dated 08/12/2017.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teamwork Garage Pte Ltd [<mailto:claims@teamworkgarage.com>]

Sent: Friday, December 08, 2017 11:58 AM

To: Claims - Motor Survey; claimsreport; Henry, Irene James

Cc: claims@teamworkgarage.com

Subject: CMTD1704428/NSW PRE-REPAIR INSPECTION NOTIFICATION FOR SLG5669G

Importance: High

WITHOUT PREJUDICE

OUR REF: 1712-13

YOUR REF: SGG3535J

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SJL5669G

ACCIDENT INVOLVING SJL5669G AND SGG3535J ON 06.12.17

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Thank you.

Regards,

Alison

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 2475

Fax: 6844 2474



Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

Register number : 201015366H

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd

50 Raffles Place , #05-01/06

Singapore Land Tower

Singapore 048623

Vehicle number : SJL5669G
Make / Model : HONDA/JAZZ
Chassis number : JHMGE68509S210033
Accident date : 06 December 2017
Reference : 1712-13

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>dentata</i>	628.00 ✓
1	REAR BUMPER TOW COVER HS <i>SVC</i>	20.88 X
2	REAR BUMPER RETAINER <i>SVC</i>	47.52 X
1	END PANEL <i>Dentata</i>	418.95 ✓
1	REAR END PANEL TOP GARNISH <i>dentata</i>	129.37 ✓
2	REAR TAILLAMP <i>H/L</i>	584.88 X
1	REAR EXHAUST SILENCER <i>H/L</i>	536.17 X
2	REAR EXHAUST MOUNTING <i>SVC</i>	50.00 X
2	REAR FENDER INNER TRIM <i>H/L</i>	693.60 X
1	TAILGATE <i>Dentata</i>	849.60 ✓
2	TAILGATE ABSORBER <i>SVC</i>	314.40 X
1	TAILGATE EMBLEM - JAZZ <i>H/L</i>	37.20 ✓
1	TAILGATE OUTER HANDLE <i>H/L</i>	151.32 X
1	TAILGATE WEATHERSTRIP <i>H/L</i>	110.76 ✓
1	TAILGATE GLASS MOULDING <i>H/L</i>	98.40 ✓
1	TAILGATE LOCK <i>SVC</i>	223.20 X
1	TAILGATE LOCK STRIKER <i>new</i>	33.60 X
2	TAILGATE HINGE <i>H/L</i>	121.20 X
1	SPARE TRYE TOP BOARD <i>H/L</i>	337.20 X
		5386.25
Less 20%		1077.25
		4309.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		4309.00
1 SET	REAR BUMPER CLIP <i>H/L</i>	60.00 <i>301-</i>
1 SET	REAR FENDER INNER TRIM CLIP <i>H/L</i>	50.00 X
1 SET	REAR REVERSE SENSOR <i>Dentata</i>	400.00 <i>2201-</i>
1	REAR NUMBER PLATE <i>H/L</i>	70.00 X
1	JOINT SEALANT <i>H/L</i>	150.00 <i>401-</i>
1	WINDSCREEN SEALANT <i>H/L</i>	150.00 <i>401-</i>
Subtotal		880.00
Balance C/F		5189.00

227228
1817.82

3301-

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	5189.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 120/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
6	TRANSFER PARTS, ATATCHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
7	PANEL BEATING ON AFFECTED AREAS	1200.00 800/-
8	SPRAY PAINTING ON AFFECTED AREAS	1000.00 800/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3260.00
	Grand total	8449.00
		8782.20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11/12/2017 @ 1130hrs

4147.82

Not Author

Supp 333.20

L15mm

4481.02

5 days

L15 3550/-

2 K1C Auto

Check part prices.



Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
ROC number : 201015366H
3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd
50 Raffles Place , #05-01/06
Singapore Land Tower
Singapore 048623

Vehicle number	SJL5669G
Make / Model	HONDA/JAZZ
Chassis number	JHMGE68509S210033
Accident date	06 December 2017
Reference	1712-13

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE INNER TRIM BOARD <i>minor crack</i>	416.50 ✓
	Less 20%	83.30
		333.20

Super
2 KK Sub



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17023431/Dvbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 22-01-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGG 3535J	Veh. Inspected	SJL 5669G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704428/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMGE68509S210033	Colour	YELLOW
Odometer	176007	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/50 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	195/50 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	195/50 R15	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/12/2017	Inspection Date	11/12/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5669G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	628.00	628.00
1	REAR BUMPER TOW COVER	SERVICEABLE	20.88	-
2	REAR BUMPER RETAINER	SERVICEABLE	47.52	-
1	END PANEL	DENTED	418.95	418.95
1	REAR END PANEL TOP GARNISH	DEFORMED	129.37	129.37
2	REAR TAILLAMP	NOT NECESSARY	584.88	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	536.17	-
2	REAR EXHAUST MOUNTING	SERVICEABLE	50.00	-
2	REAR FENDER INNER TRIM	NOT NECESSARY	693.60	-
1	TAILGATE	DENTED	849.60	849.60
2	TAILGATE ABSORBER	SERVICEABLE	314.40	-
1	TAILGATE EMBLEM-JAZZ	NECESSARY	37.20	37.20
1	TAILGATE OUTER HANDLE	NOT NECESSARY	151.32	-
1	TAILGATE WEATHERSTRIP	NECESSARY	110.76	110.76
1	TAILGATE GLASS MOULDING	NECESSARY	98.40	98.40
1	TAILGATE LOCK	SERVICEABLE	223.20	-
1	TAILGATE LOCK STRIKER	TO REPAIR SEE LABOUR	33.60	-
2	TAILGATE HINGE	NOT NECESSARY	121.20	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	337.20	-
1	TAILGATE INNER TRIM BOARD (ADDITIONAL)	MOUNTING CRACKED	416.50	416.50
	LESS 20% DISCOUNT		-1,160.55	-537.76
			4,642.20	2,151.02
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
			880.00	330.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND RENEW REAR EXHAUST ASSY.		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER OF PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK STRIKER.		1,200.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			3,260.00	2,000.00
	GRAND TOTAL		8,782.20	4,481.02
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00

Report Ref No. CS/SMO17023431/Dvbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.