

INSURANCE

INS. CASE OWNER:

Priya

CC6 / 11117023433 / Uuaz

LKK:
IDAC

Surveyor:

MARCUS

DOI:

11/12/17

Date / Time:

11/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

SHC 8125G

Name of Insured

CTPL

Insured Tel No.

HP:

Excess Sec II : S\$

D.O.A:

10/12/17

Is driver the owner?

(YES (NO))

Nature of Accident:

Claim No.:

MU17120323

Policy No.:

MUM0015

Make / Model:

HYUNDAI I40

Place of Accident:

MERPATI ROAD IN FRONT BLK 14

If NO, Driver Name / Age: TAN CHONG HUAK

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SLS 47252



INSRS:

WSP: Hup Motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLS 47252 - X

SHC 8125G - CCS/TIME 11/12/17 5/11/17 D.O.A. 10/12/17

1 - MPA 1056 14/12/23/14 D.O.A. 01/12/17

12/12/17 (THUR THUR) NO ESTIMATE

OI chang lane.

26/12/17

File pass to Typist

RECEIVED 20 DEC 2017

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PR:

Mandate Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

9/1/18

Confirm with:

David

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4800.00

Loss of Rental (LOR):

S\$

550.00

(

5 days) x 110

Loss of Use (LOU):

S\$

(

\$

x

days)

Loss of Income (LOI):

S\$

(

\$

x

days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

5.35

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

5355.35

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5355.35

Name 1:

HUP MOTOR TRADING & SERVICE

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

111
ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SL5 47252
 at Workshop m/s hupm
 of _____
 Insured: SHC81356
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 ID / Q Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No NS 673

CA / REV / REP. / 24 HRS

Date _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL547252 Yr Regn: 9 17
 Type: C / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Honda Shuttle cc 1496Colour: silver A/C Insured / Std / NI / NASp. Reading: 3698 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK8 110.1575Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

Rear

R/Bal: 9 mm R/Bal: 9 mmL/Bal: 9 mm L/Bal: 9 mmD.O.A. 10/12/17 D.O.I. 11/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S Frt, n/s 3-6
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

LIS - \$4800+ cred: \$ 6136.40 / 56%)

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp: (\$ _____) \$ + RS. \$☐ : Interview (\$ _____) Photo☐ : Tech. Invs (\$ _____) Other☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III17023433/Uua3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 11-12-2017



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8135G	Veh. Inspected	SLS 4725Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	10/12/2017	Inspection Date	11/12/2017
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hup

Our Ref: TF 2876/12/17 Your Ref: D

MS YEO YOKE GEN
BLK 333, /07-1923
ANG MO KIO AVE 1
SINGAPORE 560333

Estimate cost of repair to HONDA SHUTTLE 1.5 (A) S

1 pc front n/s fender	
6 pcs front n/s fender inner shield clips	u \$
1 pc front n/s door	
1 set front n/s door frame sticker	
2 pcs front n/s door top & low hinge	u \$ 5
1 pc front n/s door glass regulator	
12 pcs front n/s door inner trim board clips	u \$
1 pc front n/s door side mirror comp	
1 pc front n/s door checker	
1 pc front n/s door weatherstrip	
1 pc rear n/s door	
1 set rear n/s door frame sticker	
12 pcs rear n/s door inner trim board clips	u \$
2 pcs rear n/s door top & low hinge	u \$ 5
1 pc rear n/s door weatherstrip	
1 pc rear n/s fender	
6 pcs rear n/s fender inner garnish clips	u \$
1 pc rear n/s fender quarter glass moulding	
1 pc rear n/s fender quarter glass damper	
1 pc rear n/s fender quarter glass sealant	
1 pc rear bumper	
8 pcs rear bumper clips	u \$
1 pc rear bumper n/s side retainer	
1 pc n/s rocker panel sideskirt garnish	u \$
10 pcs n/s rocker panel sideskirt clips	u \$
1 pc n/s rocker panel sideskirt sealant	u \$
2 pcs front & rear n/s sport rim	

Less

60 To wiring check up for affected wiring system.	60.00	20
100 To remove & refix rear n/s fender quarter glass.	11 140.00	x
120 To remove & refix fuel tank, hose, pipe & necessary parts.	11 120.00	x
130 To check & adjust front & rear wheel alignment & balancing.	150.00	60

u 6,896.40

Balance C/F.....

1/5
\$4800+

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2576/12/17 Your Ref: Date: 11th DEC 2017

MS Y30 YOK3 GEN.,

Balance B/F... \$ 6,896.40

To remove & refix front & rear n/s door inner trim board cover, door glass, regulator, inner lock, channel, moulding, handle, hinge, checker, weatherstrip & necessary parts into new door.	250.00	60
To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set & necessary parts, to enable repair rear n/s fender, rocker panel & necessary parts.	120.00	60
To remove, refix & pump sealant for n/s rocker panel sideskirt.	120.00	50
To respray Tuff-Kote on all affected accident parts.	150.00	50
labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender, n/s rocker panel & necessary parts, to weld, renew & align above parts.	1,600.00	800
To putty & respray painting on all affected accident parts.	1,800.00	1300
	<u>\$ 10,936.40</u>	<u>6000</u>

Dollars : Ten Thousand Nine Hundred Thirty Six And Cents Forty Only.

HUP MOTOR TRADING & SERVICE

[Signature]

- L&K Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Approved
2/5 \$ 4800 / 5 day.
11/12/17

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)**Vehicle Particulars**

Vehicle No.	SLS47252	Vehicle Scheme	Normal
Vehicle Type	P10 - Passenger Motor Car		
Vehicle Attachment 1	No Attachment		
Vehicle Attachment 2	-	Vehicle Attachment 3	-
Vehicle Make	HONDA	Vehicle Model	SHUTTLE 1.5G A
Chassis No.	GK51101575	Engine No.	L1565001695
Motor No.	-	Trailer Chassis No.	-
Propellant	Petrol	Passenger Capacity	4
Engine Capacity	1498 cc	Power Rating	-
Maximum Power Output	97.0 kW (130 bhp)		
Unladen Weight	1130 kg	Maximum Laden Weight	1405 kg
Primary Colour	Silver	Secondary Colour	-
First Registration Date	26 Sep 2017	Original Registration Date	26 Sep 2017
Manufacturing Year	2016	Open Market value	\$17,506.00
PARF Eligibility	Yes	Minimum PARF Benefit	\$3,753.00
No. of Transfers	0	Additional Registration Fee Rate	First \$17,506.00 (100%)
Actual ARF Paid	\$7,506.00		

Owner Particulars

Owner Name	YEO YOKI GEN
Owner ID Type	Singapore NRIC
Owner ID	S7271967J
Registered Address Type	HDB / HUDC
Registered Block/House No.	333
Registered Street Name	ANG MO KIO AVENUE 1
Registered Unit No.	# 07 - 1923
Registered Building Name	-
Registered Postal Code	560333
COE No. / Expiry Date	2017100101000036H / 25 Sep 2027
COE Bid Category	A - Car up to 1600cc & 97kW (130bhp)
QP Paid	\$36,001.00

Transaction Details

Business Transaction Ref No.	20170926111903811950
Business Transaction Date	26 Sep 2017
Business Transaction Time	11:16:03

Message

The above vehicle has been successfully registered.

Please note that \$467.00 will be deducted from your GiRO account.



Print Received Message

This mail is associated with :

***SLS4725Z (MCT17120323)**
[SHC8135G]

TP

MISS YEO YOKE GEN

Dec 10 2017 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hup Motor Trading & Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/01/2018 16:43 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5405.35) - SLS4725Z - Claim Handler: Priya

Approved: 5405.35.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: <http://hupmotor.com.sg> Reg. No. 378091/00W

Our Ref: TP 2876/12/17

Your Ref: _____

Date: 23rd DEC 2017

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Dear Sirs,

RE : ACCIDENT ON 10/12/17 ALONG MERPATI RD
INVOLVING : SLS 4725 Z & YOUR INSURED : SHC 8135 G

We act for Ms Yeo Yoke Gen., NRIC No : S7271967J
Who is the registered owner of Veh. No : SLS 4725 Z Which was involved
in the above accident with Veh. No : SHC 8135 G Which we understand
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,
therefore, seeking compensation from you for my financial losses as
itemised below : -

Cost of repair	\$ 4,800.00
Car rental for 5 days (1 day X \$ 120.00)	600.00 (Client SUV)
LTA Search Fee & GIA-RMC Search Fee	5.35
Survey Fee	0.00
	\$ 5,405.35
	=====

We have enclosed copies of relevant documents to support my client's
claim, There was no receipt enclosed, as my client's did not pay us
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation
Letter, ~~GIA Report, Survey Report & Ins. Cert.~~

Remark : Kindly acknowledge receipt.

TO : INDIA INTERNATIONAL INSURANCE PTE. LTD.

AUTHORIZATION TO ACT

I, YEO YOKE GEN (S7271967J) ("the third party claimant")
of BLK 333, #07-1923, Ang Mo Kio Ave 1, S (560333) (address),
owner of SLS 4725 Z (vehicle no.) hereby authorize
Hup Motor Trading & Service,
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SLS 4725 Z that was damaged pursuant to the
accident which occurred on 10/12/17 (date) along Merpati
Road (location)
involving Vehicle No/s GHC 8135 G
("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit, and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 23rd day of December (month) 20 17 (year)

HUP MOTOR TRADING & SERVICE

S7271967J
Ms Yeo Yoke Gen (Owner Of SLS 4725 Z)
Signed by "the third party claimant"

7
Signed by "the workshop"

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MCT17120323

Claimant Ref: SLS 4725Z

We/I, Hup Motor Trading & Service ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4,800.00 (repair cost), S\$ 550.00 (loss of ~~use~~/rental), S\$ 5.35 (search fee), vehicle no. SLS 4725Z that was damaged pursuant to the accident which occurred on 10/12/2017 (date) at MERPATI ROAD (location) involving vehicle no. SHC 8135G (insured vehicle). This is pursuant to the inspection conducted on 11/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner MISS YEO YOKE GEN ("the third party claimant") of vehicle no. SLS 4725Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLS 4725Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,355.35 to Hup Motor Trading & Service

Dated this 9th day of January, 2018

HUP MOTOR TRADING & SERVICE

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

ANG BENG YEOW DAVID

NRIC:

S1547254/E

Address:

BLK 241, #08-1096, YISHUN

RING RD, S (760241)

SINGAPOREAN

Nationality:

Occupation:

MANAGER

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

Blk 51, Paya Ubi Industrial Park,

Ubi Avenue 1, #02-25 | S(408933)

Nationality:

Occupation:

-

-



cks

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2876/12/17 Your Ref: _____ Date: 23rd DEC 2017

MS YEO YOKE GEN
BLK 333, #07-1923
ANG MO KIO AVE 1
SINGAPORE 560333

Cost of repair to HONDA SHUTTLE 1.5 (A) S/Wagon - SLS 4725 Z

To supply fender inner shield clips, front n/s door, sticker, hinge, side mirror, rear bumper, clips, side retainer, n/s rocker panel sideskirt garnish, clips, sealant, sport rim & necessary parts.

To check & adjust front & rear wheel alignment & balancing, including wiring check up for affected wiring system, to remove & refix front n/s door inner trim board, glass, regulator, motor, moulding, channel, inner lock, handle, hinge, channel, weatherstrip & necessary parts.

To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set, n/s rocker panel garnish & necessary parts, including repump sealant for n/s rocker panel sideskirt.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front n/s fender, rear n/s door, rear n/s fender, n/s rocker panel & necessary parts, to weld, renew & align above parts,

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected accident parts.

Lumpsum Repair : \$ 4,800.00

=====

Dollars : Four Thousand And Eight Hundred Only.

HUP MOTOR TRADING & SERVICE



專營運善必甲出租
汽車修理
汽車保險賠償服務
嘉賓多授權服務中心

國家汽車服務

NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279
(off Ang Mo Kio Avenue 3) Singapore 569536
TEL: 6482 5577 (3 Lines) FAX: 6482 5000
TOWING SERVICE: 9182 8211 (After 10.30pm)
Reg. No: 062389/00M



TRUCK RENTAL
MOTOR REPAIR
INSURANCE CLAIMS
AGENCY
AUTHORISED CASTROL
SERVICE CENTRE

車輛出租合同 VEHICLE RENTAL AGREEMENT

Date:

18/11/17

Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")

Hirer: MS YEO YOKE GEN (Owner of SLS 4725 Z)

Address: BLK 333, #07-1923, ANG MO KIO AVE 1, S (560333)

NRIC / Co. Reg. No: S7271967J

Tel: 90700372 (Owner) Fax: H/P: 93684524 (Driver)

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SJC 9076 R		TOYOTA WISH S/Wagon	Agreement No: 56275	
Driver's Particulars				
Name: MS HO SOO LEE			Odometer:	
Address: BLK 333, #08-1913, ANG MO KIO AVE 1, S (560333)			Date & Time Out: 18/11/17 10.30hrs	
I/C No: S7737699B			Date & Time In: 23/12/17 1000HRS	
Dr/Licence No: S7737699B		Hour @\$		
Date of Issue: 27/05/06		5 Days @\$ 120-00 \$ 600-00		
YOD: 27/05/06		Wks @\$		
Date of Birth: 24/12/77		Mths @\$		
Tools: One set		Deposit (Refundable): NIL		
Spare Tyre: One set		Sub-Total: \$ 600-00		
		Balance To Pay: \$ 600-00		

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner \$5,000 comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$3,000 excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreen) plus loss of earnings while damaged vehicle is under repair.

Authorized Driver

Hirer shall pay additional excess of \$51500 if the Authorized Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below

PETROL
PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE

Authorized Signature

Hirer's Signature

ATTN: DAVID

U/M

Enquire Vehicle & Owner Information (Vehicle No. SHC8135G As At 10 Dec 2017 / 13:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: HL/HMT/2017/CK

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC8135G

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	MISS YEO YOKE GEN, ID: 572719673		
Vehicle Reg. No.:	SLS4725Z	Date of Loss:	10/12/2017 13:00 - :59
Claim Type:	TP / MCT17120323	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC8135G	Policy No. (Claimant):	DMPCSN3075771700
		Excess:	
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (08/01/2018): Alert - Adj Mandate Approved (S\$5405.35) - SLS4725Z - Claim Handler: Priya
- III_SG (12/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SLS4725Z - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS4725Z (MCT17120323)

[SHC8135G]

TP

MISS YEO YOKE GEN

Dec 10 2017 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hup Motor Trading & Service

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/12/17 14:41	General View							 Load JPG	☒	
2	11/12/17 14:41	General View							 Load JPG	☒	
3	11/12/17 14:41	General View							 Load JPG	☒	
4	11/12/17 14:41	General View							 Load JPG	☒	
5	11/12/17 14:41	General View							 Load JPG	☒	
6	11/12/17 14:41	General View							 Load JPG	☒	
7	11/12/17 14:41	General View							 Load JPG	☒	
8	11/12/17 14:41	General View							 Load JPG	☒	
9	11/12/17 14:41	General View							 Load JPG	☒	
10	11/12/17 14:41	General View							 Load JPG	☒	
11	11/12/17 14:41	General View							 Load JPG	☒	
12	11/12/17 14:41	General View							 Load JPG	☒	
13	11/12/17 14:41	General View							 Load JPG	☒	
14	11/12/17 14:41	General View							 Load JPG	☒	
15	11/12/17 14:41	General View							 Load JPG	☒	
16	11/12/17 14:41	General View							 Load JPG	☒	
17	11/12/17 14:41	General View							 Load JPG	☒	
18	11/12/17 14:41	General View							 Load JPG	☒	
19	11/12/17 14:41	General View							 Load JPG	☒	
20	11/12/17 14:41	General View							 Load JPG	☒	
21	11/12/17 14:41	General View							 Load JPG	☒	
22	11/12/17 14:41	General View							 Load JPG	☒	
23	11/12/17 14:41	General View							 Load JPG	☒	
24	11/12/17 14:41	General View							 Load JPG	☒	
25	11/12/17 14:41	General View							 Load JPG	☒	
26	11/12/17 14:41	General View							 Load JPG	☒	
27	11/12/17 14:41	General View							 Load JPG	☒	
28	11/12/17 14:41	General View							 Load JPG	☒	
29	11/12/17 14:41	General View							 Load JPG	☒	
30	11/12/17 14:41	General View							 Load JPG	☒	
31	11/12/17 14:41	General View							 Load JPG	☒	
32	11/12/17 14:41	General View							 Load JPG	☒	
33	11/12/17 14:41	General View							 Load JPG	☒	
34	11/12/17 14:41	General View							 Load JPG	☒	
35	11/12/17 14:41	General View							Load JPG	☒	

36	11/12/17 14:41	General View	1	Load JPG	☒
37	11/12/17 14:41	General View	1	Load JPG	☒
38	11/12/17 14:41	General View	1	Load JPG	☒
39	11/12/17 14:41	General View	1	Load JPG	☒
40	11/12/17 14:41	Odometer Reading	1	Load JPG	☒
41	11/12/17 14:41	General View	1	Load JPG	☒
42	11/12/17 14:41	Chassis Number	1	Load JPG	☒
Documentation					
				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 15:55	TP GIA REPORT	1	Load PDF	
2	26/12/17 11:45	TP ESTIMATE - MARKED	1	Load PDF	
3	05/01/18 11:41	WORKSHOP INVOICE	1	Load PDF	
4	05/01/18 11:41	RENTAL RECEIPT	1	Load PDF	
5	05/01/18 11:41	LTA SEARCH	1	Load PDF	
6	05/01/18 11:41	LOD	1	Load PDF	
7	15/01/18 17:02	DISCHARGE VOUCHER	1	Load PDF	
8	15/01/18 17:02	AUTHORISATION TO ACT FORM	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 08:47	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17023433/UUA3Q2

Date: 15/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLS4725Z Insured Vehicle No: SHC8135G
 Date of Loss: 10/12/2017 Nature of Claim: TP Claim No: MCT17120323

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS4725Z
 Make & Model: HONDA SHUTTLE, 1.5 G (A) Engine No: L15B5001895
 Reg. Date: 26/09/2017 (Man. Year: 2016) Chassis No: GK81101575
 Colour: Silver Odometer: 3699 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,426.40	3,605.60	2,820.80	43.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	2,400.00	2,110.00	46.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,936.40	6,005.60	4,930.80	45.09
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	10,936.40	4,800.00	6,136.40	56.11
+ Car Rental (5.0 x S\$110.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		5,355.35		

INSPECTION

Date of Assignment: 11/12/2017
 Date Inspected: 11/12/2017 Inspected At: Hup Motor Trading & Service (HQ)
 Blk 9004 Tampines Street 93, #01-120
 Singapore 528838
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jan 2018)	
Parts:	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS4725Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Repair	479.10 FL	*- FL
2	6		*FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	23.40 FL	*23.40 FL
3	1		*FRONT N/S DOOR	Dented / Bent	992.30 FL	*992.30 FL
4	1		*FRONT N/S DOOR FRAME STICKER	Necessary	48.80 FL	*48.80 FL
5	2		*FRONT N/S DOOR TOP & LOW HINGE	Not Necessary	107.80 FL	*- FL
6	1		*FRONT N/S DOOR GLASS REGULATOR	Not Necessary	451.30 FL	*- FL
7	12		*FRONT N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	69.60 FL	*- FL
8	1		*FRONT N/S DOOR SIDE MIRROR COMP	Deep Cut	681.20 FL	*681.20 FL
9	1		*FRONT N/S DOOR CHECKER	Not Necessary	53.90 FL	*- FL
10	1		*FRONT N/S DOOR WEATHERSTRIP	Necessary	86.10 FL	*86.10 FL
11	1		*REAR N/S DOOR	Repair	928.90 FL	*- FL
12	1		*SET REAR N/S DOOR FRAME STICKER	Not Necessary	35.40 FL	*- FL
13	12		*REAR N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	69.60 FL	*- FL
14	2		*REAR N/S DOOR TOP & LOW HINGE	Not Necessary	100.60 FL	*- FL
15	1		*REAR N/S DOOR WEATHERSTRIP	Not Necessary	45.40 FL	*- FL
16	1		*REAR N/S FENDER	Repair	975.70 FL	*- FL
17	6		*REAR N/S FENDER INNER GARNISH CLIPS	Not Necessary	34.80 FL	*- FL
18	1		*REAR N/S FENDER QUARTER GLASS MOULDING	Not Necessary	68.90 FL	*- FL
19	1		*REAR N/S FENDER QUARTER GLASS DAMPER	Not Necessary	45.00 FL	*- FL
20	1		*REAR N/S FENDER QUARTER GLASS SEALANT	Not Necessary	60.00 FL	*- FL
21	1		*REAR BUMPER	Cut	928.90 FL	*928.90 FL
22	8		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
23	1		*REAR BUMPER N/S SIDE RETAINER	Necessary	25.10 FL	*25.10 FL
24	1		*N/S ROCKER PANEL SIDESKIRT GARNISH	Deep Cut	478.40 FL	*478.40 FL
25	10		*N/S ROCKER PANEL SIDESKIRT CLIPS	Necessary	39.00 FL	*39.00 FL
26	1		*N/S ROCKER PANEL SIDESKIRT SEALANT	Necessary	60.00 FL	*60.00 FL
27	2		*FRONT & REAR N/S SPORT RIM	Cut	1,112.60 FL	*1,112.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,033.00	4,507.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,606.60	901.40
Total Parts (S\$)	6,426.40	3,605.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	60.00	20.00
2	TO REMOVE & REFIX REAR N/S FENDER QUARTER GLASS	New	140.00	0.00
3	TO REMOVE & REFIX FUEL TANK ,HOSE ,PIPE & NECESSARY PARTS	New	120.00	0.00
4	TO CHECK & ADJUST FRONT & REAR WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
5	TO REMOVE & REFIX FRONT & REAR N/S DOOR INNER TRIM BOARD COVER ,DOOR GLASS ,REGULATOR ,INNER LOCK ,CHANNEL ,MOULDING ,HANDLE,HINGE ,CHECKER,WEATHERSTRIP & NECESSARY PARTS INTO NEW DOOR	New	250.00	60.00
6	TO REMOVE & REFIX CUSHION SEAT ,CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER ,TOOL SET & NECESSARY PARTS ,TO ENABLE REPAIR REAR N/S FENDER ,ROCKER PANEL & NECESSARY PARTS	New	120.00	60.00
7	TO REMOVE,REFIX & PUMP SEALANT FOR N/S ROCKER PANEL SIDESKIRT	New	120.00	50.00
8	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	150.00	50.00
9	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR N/S FENDER ,N/S ROCKER PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,600.00	800.00
10	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,800.00	1,300.00
Gross Labour Cost (S\$)			4,510.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >