

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2876/12/17 Your Ref: Date: 11th DEC 2017

MS YEO YOKE GEN
BLK 333, #07-1923
ANG MO KIO AVE 1
SINGAPORE 560333

Estimate cost of repair to HONDA SHUTTLE 1.5 (A) S/Wagon - SLS 4725 4

1 pc front n/s fender		2	\$ 479.10	α
6 pcs front n/s fender inner shield clips	© \$ 3.90	ru	23.40	—
1 pc front n/s door		ad/set	992.30	—
1 set front n/s door frame sticker		ru	48.80	—
2 pcs front n/s door top & low hinge	© \$ 53.90	11	107.80	α
1 pc front n/s door glass regulator		11	451.30	α
12 pcs front n/s door inner trim board clips	© \$ 5.80	11	69.60	α
1 pc front n/s door side mirror comp		Deep cut	681.20	—
1 pc front n/s door checker		11	53.90	α
1 pc front n/s door weatherstrip		ru	86.10	—
1 pc rear n/s door		2	928.90	α
1 set rear n/s door frame sticker		11	35.40	α
12 pcs rear n/s door inner trim board clips	© \$ 5.80	11	69.60	α
2 pcs rear n/s door top & low hinge	© \$ 50.30	11	100.60	α
1 pc rear n/s door weatherstrip		11	45.40	α
1 pc rear n/s fender		2	975.70	α
6 pcs rear n/s fender inner garnish clips	© \$ 5.80	11	34.80	α
1 pc rear n/s fender quarter glass moulding		11	68.90	α
1 pc rear n/s fender quarter glass damper		11	45.00	α
1 pc rear n/s fender quarter glass sealant		11	60.00	α
1 pc rear bumper		cut	928.90	—
8 pcs rear bumper clips	© \$ 3.90	ru	31.20	—
1 pc rear bumper n/s side retainer		ru	25.10	—
1 pc n/s rocker panel sideskirt garnish		Deep cut	478.40	—
10 pcs n/s rocker panel sideskirt clips	© \$ 3.90	ru	39.00	—
1 pc n/s rocker panel sideskirt sealant		ru	60.00	—
2 pcs front & rear n/s sport rim	© \$ 556.30	cut	1,112.60	—
			\$ 8,033.00	4507
	Less 20%		\$ 1,606.60	3605.6
			\$ 6,426.40	

- 60 To wiring check up for affected wiring system. 60.00 20
- 140 To remove & refix rear n/s fender quarter glass. 11 140.00 α
- 120 To remove & refix fuel tank, hose, pipe & necessary parts. 11 120.00 α
- 150 To check & adjust front & rear wheel alignment & balancing. 150.00 60

\$ 6,896.40
Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2876/12/17 Your Ref: Date: 11th DEC 2017

MS YEO YOKE GEN.,

Balance B/F... \$ 6,896.40

To remove & refix front & rear n/s door inner trim board cover, door glass, regulator, inner lock, channel, moulding, handle, hinge, checker, weatherstrip & necessary parts into new door. 250.00 60

To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set & necessary parts, to enable repair rear n/s fender, rocker panel & necessary parts. 120.00 60

To remove, refix & pump sealant for n/s rocker panel sideskirt. 120.00 50

To respray Tuff-Kote on all affected accident parts. 150.00 50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender, n/s rocker panel & necessary parts, to weld, renew & align above parts. 1,600.00 800

To putty & respray painting on all affected accident parts. 1,800.00 1300

\$ 10,936.40

===== 60056

Dollars : Ten Thousand Nine Hundred Thirty Six And Cents Forty Only.

HUP MOTOR TRADING & SERVICE

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
L/S \$ 4800 /
5 day.
11/12/17