

ASS. REC. BY:

REF:

CG/MSG17023434/Mlg6

Special Instruction:

SUNAJOR:

ma.

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSCI

Date/Time:

08/12/2017 635pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SCW 8026S

Insured:

SDJ 918C

at Workshop m/s

Chew Goon

Tel:

6484 1626

of

Blk 10 Amk Ind Park 2A #01-15

Policy No:

A289839521VW

Claim No:

539239

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/12/2017

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

11/12/2017

10:17am

Person Contacted:

Grace

Vehicle

IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SCW 8026S - X
	SDJ 918C - NA / MSCD 902615 / W1
	DCA: 1911-09
12/12/17 @ 2:16pm	revised to Monica Chung via Weizen.
31/12/18 @ 4:27pm	confirmed with Grace is \$3500, 5 days.
	CPA \$1877.75, 35%.

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of CHEN BOND

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SCW80265 Yr Regn: APD / 1999Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SOLUNA c.c. 1498Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 242988 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRC53AN5000037351Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R14R: 185/65R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAKRENFront 8 mm Rear 8 mmR/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 03/12/07 D.O.I. 11/12/07Survey held at CHEN BONDDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[Signature]  
1/6/2018

RECEIVED 01 JUN 2010

Date/Time, File Pass to?

1) 01/6/2018 TP

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

200

10

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) Photos

) Others:

TOTAL

210

Report Format: MEP-TPLump Sum / I.B.I: (\$ 3500)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17023434/M1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-12-2017	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SDJ 918C	Veh. Inspected	SCW 8026S
Policy No.	A28983952AVW	Coverage (\$)	0.00
Claim No.	539239	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	08/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	03/12/2017	Inspection Date	11/12/2017
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 12 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: SDJ918C	Accident Date	: 03/12/2017
TP Vehicle No	: SCW8026S	Assignment Date	: 08/12/2017
Make	: TOYOTA SOLUNA	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/12/2017		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,377.75
Revised Amount	:S\$	3,756.60
Check Items (Estimated)	:S\$	764.75
Total	:S\$	4,521.35

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Fct Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Dec 2017 10:11 <a href="#">Sendback Est</a>	08 Dec 2017 10:49 <b>S\$5,377.75</b>	08 Dec 2017 18:35 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b> <b>Insured:</b> CHONG CHIEW YOON, ID: S1490942G, Tel: +6596420939 <b>Main Claimant:</b> LEE CHIEW HUA, ID: S1117460D <b>Vehicle Reg. No.:</b> SCW8026S <b>Date of Loss:</b> 03/12/2017 12:00 - :59 <b>Claim Type:</b> TP / 539239 <b>Policy/Cover Note No.:</b> A28983952AVW (Comprehensive) <b>Vehicle Reg. No. (Insured):</b> SDJ918C <b>Policy No. (Claimant):</b> Coverage: 29/06/2017 - 28/06/2018 <b>Excess:</b> <b>Repairer:</b> Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626 <b>Handling Insurer:</b> MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552] <b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/12/2017] <b>Driver/Custodian (Insured):</b> LEE YUNXI (20 / Male), NRIC: S9722896E, Tel: +6593610002																								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a> There are no mail for this case.																								
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

11.12.2017 @ 10:17am  
Grou veh in

## Shiau Chan (LKKAUTO)

---

**From:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>  
**Sent:** Thursday, 31 May 2018 4:22 PM  
**To:** Ma C.F (LKKAUTO)  
**Cc:** Shiau Chan (LKKAUTO); chewgoon@singnet.com.sg  
**Subject:** RE: SCW8026S date of acc: 03.12.2017

Dear Shiau Chan/ Mr Ma,

As spoken, confirm L/S amount \$3500.00 and 5 working days.

Thanks & Regards,  
Grace

### **Chew Goon Motor**

Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15, 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Chew Goon Motor(ad3)  
**Sent:** Thursday, 19 April 2018 3:28 PM  
**To:** Ma C.F (LKKAUTO)  
**Cc:** Shiau Chan (LKKAUTO); chewgoon@singnet.com.sg  
**Subject:** RE: SCW8026S date of acc: 03.12.2017

Dear Mr Ma,

### **Gentle reminder.**

We wish to counter propose L/S \$3600.00.

Our breakdown as following:-

Parts :	2549.00
+15%:	382.35
-----	
	2931.35
L/B:	1590.00
-----	
Total:	4521.35
-----	

L/S 3617.08

Please revert.



SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	04/12/2017 11:30
Date Of Accident	03/12/2017 12:15
Exact Location Of Accident	SENGKANG EAST RD SLIP RD TOWARDS TPE
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SCW8026S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE CHIEW HUA
NRIC No	S1117460D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93610001
Alternative Phone No	OTHERS-93610001

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	SOLUNA GLI A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

**Insurance Company**

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	0086319715-13
Cover Note Number	

**Driver**

Name of Driver	CHARLES WONG
NRIC No	S1484728F
Date Of Birth	08/12/1951
Occupation	INDOOR
Date Of Driving Pass	21/09/1973
Driving Experience	44 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93610002
Fax Number	
Contact Number	
EEmail Address	ACEEWONG@HOTMAIL.COM



Address	BLK 260D SENGKANG EAST WAY #03-480
Postcode	544260
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 3/12/17, MY CAR STOPPED AT THE SLIP ROAD ON SENGKANG EAST ROAD TOWARDS TPE TO GIVE WAY TO ON COMING TRAFFIC, SUDDENLY CAR (SDJ918C) HIT MY CAR (SCW8026S) FROM BEHIND.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDJ918C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	MR LEE
NRIC/Passport Number	
Contact Number	97976882
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: 

### Sketch Plan #2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/12/17, my car stopped at the sliproad on Sengkang East Road towards TPE to give way to oncoming traffic. Suddenly car SDJ918C hit my car SCW80265 from behind.

## DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_


Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

REPUBLIC OF SINGAPORE
DRIVING LICENCE



Licence Number: **S1484728F**  
Name: **CHARLES WONG**  
Birth Date: **08 Dec 1951**  
Issue Date: **08 Sep 2003**


000812907A


REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S1117460D**




Name: **LEE CHIEW HUA**  
Race: **CHINESE**  
Date of Birth: **12-04-1955**  
Country of Birth: **SINGAPORE**


S1117460D

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S1484728F**



Name: **CHARLES WONG**  
Race: **CHINESE**  
Date of Birth: **08-12-1951**  
Country of Birth: **SELANGOR**


S1484728F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles <= 200 CC	07 May 1976
Class 2A	Motorcycles between 201 CC and 400 CC	07 May 1976
Class 2	Motorcycles > 400 CC	07 May 1976
Class 3	Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	21 Sep 1973

S1484728F

S / No. 9000233983


Licence No: S1484728F

NP 428A




NRIC No. **S1117460D**

Blood Group: **A+** Date of issue: **10-08-1993**

APT BLK 260D SENGKANG EAST WAY #03-480  
SINGAPORE 544260

NRIC No: **S1117460D** Date: **05-05-2001** No: **3963434**



NRIC No. **S1484728F**

Blood Group: **O+** Date of issue: **10-08-1993**

APT BLK 260D SENGKANG EAST WAY #03-480  
SINGAPORE 544260

NRIC No: **S1484728F** Date: **05-05-2001** No: **3963433**

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 0086319715-13

**Cover :** Third Party, Fire & Theft

1. Index mark and Registration Number of Vehicle : **SCW8026S**  
Chassis Number : **MR053AN5000037351**
2. Name of Policyholder : **LEE CHIEW HUA**
3. Effective Date of Insurance : **25 Apr 2017**
4. Expiry Date of Insurance : **24 Apr 2018**
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

**This Policy does not cover**

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
PRIMARY DRIVER	: LEE CHIEW HUA
NAMED DRIVER (1)	: CHARLES WONG
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ERNEST YONG INSURANCE AGENCY (00000591289)  
Date of Issue : 20 Mar 2017 11:19 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

**Chew Goon Motor** (Co.Reg.No:22188000C)Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint  
Singapore 568047

Tel: 64841626 Fax: 64840465 Email: aaronm3@chewgoonmotor.com.sg;chewgoon@singnet.com.sg

**TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)****LEE CHIEW HUA**

BLK 260D SENGKANG EAST WAY #03-480

Singapore 544260

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	31217_SCW8026S
Policy No:		Date of Loss:	03/12/2017
Vehicle Reg. No.:	SCW8026S	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (Insured):	CHARLES WONG		
Make/Model:	TOYOTA SOLUNA, GLI	Vehicle Reg. Date:	24/04/1999
Vehicle Colour:	SILVER		
Engine No:	5AH202762	Chassis No:	MR053AN5000037351
Odometer:	242988 KM		

Paint Type:

Total Loss? **NO**Est. Duration 7  
of Repair  
(day)

Description of ON 3/12/17, MY CAR STOPPED AT THE SLIP ROAD ON SENGKANG EAST ROAD  
Accident/Loss TOWARDS TPE TO GIVE WAY TO ON COMING TRAFFIC, SUDDENLY CAR  
(SDJ918C) HIT MY CAR (SCW8026S) FROM BEHIND.

Present Location: CHEW GOON MOTOR (AMK)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	3,317.75
Miscellaneous Items	0.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>5,377.75</b>
<b>+ GST 7.00% (\$\$)</b>	<b>376.44</b>
<b>Nett Amount (\$\$)</b>	<b>5,754.19</b>

**This claim is handled by: ERIC CHEW**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**



**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2017)

Parts: 143 TOYOTA SOLUNA GLI (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Chew Goon Motor/SCW8026S/08/12/2017 10:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR NUMBER PLATE	0.00	0.00	45.00 F 40 ✓
2	1		*REAR BUMPER	0.00	0.00	360.00 F ✓
3	10		*REAR BUMPER CLIPS	0.00	0.00	15.00 F ✓
4	1		*REAR BUMPER TOP REINFORCEMENT	0.00	0.00	295.00 Fx ✓
5	2		*REAR BUMPER CORNER RETAINERS	0.00	0.00	20.00 F ✓
6	1		*REAR NUMBER PLATE LAMP	0.00	0.00	36.00 F ✓
7	1		*BOOT	0.00	0.00	1,030.00 F ✓
8	1		*BOOT EMBLEM	0.00	0.00	32.00 F ✓
9	1		*BOOT BADGE 1.5	0.00	0.00	33.00 F ✓
10	1		*BOOT BADGE GLI	0.00	0.00	36.00 F ✓
11	1		*BOOT BADGE SOLUNA	0.00	0.00	42.00 F ✓
12	1		*BOOT LOCK	0.00	0.00	48.00 F ✓
13	1		*BOOT LOCK CATCH	0.00	0.00	36.00 F x
14	1		*BOOT WEATHERSTRIP	0.00	0.00	92.00 F ✓
15	1		*END PANEL BUC	0.00	0.00	495.00 F ? ✓
16	1		*SPARE TYRE BOARD	0.00	0.00	100.00 F ✓
17	1		*TAILLAMP ASSY LH CPA	0.00	0.00	170.00 F ? ✓

F=Franchise part.

Sub Total (S\$)	2,885.00
+ Margin on L,N Items 15.00% (S\$)	432.75
<b>Total Parts (S\$)</b>	<b>3,317.75</b>

Chew Goon Motor/SCW8026S/08/12/2017 10:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CONDUCT REAR ELECTRICAL CHECK, LOCKING SYSTEM, ADJUST, TAIL LAMP ETC	New	30.00 ✓
2	TO DISMANTLE / TRANSFER BOOT FITTING / ANCILLARY ACCESSORIES	New	<del>90.00</del> X.
3	TO DISMANTLE / TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS / GARNISH AND REAR FENDERS INNER TRIMS BOARDS / GARNISH TO FACILITATE REPAIR	New	<del>80.00</del> 40
4	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	100.00 60
5	LABOUR CHARGE - PANEL BEATING, REPAIRING OF REAR CHASSIS MEMBER, INNER PANEL, SPARE TYRE PANEL, CNT, WELD END PANEL AND PARTS REPLACEMENT	New	<del>900.00</del> 700
6	TO RESPRAY AFFECTED AREAS	New	<del>800.00</del> 700
7	TO SUPPLY END PANEL JOINT SEALANT	New	60.00 ✓
Gross Labour Cost (S\$)			2,060.00

Chew Goon Motor/SCW8026S/08/12/2017 10:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Not Authorised

R/S. Repair

Before Paint Photos

11/12/2017

Hk Auto (Mk)

5w/ day 8

  
12/12/17

4/5 Repair  
\$3500  
5w/ day 8



# REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 08 Dec 2017)
Parts:	143	TOYOTA SOLUNA GLI (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Chew Goon Motor/SCW8026S/08/12/2017 10:49		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *		

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR NUMBER PLATE	0.00	0.00	45.00F ✓
2	1		*REAR BUMPER	0.00	0.00	360.00F ✓
3	10		*REAR BUMPER CLIPS	0.00	0.00	15.00F ✓
4	1		*REAR BUMPER TOP REINFORCEMENT	0.00	0.00	295.00F ✓
5	2		*REAR BUMPER CORNER RETAINERS	0.00	0.00	20.00F ✓
6	1		*REAR NUMBER PLATE LAMP	0.00	0.00	36.00F ✓
7	1		*BOOT	0.00	0.00	1,030.00F ✓
8	1		*BOOT EMBLEM	0.00	0.00	32.00F ✓
9	1		*BOOT BADGE 1.5	0.00	0.00	33.00F ✓
10	1		*BOOT BADGE GLI	0.00	0.00	36.00F ✓
11	1		*BOOT BADGE SOLUNA	0.00	0.00	42.00F ✓
12	1		*BOOT LOCK	0.00	0.00	48.00F ✓
13	1		*BOOT LOCK CATCH	0.00	0.00	36.00F x
14	1		*BOOT WEATHERSTRIP	0.00	0.00	92.00F ✓
15	1		*END PANEL / <i>Rec</i>	0.00	0.00	495.00F ?
16	1		*SPARE TYRE BOARD	0.00	0.00	100.00F ✓
17	1		*TAILLAMP ASSY LH / <i>CA</i>	0.00	0.00	170.00F ?

F=Franchise part.

Sub Total (S\$) 2,885.00  
+ Margin on L,N Items 15.00% (S\$) 432.75

Total Parts (S\$) 3,317.75

Chew Goon Motor/SCW8026S/08/12/2017 10:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

*Goo Air*  
*03/1/18*

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CONDUCT REAR ELECTRICAL CHECK, LOCKING SYSTEM, ADJUST, TAIL LAMP ETC	New	30.00 ✓
2	TO DISMANTLE / TRANSFER BOOT FITTING / ANCILLARY ACCESSORIES	New	<del>80.00</del> X.
3	TO DISMANTLE / TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS / GARNISH AND REAR FENDERS INNER TRIMS BOARDS / GARNISH TO FACILITATE REPAIR	New	<del>80.00</del> 40
4	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	<del>100.00</del> 60.
5	LABOUR CHARGE - PANEL BEATING, REPAIRING OF REAR CHASSIS MEMBER, INNER PANEL, SPARE TYRE PANEL, CNT, WELD END PANEL AND PARTS REPLACEMENT	New	<del>900.00</del> 700.
6	TO RESPRAY AFFECTED AREAS	New	<del>800.00</del> 700
7	TO SUPPLY END PANEL JOINT SEALANT	New	60.00 ✓
Gross Labour Cost (S\$)			2,060.00

Chew Goon Motor/SCW8026S/08/12/2017 10:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Not Authorised  
R/P Repair  
Before Paint Photo  
11/12/2017  
HKK Auto (mk)  
Sunday 8

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023434/M1QBN2

Date: 04/06/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28983952AVW
Claimant Vehicle No :	SCW8026S	Insured Vehicle No :	SDJ918C
Date of Loss:	03/12/2017	Nature of Claim:	TP
		Claim No:	539239

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCW8026S	Engine No:	5AH202762
Make & Model:	TOYOTA SOLUNA, GLI	Chassis No:	MR053AN5000037351
Reg. Date:	24/04/1999 (Man. Year: 1999)	Odometer:	242988 km
Colour:	Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,317.75	2,925.35	392.40	11.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,590.00	470.00	22.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,377.75</b>	<b>4,515.35</b>	<b>862.40</b>	<b>16.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	<b>5,377.75</b>	<b>3,500.00</b>	<b>1,877.75</b>	<b>34.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>376.44</b>	<b>245.00</b>	<b>131.44</b>	<b>34.92</b>
<b>Nett Amount (S\$)</b>	<b>5,754.19</b>	<b>3,745.00</b>	<b>2,009.19</b>	<b>34.92</b>

### INSPECTION

Date of Assignment:	08/12/2017 Present Location:	Chew Goon Motor (AMK)
Date Inspected:	11/12/2017 Inspected At:	Chew Goon Motor (AMK)
		Blk 10 Ang Mo Kio Industrial Park 2A,
		#01-15/16 & 17, AMK Autopoint
		Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
<b>Parts:</b> 143	TOYOTA SOLUNA GLI (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SCW8026S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	45.00 F	*40.00 FS
2	1		*REAR BUMPER	Deformed	360.00 F	*360.00 F
3	10		*REAR BUMPER CLIPS	Necessary	15.00 F	*15.00 F
4	1		*REAR BUMPER TOP REINFORCEMENT	No such part	295.00 F	*- F
5	2		*REAR BUMPER CORNER RETAINERS	Distorted	20.00 F	*20.00 F
6	1		*REAR NUMBER PLATE LAMP	Missing	36.00 F	*36.00 F
7	1		*BOOT	Bent	1,030.00 F	*1,030.00 F
8	1		*BOOT EMBLEM	Necessary	32.00 F	*32.00 F
9	1		*BOOT BADGE 1.5	Necessary	33.00 F	*33.00 F
10	1		*BOOT BADGE GLI	Necessary	36.00 F	*36.00 F
11	1		*BOOT BADGE SOLUNA	Necessary	42.00 F	*42.00 F
12	1		*BOOT LOCK	Bent	48.00 F	*48.00 F
13	1		*BOOT LOCK CATCH	Repair	36.00 F	*- F
14	1		*BOOT WEATHERSTRIP	Necessary	92.00 F	*92.00 F
15	1		*END PANEL	Buckled	495.00 F	*495.00 F
16	1		*SPARE TYRE BOARD	Torn	100.00 F	*100.00 F
17	1		*TAILLAMP ASSY LH	Cracked	170.00 F	*170.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>2,885.00</b>	<b>2,549.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (S\$)</b>	<b>432.75</b>	<b>376.35</b>
<b>Total Parts (S\$)</b>	<b>3,317.75</b>	<b>2,925.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT REAR ELECTRICAL CHECK, LOCKING SYSTEM, ADJUST, TAIL LAMP ETC	New	30.00	30.00
2	TO DISMANTLE / TRANSFER BOOT FITTING / ANCILLARY ACCESSORIES	New	90.00	-
3	TO DISMANTLE / TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS / GARNISH AND REAR FENDERS INNER TRIMS BOARDS / GARNISH TO FACILITATE REPAIR	New	80.00	40.00
4	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	100.00	60.00
5	LABOUR CHARGE - PANEL BEATING, REPAIRING OF REAR CHASSIS MEMBER, INNER PANEL, SPARE TYRE PANEL, CNT, WELD END PANEL AND PARTS REPLACEMENT	New	900.00	700.00
6	TO RESPRAY AFFECTED AREAS	New	800.00	700.00
7	TO SUPPLY END PANEL JOINT SEALANT	New	60.00	60.00
Gross Labour Cost (\$\$)			2,060.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >