

ASS. REC. BY:

REF:

CS/AU17023438/Kgb

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Chin Lee Yng

of

PUC

Date/Time:

11/12/2017 9:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S47 706C

Insured:

at Workshop m/s

Motor Image

Tel:

7299 2683

of

19 Jorong 8 Tuo Payoh

Policy No:

2100 699590

Claim No:

998992246856

Sum Insured:

Excess:

700/-

Make of Veh:

(Client's Record)

D.O.A.

03-12-2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/12/2017 10:37am

Person Contacted:

Sayed

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

S47 706C - CIG/AXA 14005827 / Cip/SC3

DUT: 250311

12/12/17 @ 12:13pm revert to Victor via Messenger

14/12/17 @ 12:31pm authorise repair by Victor (mandate remark)

14/12/17 @ 2:05pm informed Sayed authorise repair via email & phone call excess \$700/-

18/12/17 @ 4:54am informed Saye re-adjust labour to 3 days instead of 6

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *8100k*

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *3* days*66*

Res: Yes or No

Lum Sum: *20 + A1* %*20 + A1*

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SGZ 706C*Yr Regn: *01, 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Subaru*Colour: *M. Grey*Sp. Reading: *11235*

Eng/No: _____

C/No: *JF18 JGK 8566 083525*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *225/55R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: *8*R/Bal: *8* mmL/Bal: *8* mmD.O.A: *8/12/17*Rear: *8*R/Bal: *8* mmL/Bal: *8* mmD.O.I: *11/12/17*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*12/12**File pass to Catherine**02/08/18 @ 4.43pm**Confirmed with Saye is \$4700, 3 days by email.
Used \$583.86, 55%.*

RECEIVED 03 AUG 2018

Date/Time, File Pass to?

☐

Preli. Report

02/08/18☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: *MEMO*Lump Sum / I.B.T. is *4700*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG17023438/Kqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-12-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGZ 706C
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From CHIN LEE YING	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 08/12/2017	Inspection Date 11/12/2017
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

- FW: SGZ706C-OD-AIG-SURVEY-11/12/2017-VEHICLE NON DRIVABLE

From: Chin, Lee-Ying
To: 'assignments', 'Admin A'
Cc: Fong, Andy-SY
Sent: Monday, 11 December, 2017 9:39:14 AM
Attachments:  SGZ706C ESTIMATE.PDF  SGZ706C OD GIA REPORT.PDF

Hi LKK,


Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Sayedinah Bin Ali [<mailto:sayedinah@motorimage.net>]
Sent: Saturday, December 09, 2017 5:42 PM
To: AIG SGP, Claims-Survey
Cc: Chin, Lee-Ying
Subject: SGZ706C-OD-AIG-SURVEY-11/12/2017-VEHICLE NON DRIVABLE
Importance: High

Hi Claims Team,
Kindly arrange survey on the 11/12/2017. Vehicle in
Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Thursday, 2 August 2018 4:43 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR; Daniel Lim; Daniel Jude; Kuan Wei Loong
Subject: RE: FINAL BILL OF VEHICLE SGZ 706C (DOA: 08/12/2017)

Hi Shiau Chan,
Accept.

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 2 August 2018 4:25 PM
To: Sayedinah <sayedinah@motorimage.net>
Cc: SUR <sur@lkkauto.com>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: RE: FINAL BILL OF VEHICLE SGZ 706C (DOA: 08/12/2017)

Dear Saye,

Can we confirm?

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 July 2018 12:06 PM
To: Sayedinah <sayedinah@motorimage.net>
Cc: SUR <sur@lkkauto.com>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: RE: FINAL BILL OF VEHICLE SGZ 706C (DOA: 08/12/2017)

Dear Saye,

WITHOUT PREJUDICE

Offer Lump Sum \$4,700.00 before excess \$700.00 & GST and 3 repair days. (due to no before paint photographs support)

Kindly confirm.

View Received Message

This mail is associated with :

***SGZ706C (9989927468SG)**

OD

Dec 8 2017 12:00AM

[SHAUN LEE LING CHOON]

Motor Image Enterprises Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 14/12/2017 12:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5933.52) - SGZ706C - Claim Handler: Mohd Zawaye, Norsazani

Approved:5933.52:Re-inspect and upload damage photos of Wheel Apr Ft C RPRM, Labour to readjust to 3 days and re-seek mandate. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 14 December, 2017 2:05 PM
To: 'sayedinah@motorimage.net'
Cc: SUR: 'Linda Teo'
Subject: SGZ 706C OD AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGZ 706C (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Dec 2017

Preliminary Advice

Vehicle No	: SGZ706C	Accident Date	: 08/12/2017
Make	: SUBARU FORESTER	Policy No.	:
Assignment Date	: 11/12/2017	Excess	: S\$0.00
Date of Inspection	: 11/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,483.86
Revised Amount	:S\$	5,933.52
Check Items (Estimated)	:S\$	2,541.12
Total	:S\$	8,474.64

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	62,699.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,301.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9726H
Vehicle Details	
Vehicle No.	SGZ706C
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	SUBARU
Vehicle Model	FORESTER 2.0XT CVT AWD SR
Primary Colour	Grey
Manufacturing Year	2016
Engine No.	FA20B902494
Chassis No.	JF1SJGK85GG083529
Maximum Power Output	177.0 kW (237 bhp)
Open Market Value	\$19,305.00
Original Registration Date	31 Jan 2017
First Registration Date	31 Jan 2017
Transfer Count	0
Actual ARF Paid	\$19,305.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Jan 2027
PARF Rebate Amount	\$14,478.00
Intended COE Rebate Details	
COE Expiry Date	30 Jan 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,807.00
COE Rebate Amount	\$48,221.00
Total Rebate Amount	\$62,699.00

The information contained herein is correct as at 12 Dec 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2017 08:13
Date Of Accident	08/12/2017 13:35
Exact Location Of Accident	MARYMOUNT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ706C
Insured/Policyholder	
Name Of Registered Owner	SHAUN LEE LING CHOON
NRIC No	S8269726H
Email Address	EDALYN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98578909
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER-2.0 XT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LUM SHENYAN EDA
NRIC No	S8436680C
Date Of Birth	16/11/1984
Occupation	INDOOR
Date Of Driving Pass	30/06/2003
Driving Experience	14 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96680814
Fax Number	
Contact Number	
Email Address	EDALYN@GMAIL.COM

Details Of Properties

REAR PORTION

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Individual Statement

Describe Circumstances of the Accident

Right Arrow was Red


I was trying to change lane, to left, did not stop in time

I hit SFM 92130 back left and it moved forward to hit
(car B) car A

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

SUBARU AUTO PROTECTOR

OWN DAMAGE EXCESS S\$1400.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 2100499590-00000

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SGZ706C

2) NAME OF INSURED

Shaun Lee Ling Choon

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

31 Jan 2017

4) DATE OF EXPIRY OF INSURANCE

30 Jan 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial, speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / SUBARU AUTHORISED REPAIRERS

1. Motor Image Enterprises Pte Ltd - 19 Lor 8 Toa Payoh (Tel: 6417 0100)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Crest Tel: 66547777 5. Glass-Fix - S2 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss of Use 10 Days (1500 - 1600cc) - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN United Overseas Bank Limited

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 8 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

500619-010

TAN CHONG CREDIT - SUBARU PA

911 BUKIT TIMAH ROAD SINGAPORE 589622 ANSP-
MOTOR

AUTHORISED REPRESENTATIVE

ORIGINAL

55CK/SA

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8269726H



Name
SHAUN LEE LING CHOON

Religion
CHINESE

Date of birth
21-09-1982

Sex
M

Country/Place of birth
MALAYSIA

S8269726H

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8269726H
Name:
SHAUN LEE LING CHOON

Birth Date: 21 Sep 1982
Issue Date: 28 Mar 2016

002551410E

9394435



NRIC No. S8269726H



Nationality
MALAYSIAN

Date of issue
26-02-2016

Address
97A UPPER THOMSON ROAD
#21-03
SINGAPORE 574327

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	24 Mar 2012

NP 428A

Licence No: S8269726H

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8436680C**

Holder:

LUM SHENYAN, EDA
(LIN SHENYAN, EDA)

Birth Date: 16 Nov 1984

Valid Until: 30 Dec 2016

002643338J



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	EFFECTIVE DATE
Class 3		30 Jun 2003

NP 428A

Licence No: S8436680C

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0521/2017
DATE : 09-DEC-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
7B SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : SHAUN LEE LING CHOON
ADDRESS : 97A UPPER THOMSON ROAD
#21-03
S(574327)
TELEPHONE NO : 98578909

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100499590
VEHICLE NO : SGZ706C
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20B902494
CHASSIS NO : JF1SJGK85GG083529
MILEAGE : 1 KM
DATE IN : 09/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 1400.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 08/12/2017

Print Date : 09/12/2017
Print Time : 17:32:24

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE Y19255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGZ706C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 XX/001	REPLACE/REPAIR FRT BUMPER,PANEL,HOOD, FRT RH FENDER, FRT RH DOOR & FRT WHEEL APRON	1200.00	800
2 XX/002	RESPRAY FRT BUMPER,PANEL,HOOD,FRT RH FENDER, FRT RH DOOR & WHEEL APRON	1440.00	1200
3 XX/003	CHECK LIGHTING AFTER REPAIR	20.00	✓
4 XX/004	REMOVE/REFIX AIRCON CONDENSER,RADIATOR TO FACILITATE REPAIR	171.00	✓
5 XX/005	REMOVE/REFIX ENGINE TO FACILITATE REPAIR	NK 342.00	X
6 XX/006	SUNDRIES	100.00	50
	TOTAL LABOUR CHARGES	3281.00	

MOTOIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGM NO SG2706C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	DUCT AIR INTAKE	46012YC000			50.40		X
2	CASE-AIR CLNR UPR	46052SG010			32.40		X
3	CASE-AIR CLNR LWR	46052SG020			32.40		X
4	WHEEL APR FF C RPRH	51610SG1209P			172.80		—
5	RAD PNL COMPL RPR	53029SG0009P			360.00		—
6	FRT FENDER RH	57120SG0209P			270.00		—
7	HOOD F CPL	57229SG0009P			882.00		—
8	HINGE COMPL F RD RH	57260SG0009P			43.20		—
9	HINGE COMPL F RD LH	57260SG0109P			43.20		X
10	LOCK ASSY F HOOD RHD	57310SG000			54.00		X
11	BRKT CORNER F RH	57707SG000			36.00		—
12	BRKT CORNER F LH	57707SG010			36.00		—
13	BRKT SD F RH	57707SG020			12.60		X
14	BRKT SD F LH	57707SG030			12.60		X
15	BUMPER FACE F (FOR HL/W)	57709SG011			594.00		—
16	BACK BEAK CPL F	57711SG0009P			288.00		—
17	ENERGY ABSOR F	57722SG0020			126.00		X
18	COVER HOOK F RP	57731SG070			5.40		—
19	COVER FOG F SP RH	57731SG080			43.20		—
20	COVER SD F SP RH	57731SG120			12.60		—
21	MUD GUARD ASSY F RH	59110SG021			86.40		—
22	PNL COMPL DR F RH	60009SG0429P			720.00		X
23	WSTR OUT DR F RH	61280SG020			100.80		X
24	WSTR DR F LH	USE SG000 63511SG001			144.00		X
25	GLASSRUN F DR RH	63527SG100			72.00		X

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SG1706C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26	WSTR BODY SD FLG F	63571SG001			Sm 122.40	X
27	LAMP ASSY HEAD EOF	84002SG220			SM 2380.00	X
28	LAMP ASSY HEAD EOF	84002SG230			SM CM 2380.00	✓
29	FOG LAMP ASSY F	84501A3060			Sm 272.00	X
30	NOZZLE COVER ASSYRH	86636SG340EN			SM 54.00	✓
31	NOZZLE H L WASHERRH	86636SG361			Sm 79.20	X
32	TAPE DR SASH F F RH	90422SG000			SM 5.40	X
33	TAPE DR SASH F M RH	90422SG020			SM 18.00	✓
34	TAPE DR SASH F R RH	90422SG040			SM 18.00	X
35	INSULATOR HOOD TBRH	90815SG061			Sm 36.00	X
36	INSULATOR HOOD TBLH	90815SG071			Sm 36.00	X
37	GRILLE ASSY F UPRHG	PDI STOCK 91121SG210A			Sm 140.40	X
38	GRILLE ASSY F CTRHG	PDI STOCK 91121SG240A			Sm 180.00	X
39	GRILLE ASSY F LWRHG	PDI STOCK 91121SG280A			Sm 316.00	X
40	BKT GRILLE LWR	91165SG010			Sm 21.60	X
SUB TOTAL			0.00	0.00	0.00	10289.80
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	3086.94
GRAND TOTAL			0.00	0.00	0.00	7202.86
OVERALL TOTAL			7202.86			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG B, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SG2706C

TOTAL LABOUR CHARGES	3281.00
TOTAL SPARE PARTS CHARGES	7202.86
GRAND TOTAL	10483.86 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	1400.00
LIABILITY	:	0.00
REMARKS	:	

Not Authored
1-31
Resurvey B4 part
6 days

PLEASE NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0521/2017
DATE : 09-DEC-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : SHAUN LEE LING CHOON
ADDRESS : 97A UPPER THOMSON ROAD
#21-03
S(574327)
TELEPHONE NO : 98578909

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100499590
VEHICLE NO : SGZ706C
MODEL CODE : SJCXKX8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20B902494
CHASSIS NO : JF1SJCX85GG083529
MILEAGE : 11235 KM
DATE IN : 09/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 700.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 08/12/2017

Print Date : 23/05/2018
Print Time : 16:05:56

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCZ706C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	REPLACE/REPAIR FRT BUMPER,PANEL,HOOD, FRT RH FENDER, FRT RH DOOR & FRT WHEEL APRON	1200.00	800.00
3	ZZ/002	RESFRAY FRT BUMPER,PANEL,HOOD,FRT RH FENDER, FRT RH DOOR & WHEEL APRON	1440.00	1200.00
4	ZZ/003	CHECK LIGHTING AFTER REPAIR	28.00	28.00
5	ZZ/004	REMOVE/REFIXAIRCON CONDENSER,RADIATOR TO FACILITATE REPAIR	171.00	171.00
6	ZZ/005	REMOVE/REFIX ENGINE TO FACILITATE REPAIR	342.00	.00
7	ZZ/006	SUNDRIES	100.00	50.00
8	ZZ/007	CONDUCT OD CLAIM AIG DATE:08/12/2017TIME:1135 MARYMOUNT ROAD		
TOTAL LABOUR CHARGES			3281.00	2249.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SG2706C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	DUCT AIR INTAKE	46012YC000				50.40	X
2	CASE-AIR CLNR UPR	46052SG010				32.40	X
3	CASE-AIR CLNR LWR	46052SG020				32.40	X
4	WHEEL APR FF C R2RH	51610SG1209P				172.80	OK
5	RAD PNL COMPL RFR	53029SG0009P				360.00	OK
6	FRT FENDER RH	57120SG0209P				270.00	OK
7	HOOD F CPL	57229SG0009P				882.00	OK
8	HINGE COMPL F HD RH	57260SG0009P				43.20	OK
9	HINGE COMPL F HD LH	57260SG0109P				43.20	X
10	LOCK ASSY F HOOD RH	57310SG000				54.00	X
11	BRKT CORNER F RH	57707SG000				36.00	OK
12	BRKT CORNER F LH	57707SG010				36.00	OK
13	BRKT SD F RH	57707SG020				12.60	X
14	BRKT SD F LH	57707SG030				12.60	X
15	BUMPER FACE F (FOR HL/W)	57709SG011				594.00	OK
16	BACK BEAM CPL F	57711SG0009P				288.00	OK
17	ENERGY ABSOR F	57722SG020				126.00	X
18	COVER HOOK F SP	57731SG070				5.40	OK
19	COVER POG F SP RH	57731SG080				43.20	OK
20	COVER SD F SP RH	57731SG120				12.60	OK
21	MUD GUARD ASSY F RH	59110SG021				86.40	OK
22	PNL COMPL DR F RH	60009SG0429P				720.00	X
23	WSTR OUT DR F RH	61280SG020				100.80	X
24	WSTR DR F LH	USE SG000 63511SG001				144.00	X
25	GLASSRUN F DR RH	63527SG100				72.00	X

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGZ706C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
26	WSTR BODY SD FLG F	63571SG001				122.40	X
27	LAMP ASSY HEAD EOF	84002SG220				2380.00	X
28	LAMP ASSY HEAD EOF	84002SG230				2380.00	OK
29	FOG LAMP ASSY F	84501AJ060				272.00	X
30	NOZZLE COVER ASSYRH	86636SG340EN				54.00	OK
31	NOZZLE H L WASHERRH	86636SG361				79.20	X
32	TAPE DR SASH F F RH	90422SG000				5.40	X
33	TAPE DR SASH F M RH	90422SG020				18.00	X
34	TAPE DR SASH F R RH	90422SG040				18.00	X
35	INSULATOR HOOD TBRH	90815SG061				36.00	X
36	INSULATOR HOOD TBLH	90815SG071				36.00	X
37	GRILLE ASSY F UPRHG	PDI STOCK 91121SG210A				140.40	X
38	GRILLE ASSY F CTRHG	PDI STOCK 91121SG240A				180.00	X
39	GRILLE ASSY F LWRHG	PDI STOCK 91121SG280A				316.80	X
40	BKT GRILLE LWR	91165SG010				21.60	X
SUB TOTAL			0.00	0.00	0.00	5263.60	
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1579.08	
GRAND TOTAL			0.00	0.00	0.00	3684.52	
OVERALL TOTAL			3684.52				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGZ706C

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	5263.60
LESS 30 %	-1579.08
S/LIST AMOUNT	3684.52
TOTAL LABOUR CHARGES	2249.00
TOTAL SPARE PARTS CHARGES	3684.52
TOTAL CHARGES	5933.52
LESS EXCESS	700.00
TOTAL	5233.52
ADD 7 % GST	366.35
GRAND TOTAL	5599.87



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
25 Leng Kee Road Singapore 159097
Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L480877

For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.

DATE REC'D: 11-Dec-2017

SERVICE ADVISOR: SAYED

JOB No.: L472657

MILEAGE: 11235

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0XT AWD CVT
ENGINE No.: FA20B902494
CHASSIS No.: JF15JGK85GG083529
REGISTRATION No.: SGZ706C

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	REMARK REPLACE/REPAIR FRT BUMPER,PANEL,HOOD, FRT RH FENDER, FRT RH DOOR & FRT WHEEL APRON	
2	REMARK RESPRAY FRT BUMPER,PANEL,HOOD,FRT RH FENDER, FRT RH DOOR & WHEEL APRON	
3	REMARK CHECK LIGHTING AFTER REPAIR	
4	REMARK REMEOVE/REFIXAIRCON CONDENSER,RADIATOR TO FACILITATE REPAIR	
5	REMARK REMOVE/REFIX ENGINE TO FACILITATE REPAIR	
6	REMARK SUNDRIES	
7	ODCLAI CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
8	INS01 FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
9	INS02 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
10	INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
11	INS04 SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
12	INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
13	INS06 THE OWNER IS REQUIRED.	
14	INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
15	INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
16	INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
17	REMARK CONDUCT LUMP SUM REPAIR	4,700.00
TOTAL(LABOUR)		4,700.00

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L480877

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 11-Dec-2017

SERVICE ADVISOR: SAYED

JOB No.: L472657

MILEAGE: 11235

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0XT AWD CVT
ENGINE No.: FA20B902494
CHASSIS No.: JF1SJGK85GG083529
REGISTRATION No.: SGZ706C

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
	less INSURANCE EXCESS	700.00

Subtotal	4,000.00
GST(7%)	280.00
TOTAL	\$4,280.00

DATE : 03-Aug-2018

CUSTOMER

Indis

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net
Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: SHAUN LEE LING CHOON
Address of Insured: 97A UPPER THOMSON ROAD #21-03 S(574327)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225
Place of Accident: MARYMOUNT ROAD
Date of Accident: 08/12/2017 Vehicle No: SGZ706C
Policy No: 2100499590 Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INS P/L settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

INSURED:

S8269726H

IC No. & Signature/Company's Chop

SAYEDINAH ALI

Name

SHAUN LEE LING CHOON

Name

22/12/2017

Date

22/12/2017

Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017 12:06		11 Dec 2017 14:25 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SHAUN LEE LING CHOON , ID: S8269726H, Tel: +6598578909									
Vehicle Reg. No.: SGZ706C		Date of Loss: 08/12/2017 00:00 - :59 [10 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9989927468SG		Policy/Cover Note No.: 2100499590 (Comprehensive)							
		Excess: S\$700.00							
Repairer: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2017]									
Driver/Custodian: LUM SHENYAN EDA (33 / Female), NRIC: S8436680C, Tel: +6596680814									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (14/12/2017): Alert - Adj Mandate Approved (S\$5933.52) - SGZ706C - Claim Handler: Mohd Zawaye,... - AIG_SG (12/12/2017): SGZ706C / OD / 08/12/2017 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ706C (9989927468SG)
OD
Dec 8 2017 12:00AM
[SHAUN LEE LING CHOON]
Motor Image Enterprises Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page ☐	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	09/12/17 08:42	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports			1 per page ☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 12:09	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 12:10	General View	Load JPG	☒
2	12/12/17 12:10	General View	Load JPG	☒
3	12/12/17 12:10	General View	Load JPG	☒
4	12/12/17 12:10	General View	Load JPG	☒
5	12/12/17 12:10	General View	Load JPG	☒
6	12/12/17 12:10	General View	Load JPG	☒
7	12/12/17 12:10	General View	Load JPG	☒
8	12/12/17 12:10	General View	Load JPG	☒
9	12/12/17 12:10	General View	Load JPG	☒
10	12/12/17 12:10	General View	Load JPG	☒
11	12/12/17 12:10	General View	Load JPG	☒
12	12/12/17 12:10	General View	Load JPG	☒
13	12/12/17 12:10	General View	Load JPG	☒
14	12/12/17 12:10	General View	Load JPG	☒
15	12/12/17 12:10	General View	Load JPG	☒
16	12/12/17 12:10	General View	Load JPG	☒
17	12/12/17 12:10	General View	Load JPG	☒
18	12/12/17 12:10	Odometer Reading	Load JPG	☒
19	12/12/17 12:10	Chassis Number	Load JPG	☒
20	12/12/17 12:10	General View	Load JPG	☒
Documentation			1 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 12:15	Singapore Accident Statement	Load PDF	☐
2	12/12/17 12:15	Certificate of Insurance	Load PDF	☐
3	12/12/17 12:15	Insured Person's NRIC	Load PDF	☐
4	12/12/17 12:15	Driver's Driving License	Load PDF	☐
5	12/12/17 12:15	WORKSHOP ESTIMATE	Load PDF	☐
6	29/08/18 14:56	WORKSHOP INVOICE	Load PDF	☐
7	29/08/18 14:56	DISCHARGE VOUCHER	Load PDF	☐

Linked Accident Report Documents

				View	View in Browser
Video				1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print	
1	09/12/17 08:42	Video - Accident	 Load MP4		
Assessment Reports				1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print	
1	09/12/17 08:43	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print	
1	09/12/17 08:37	Accident Photo	 Load JPG	☒	
2	09/12/17 08:37	Accident Photo	 Load JPG	☒	
3	09/12/17 08:37	Accident Photo	 Load JPG	☒	
4	09/12/17 08:37	Accident Photo	 Load JPG	☒	
5	09/12/17 08:37	Accident Photo	 Load JPG	☒	
6	09/12/17 08:37	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print	
1	09/12/17 08:37	Accident Sketch Plan	 Load JPG	☒	
2	09/12/17 08:37	Individual Statement	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG17023438/KQBQ2

Date: 29/08/2018

REFERENCE

Insured/Claimant: SHAUN LEE LING CHOON Policy No: 2100499590
Date of Loss: 08/12/2017 Nature of Claim: OD Claim No: 9989927468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ706C**
Make & Model: SUBARU FORESTER, 2.0 XT AWD CVT (A) Engine No: FA20B902494
Reg. Date: 31/01/2017 (Man. Year: 2016) Chassis No: JF1SJGK85GG083529
Colour: Metallic Grey Odometer: 11235 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,302.86	3,734.52	3,568.34	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,181.00	2,199.00	982.00	30.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,483.86	5,933.52	4,550.34	43.40
Approved Total (Overridden) (S\$)		4,700.00		
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	9,783.86	4,000.00	5,783.86	59.12
+ GST 7.00/7.00% (S\$)	684.87	280.00	404.87	59.12
Nett Amount (S\$)	10,468.73	4,280.00	6,188.73	59.12

INSPECTION

Date of Assignment: 11/12/2017
Date Inspected: 11/12/2017 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DUCT AIR INTAKE	Serviceable	50.40 FL	*- FL
2	1		*CASE -AIR CLNR UPR	Serviceable	32.40 FL	*- FL
3	1		*CASE -AIR CLNR LWR	Serviceable	32.40 FL	*- FL
4	1		*WHEEL APR FF C RPRH	Cracked	172.80 FL	*172.80 FL
5	1		*RAD PNL COMPL RPR	Bent	360.00 FL	*360.00 FL
6	1		*FRT FENDER RH	Buckled	270.00 FL	*270.00 FL
7	1		*HOOD F CPL	Bent	882.00 FL	*882.00 FL
8	1		*HINGE COMPL F HD RH	Distorted	43.20 FL	*43.20 FL
9	1		*HINGE COMPL F HD LH	Repair	43.20 FL	*- FL
10	1		*LOCK ASSY F HOOD RHD	Repair	54.00 FL	*- FL
11	1		*BRKT CORNER F RH	Cracked	36.00 FL	*36.00 FL
12	1		*BRKT CORNER F LH	Distorted	36.00 FL	*36.00 FL
13	1		*BRKT SD F RH	Repair	12.60 FL	*- FL
14	1		*BRKT SD F LH	Repair	12.60 FL	*- FL
15	1		*BUMPER FACE F (FOR HL /W)	Cracked	594.00 FL	*594.00 FL
16	1		*BACK BEAM CPL F	Bent	288.00 FL	*288.00 FL
17	1		*ENERGY ABSOR F	Serviceable	126.00 FL	*- FL
18	1		*COVER HOOK F SP	Dented	5.40 FL	*5.40 FL
19	1		*COVER FOG F SP RH	Missing	43.20 FL	*43.20 FL
20	1		*COVER SD F SP RH	Missing	12.60 FL	*12.60 FL
21	1		*MUD GUARD ASSY F RH	Cracked	86.40 FL	*86.40 FL
22	1		*PNL COMPL DR F RH	Repair	720.00 FL	*- FL
23	1		*WSTR OUT DR F RH	Serviceable	100.80 FL	*- FL
24	1		*WSTR DR F LH	Serviceable	144.00 FL	*- FL
25	1		*GLASSRUN F DR RH	Serviceable	72.00 FL	*- FL
26	1		*WSTR BODY SD FLG F	Serviceable	122.40 FL	*- FL
27	1		*LAMP ASSY HEAD EOF LH	Serviceable	2,380.00 FL	*- FL
28	1		*LAMP ASSY HEAD EOF RH	Cracked	2,380.00 FL	*2,380.00 FL
29	1		*FOG LAMP ASSY F	Serviceable	272.00 FL	*- FL
30	1		*NOZZLE COVER ASSYRH	Missing	54.00 FL	*54.00 FL
31	1		*NOZZLE H L WASHERRH	Serviceable	79.20 FL	*- FL
32	1		*TAPE DR SASH F F RH	Not Necessary	5.40 FL	*- FL
33	1		*TAPE DR SASH F M RH	Not Necessary	18.00 FL	*- FL
34	1		*TAPE DR SASH F R RH	Not Necessary	18.00 FL	*- FL
35	1		*INSULATOR HOOD TBRH	Serviceable	36.00 FL	*- FL
36	1		*INSULATOR HOOD TBLH	Serviceable	36.00 FL	*- FL
37	1		*GRILLE ASSY F UPRHG	Serviceable	140.40 FL	*- FL
38	1		*GRILLE ASSY F CTRHG	Serviceable	180.00 FL	*- FL
39	1		*GRILLE ASSY F LWRHG	Serviceable	316.80 FL	*- FL
40	1		*BKT GRILLE LWR	Serviceable	21.60 FL	*- FL
41	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,389.80	5,313.60
- List Item Discount on L Items 30.00/30.00% (\$\$)	3,086.94	1,579.08
Total Parts (\$\$)	7,302.86	3,734.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (S\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE /REPAIR FRT BUMPER ,PANEL ,HOOD ,FRT RH FENDER ,FRT RH DOOR & FRT WHEEL APRON	New	1,200.00	800.00
2	RESPRAY FRT BUMPER ,PANEL,HOOD ,FRT RH FENDER ,FRT RH DOOR & WHEEL APRON	New	1,440.00	1,200.00
3	CHECK LIGHTING AFTER REPAIR	New	28.00	28.00
4	REMOVE /REFIXAIRCON CONDENSER ,RADIATOR TO FACILITATE REPAIR	New	171.00	171.00
5	REMOVE/REFIX ENGINE TO FACILITATE REPAIR	New	342.00	0.00
Gross Labour Cost (S\$)			3,181.00	2,199.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >