COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 3110E

MAKE

LKK/CeWin

DATE 8/12/2017 12:08

ODEL	: HYUNDAI i40				
MODEL Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper × / y v			\$	603.60
	Rear Bumper Clips ×			\$	22.00
	Rear Wheel Hub Cap (LH) 🗶			\$	150.70
	SUB TOTAL			\$	776.30
	LESS 20%			\$	155.26
	DISCOUNTED TOTAL			\$	621.04
				1	
	Labour Charge				100
	Panel Beating			\$	350.00
	Spray Painting Charge			\$	200.00
	Wiring Charge			\$	50.00
	R/Refix Reverse Sensor			\$	120.00
	TOTAL LABOUR			\$	720.00
	ESTIMATE TOTAL			\$	1,341.0
	ESTRUME				
	1. 1. 11.04				
	Calvin L.				
	6/ 8/12/17 1410hrs				
	Kalun 16RK M 8/12/17 1410hrs 2/ays			1	
		LVV			
	After Regar pl	LKK the F	20	tify	
	Alla Report Phil	• To resur.			
	AFF	To displa Parts price	vi i i	irvey	- 1
		• I hird part	y Survey is on a "Mithaut "	ud -" L	
		No illegal		udice ba	ISIS
		is subject	to fir all approval from insuran	and	
		1	1	T Tip	any
		Signature:	ed by Repairer		-
		Date:			

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.