

INS CASE OWNER:

Jaclyn

CC6 / AIG170 23448 1

Aya391

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

08/12/17

Date / Time:

08/12/17

Registered in Merimen:

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFD 60682

Name of Insured:

CHONG KHIN WEI, NICHOLAS

Insured Tel No.:

HP:

Claim No.:

8013870067 SG

Policy No.:

2100494286

Make / Model:

NISSAN NOTE - 1.2 (A)

Excess Sec II : \$5

D.O.A.:

04/12/17

Place of Accident:

TOA PAYOH LORONG 6

Is driver the owner?

(YES ☒ NO ☐)

Nature of Accident:

If NO, Driver Name / Age: CHAN SUNY MOSEY DOREEN

OI GIA REPORT ☒ YES / NO ; TP GIA REPORT ☒ YES / NO

Driver Tel No.:

9667 7063

(VI ☒ YES / NO)

Insured Liability:

%

Final ? Yes / No

SGO 2740E



INSRS:

WSP: Sn Hwee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SGO 2740E - X

SFD 60682 - C/LAIG 11015397/R, 332 DA 02/10/17

- C/LAIG 11015397/R, 332 DA 02/10/17

- NA/M/G 110131647/1 DA 25/01/17

- NA/M/G 110131647/1 DA 25/01/17

13/12/17 (Jas)

NO ESTIMATE

13/12/17 @ 2:45

Called OI, No response.

AIG Jaclyn share vide in Merimen. OI
turning right before green arrow appear
& collided with TP coming from opp
direction. Risk Agency OI

RECEIVED 27 FEB 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 6800 (10 days) Reduction: 60 %

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Mr.

Email ☐Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 5

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 6,800.00

Loss of Rental (LOR):

\$5 (days)

Loss of Use (LOU):

\$5 720.00 (\$60 x 12 days)

Loss of Income (LOI):

\$5 (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5 5.35

Medical:

\$5

Disbursement:

\$5

Legal Cost

\$5

Total:

\$5 7,525.35

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

\$5 7,525.35

Name 1:

Sn Hwee Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGD2740 E. Yr Regn: 2006 FebType: M. Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ATF Toyota Altis- cc: 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: - T. Radio: Insured / Std / NI / NA

Eng No: _____

C/No: MR0537EC107113258Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14.R: 185/70R14.BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A: _____ D.O.I: 08/12/17.Survey held at: Sin Huse.

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s, u/c.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

TPA19.

MV: 25K

PV: 17K

Nett: 8K.

Date/Time: File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

____ \$ - RS ____ \$

Food

Other

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023448/Aya3	
78 SHENTON WAY #03-16 CHARTIS BUILDING SINGAPORE 079120		Date : 11-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFD 6068Z	Veh. Inspected	SGD 2740E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/12/2017	Inspection Date	08/12/2017
Survey held at	SIN HWEE MOTOR PTE LTD BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

SNG MUI NGUAN

264 BISHAN ST 24

#13-116

S570264

TPA

Ins

LKK Ag

the Repairer

• To resurvey before start

• To display damaged part(s) during resurvey

• Part prices are subject to confirmation

• The estimate is on a "Without Prejudice" basis

• No repairs/modifications is allowed

• Subsequent repairs must be resurveyed and

is subject to final approval from Insurance Company

• This estimate is valid for 30 days

• This estimate is valid for 30 days

• This estimate is valid for 30 days

DATE	7/12/2017
VEHICLE NO:	SGD 2740 E
MAKE:	TOYOTA
MODEL:	ALTIS

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	FRONT BUMPER <i>Distorted</i>	486.00	486.00 ✓
10 PCS	BUMPER CLIP <i>new</i>	4.50	45.00 ✓ <i>30</i>
1 PC	FRONT BUMPER REINFORCEMENT <i>Best</i>	329.31	329.31 ✓ <i>2</i>
2 PCS	BUMPER SIDE RETAINER <i>new</i>	39.11	78.22 ✓ <i>29.11</i>
1 PC	FRONT FENDER R/H <i>Distorted</i>	256.33	256.33 ✓
1 PC	FRONT FENDER INNER COVER R/H <i>new</i>	87.39	87.39 ✓
1 PC	FOG LAMP COVER R/H <i>missing</i>	58.22	58.22 ✓
1 PC	HEADLAMP L/H <i>new</i>	384.62	384.62 ✓
1 PC	HEADLAMP R/H <i>smashed</i>	384.62	384.62 ✓
1 PC	CENTER GRILLE <i>new</i>	265.50	265.50 ✓
1 PC	WASHER TANK <i>Distorted</i>	186.80	186.80 ✓
1 PC	WASHER TANK MOTOR <i>new</i>	76.78	76.78 ✓
1 PC	ABS PUMP <i>new</i>	2,859.25	2,859.25 ✓
1 PC	RADIATOR ASSY <i>new</i>	895.50	895.50 ✓
1 PC	SUPPORT PANEL <i>new</i>	887.66	887.66 ✓
1 PC	WHEEL HOUSE PANEL <i>new</i>	798.54	798.54 ✓
1 PC	FRONT DOOR R/H <i>Distorted</i>	558.14	558.14 ✓
1 PC	FRONT DOOR PROTECTOR R/H <i>cut</i>	56.27	56.27 ✓
1 PC	PROTECTOR CHROME <i>cut</i>	35.74	35.74 ✓
1 PC	FRONT DOOR HINGE - TOP <i>Best</i>	48.57	48.57 ✓
1 PC	FRONT DOOR HINGE - BOTTOM <i>Best</i>	48.57	48.57 ✓
1 PC	BATTERY HOLDER <i>new</i>	49.28	49.28 ✓
1 PC	FRONT ABSORBER R/H <i>Best</i>	367.25	367.25 ✓
1 PC	ABSORBER TOP MOUNT <i>new</i>	87.54	87.54 ✓
1 PC	LOWER ARM R/H <i>Best</i>	240.69	240.69 ✓
1 PC	LOWER ARM BALL JOINT <i>Best</i>	84.24	84.24 ✓
1 PC	KUNCKLE ARM R/H <i>Best</i>	380.14	380.14 ✓
1 PC	KUNCKLE ARM BEARING <i>new</i>	95.87	95.87 ✓
1 PC	ABS SENSOR <i>new</i>	248.10	248.10 ✓
1 PC	TIE ROD R/H <i>Best</i>	87.20	87.20 ✓
1 PC	STEERING RACK ASSEMBLY <i>Damaged</i>	1,290.58	1,290.58 ✓
1 PC	ANTI ROLL BAR <i>new</i>	257.41	257.41 ✓
1 PC	ANTI ROLL BAR LINK <i>Best</i>	67.14	67.14 ✓
1 PC	FRONT CROSSMEMBER <i>Best</i>	780.45	780.45 ✓
1 PC	DRIVE SHAFT <i>Damaged</i>	764.00	764.00 ✓

7727-07
5795-30

LESS 25% SUBTOTAL 13,626.92
LESS 25% -25.00% -3,406.73

1 PC SPORT RIM - NETT *cut* 580 480.00 ~~480.00~~ 400
1 PC TYRE - NETT *Replaced* 180.00 ~~180.00~~ 180

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

SNG MUI NGUAN

264 BISHAN ST 24

#13-116

SS70264

DATE	7/12/2017
VEHICLE NO	SGD 2740 E
MAKE:	TOYOTA
MODEL:	ALTIS

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO DISMOUNT RADIATOR / CONDENSER ASSY TO FACILITATE REPAIR WORK.	280.00	280.00 100
-	TO SUPPLY AND TOP UP AIR CON GAS		
1 TIN	ENGINE COOLANT	65.00	65.00 20.
-	TO DISMOUNT AND MOUNT DASHBOARD TO FACILITATE WHEEL HOUSE PANEL REPLACEMENT	480.00	480.00 *
-	TO CARRY ABS SYSTEM SCAN AND RESET FAULT CODE		
-	TO SUPPLY BRAKE FLUID AND CARRY OUT ABS SYSTEM FLUSHING / BLEEDING	350.00	350.00 *
-	TO DISMOUNT AND REPLACE FRONT UNDER CARRIAGE INCLUDE CROSSMEMBER, STEERING RACK, ARMS, ABSORBER AND LINKS.		
-	TO PRESS AND JACK KUNCKLE ARM BEARING	580.00	580.00 380
-	TO SET UP CAR O LINER TOOLS AND BENCH.		
-	TO MOUNT VEHICLE ON BENCH AND MEASURE FRONT CHASSIS FRAME	350.00	350.00 +
-	TO REPLACE FRONT SUPPORT PANEL AND WHEEL HOUSE PANEL INCLUDE KNOCKING, CUTTING AND WELDING		
-	TO INSTALL AND ALIGN REPLACED/AFFECTED PARTS TO SYMMETRICAL SPEC.	2,200.00	2,200.00 800
-	TO SPRAY PAINT DOOR, DOOR PILLAR, SUPPORT PANEL, BUMPER, FENDER, WHEEL HOUSE PANEL AND CHASSIS FRAME	2210 980.00	980.00 600
-	TO TRANSFER DOOR MECHANISM, FITTINGS AND TRIM TO NEW DOOR.	150.00	150.00 80
-	TO CARRY OUT COMPUTERIZED 4 WHEELS ALIGNMENT	150.00	150.00 80
-	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA	250.00	250.00 60
-	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	180.00	180.00 30
-	TOWIN SERVICE	150.00	150.00 60

ATTN: A DZIAN

total 8585.30
4/5 68K
10 Days.

Tel: 6745 5783 Fax: 6744 9582

Email: sinhwecmotor@gmail.com

Website: www.sinhwecmotor.com

TOTAL \$17,045.19

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	2462F

Vehicle Details

Vehicle No.	SGD2740E
Vehicle to be Exported	Yes
Intended De-registration Date	08 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA 1.6
Primary Colour	Silver
Manufacturing Year	2006
Engine No.	3ZZ4545625
Chassis No.	MR053ZEC107113258
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$16,950.00
Original Registration Date	15 Feb 2006
First Registration Date	15 Feb 2006
Transfer Count	1
Actual ARF Paid	\$18,645.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	14 Feb 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$26,900.00
COE Rebate Amount	\$17,132.00
Total Rebate Amount	\$17,132.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Dec 2017

OK


MYCARFORUM
 MARKETPLACE

Buy / Sell Parts & Accessories

[click here to visit now!](#)

 Username / Email Add
 password
 Connect
[Sign up New Account](#)
[Forgot Password](#)

toyota altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type


[Advanced Search](#)

Used Car Comparison

— Comparing 3 Vehicles —

Toyota Corolla Altis 1.6A (COE till 03/2021)

Toyota Corolla Altis 1.6A (COE till 02/2021)

Toyota Corolla Altis 1.6A (COE till 12/2020)



Use the search bar above to go to compare.

[Clear All](#)
[Add all to Shortlist](#)
[Back to search result](#)

CAR DETAILS

Price	\$25,000	\$25,800	\$23,588	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	08-Mar-2006	15-Feb-2006	22-Dec-2005	-
Manufactured	2006	2006	2005	-
Mileage	200,900 km	147,000 km	-	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$816 /yr	\$816 /yr	\$890 /yr	-
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	-
Curb Weight	1,115 kg	0 kg	0 kg	-
Features	-	1.6L 16-Valves VVTi DOHC 108Bhp Engine, Smooth Auto With ETC, Climatic Control Aircon, 2 x Airbags, ABS, Knockdown Rear Seats	1.6L 16 Valves VVTi DOHC 108Bhp Engine, Smooth Auto With ETC, Climatic Control Aircon, 2 x Airbags, ABS, Fog Lamps.	-
Accessories	-	Leather Seats, Sports Rims, Factory Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors, New Paintwork, Fog Lamp.	Leather Seats, Sports Rims, Factory Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors.	-
Description	Low Price. Has Been Drove For The Past 7 Years. Excellent Engine. Good Maintenance And Well Serviced. Sure Like Condition.	We Are At Saffra Punggol Car-Carnival From 4th To 10th December, "One Year Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Monthly Instalment, 10% Down Payment, Bank In House Loan Available, Lowest Down Payment, Flexible Loan Available At Low Interest Rate, Loan Tenure Up To End Of COE, Free Fully	\$0 Drive Away! 100% Accident Free, Very Well Maintained By Owner. Most Parts Has Been Replaced. In House Finance. In House Workshop. All In 1 Stop. Door Step Viewing Available. Kindly Arrange For Viewing.	-
COE	\$24,771	\$26,900	\$28,416	-
OMV	\$16,950	\$16,950	\$16,772	-
ARF	\$18,645	\$18,645	\$18,450	-
Depreciation	\$7,700 /yr	\$8,090 /yr	\$7,760 /yr	-
No. of Owners	4	2	2	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	COE Car, Direct Owner Sale	COE Car	COE Car	-
Availability	Available	Available	Available	-

Jas Khine (LKKAuto)

From: Jas Khine (LKKAuto)
Sent: Monday, 18 December, 2017 10:42 AM
To: 'NICCHONG72@GMAIL.COM'
Subject: ACCIDENT INVOLVING SFD 6068Z & SGD 2740E ALONG/AT TOA PAYOH LORONG 6 ON 04/12/2017

Our Ref: CC6/AIG17023448/Aya3

18 DECEMBER 2017

CHONG KHIN WEI, NICHOLAS

Dear Sir/Madam,

ACCIDENT INVOLVING SFD 6068Z & SGD 2740E ALONG/AT TOA PAYOH LORONG 6 ON 04/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the circumstances of the accident and available information in hand, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

TO WHOM IT MAY CONCERN

LETTER OF AUTHORITY

Accident on 04/12/17 at/along JUNCTION OF TOA PAYOH LCA 4 & LCA 6

Involving SFD 2740E AND SFD 6068Z

I/We, SNG MUI NGUAN

Nric No. S1302462 F

of 264 BISHAN ST 24 #13-116 S(570264) owner of Motor

Vehicle Registration No. SFD 2740E Insured by GREAT AMERICAN INSURANCE CO.

under Policy No. MUMVP 000002458-00-000 do hereby authorize Min Heng Motor Pte Ltd

as my authorized representative to write, negotiate & settle claim on my behalf in my claim against the owner and/or driver of motor Vehicle Registration No. SFD 6068Z in respect of the above mentioned accident.

I also hereby authorize that the agreed settlement can be made in favour of my representative, Min

Min Heng Motor Pte Ltd and the said payment be forwarded to them as full and final discharge of my claim.

I hereby exonerate the AIG ASIA PACIFIC INSURANCE PTE LTD and / or their insured and/or

driver of vehicle number SFD 6068Z from any liability after payment of any claim to my authorized

representative Min Heng Motor Pte Ltd

Owner's Signature:

Full Name :

Nric No :

Date :

SNG MUI NGUAN
S1302462 F
5/12/17

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SIN HWEE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS\$6,800.00 (Repair Cost), SS\$720.00 (Loss of Rental/Use) SS\$5.35 (Disbursement), for vehicle no. SGD 2740E that was damaged pursuant to the accident which occurred on 04/12/2017 (date) along TOA PAYOH LORONG 6 (location) involving vehicle no/s SFD 6068Z.

This is pursuant to the inspection conducted on 08/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SNG MUI NGUAN ("the third party claimant") of vehicle no. SGD 2740E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGD 2740E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 (day) of 02 (month) 2018 (year)

Signed by appointed surveyor



cup

Signed by "the workshop" (with chop)

[Signature]



SIN HWEE MOTOR PTE LTD

Invoice

GST cancelled with effect from 01 Apr 17

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

SNG MUI NGUAN

264 BISHAN ST 24

#13-116

S570264

INVOICE NO:	C1154
DATE OF ISSUE	11/2/2018

VEHICLE NO:	SGD 2740 E
MAKE:	TOYOTA
MODEL:	ALTIS

REF NO:	
---------	--

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
	LUMP SUM	6,800.00	6,800.00

Tel: 67455783 Fax: 67449582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com



TOTAL: \$6,800.00

Land Transport Authority

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006629-2

Print Date/Time : 05 Dec 2017 / 19:00:57

Receipt Date/Time : 05 Dec 2017 / 19:00:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171205-002007

Previous Receipt No. :

S/N Item Description/

Business Transaction Reference
No.

Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
------------------------------	-----------------------	-----------------------------

Result of Insurance Enquiry - SFD6068Z

As at 04 Dec 2017/15:55:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SFD6068Z

Enquiry Fee

20171205185943938835

5.00 0.35 5.35

Sub-Total

5.00 0.35 5.35

Total Before Rounding

5.00 0.35 5.35

Rounding Difference

0.00

Total Amount Payable

5.35

Paid By

20171205185955888

Direct Debit: eNETS
Debit (Internet Banking)

5.35

Total

5.35

Cash Change

0.00

Tendered Amount

5.35

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2017 Edit Reg		08 Dec 2017 00:00 Edit Adj Rpt	\$56,800.00 Edit Estimates	\$56,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		CHONG KHIN WEI, NICHOLAS , ID: S7222788C							
Main Claimant:		SNG MUI NGUAN , ID: S1302462F							
Vehicle Reg. No.:		SGD2740E	Date of Loss:	04/12/2017 15:00 - :59					
Claim Type:		TP / 8013870067SG	Policy/Cover Note No.:	2100494286 (Comprehensive) Coverage: 19/12/2016 - 18/12/2017					
Vehicle Reg. No. (Insured):		SFD6068Z	Policy No. (Claimant):	MOMVP000002758-00-000					
		Excess:							
Repairer:		Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59, 408717 Ubi - Tel: 67455783							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com							
Claimant's Insurer:		Great American Insurance Company (HQ) - Tel: 6804 6047							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/12/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGD2740E (8013870067SG)
[SFD6068Z]
TP
SNG MUI NGUAN
Dec 4 2017 3:00PM
[CHONG KHIN WEI, NICHOLAS]
Sin Hwee Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Video						1 per page v	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	13/12/17 14:39	Video - Accident			Load MP4		
Letters/Correspondences						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown			Edit		
Assessment Reports						1 per page v	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	12/12/17 14:10	Accident Statement From: OD - Reg. No: SFD6068Z, Claimant: CHONG KHIN WEI, NICHOLAS			Load HTM		
Photos/Images						3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	09/02/18 15:21	General View			Load JPG	☒	
2	09/02/18 15:21	Chassis Number			Load JPG	☒	
3	09/02/18 15:21	General View			Load JPG	☒	
4	09/02/18 15:21	General View			Load JPG	☒	
5	09/02/18 15:21	General View			Load JPG	☒	
6	09/02/18 15:21	General View			Load JPG	☒	
7	09/02/18 15:21	General View			Load JPG	☒	
8	09/02/18 15:21	General View			Load JPG	☒	
9	09/02/18 15:21	General View			Load JPG	☒	
10	09/02/18 15:21	General View			Load JPG	☒	
11	09/02/18 15:21	General View			Load JPG	☒	
12	09/02/18 15:21	General View			Load JPG	☒	
13	09/02/18 15:21	General View			Load JPG	☒	
14	09/02/18 15:21	General View			Load JPG	☒	
15	09/02/18 15:21	General View			Load JPG	☒	
16	09/02/18 15:21	General View			Load JPG	☒	
17	09/02/18 15:21	General View			Load JPG	☒	
18	09/02/18 15:21	General View			Load JPG	☒	
19	09/02/18 15:21	General View			Load JPG	☒	
20	09/02/18 15:21	General View			Load JPG	☒	
21	09/02/18 15:21	General View			Load JPG	☒	
22	09/02/18 15:21	General View			Load JPG	☒	
23	09/02/18 15:21	General View			Load JPG	☒	
24	09/02/18 15:21	General View			Load JPG	☒	
25	09/02/18 15:21	General View			Load JPG		

					☒
26	09/02/18 15:21	General View		Load JPG	☒
27	09/02/18 15:21	General View		Load JPG	☒
28	09/02/18 15:21	General View		Load JPG	☒
29	09/02/18 15:21	General View		Load JPG	☒
30	09/02/18 15:21	General View		Load JPG	☒
31	09/02/18 15:21	General View		Load JPG	☒
32	09/02/18 15:21	General View		Load JPG	☒
33	09/02/18 15:21	General View		Load JPG	☒
34	09/02/18 15:21	Reinspection Photo		Load JPG	☒
35	09/02/18 15:21	Reinspection Photo		Load JPG	☒
36	09/02/18 15:21	Reinspection Photo		Load JPG	☒
37	09/02/18 15:21	Reinspection Photo		Load JPG	☒
38	09/02/18 15:21	Reinspection Photo		Load JPG	☒
39	09/02/18 15:21	Reinspection Photo		Load JPG	☒
40	09/02/18 15:21	Reinspection Photo		Load JPG	☒
41	09/02/18 15:21	Reinspection Photo		Load JPG	☒
42	09/02/18 15:21	Reinspection Photo		Load JPG	☒
43	09/02/18 15:21	Reinspection Photo		Load JPG	☒
44	09/02/18 15:21	Reinspection Photo		Load JPG	☒
45	09/02/18 15:21	Reinspection Photo		Load JPG	☒
46	09/02/18 15:21	Reinspection Photo		Load JPG	☒
47	09/02/18 15:21	Reinspection Photo		Load JPG	☒
48	09/02/18 15:21	Reinspection Photo		Load JPG	☒
49	09/02/18 15:21	Reinspection Photo		Load JPG	☒
50	09/02/18 15:21	Reinspection Photo		Load JPG	☒
51	09/02/18 15:21	Reinspection Photo		Load JPG	☒
52	09/02/18 15:21	Reinspection Photo		Load JPG	☒
53	09/02/18 15:21	Reinspection Photo		Load JPG	☒
54	09/02/18 15:21	Reinspection Photo		Load JPG	☒
55	09/02/18 15:21	Reinspection Photo		Load JPG	☒
56	09/02/18 15:21	Reinspection Photo		Load JPG	☒
57	09/02/18 15:21	Reinspection Photo		Load JPG	☒
58	09/02/18 15:21	Reinspection Photo		Load JPG	☒
59	09/02/18 15:21	Reinspection Photo		Load JPG	☒
60	09/02/18 15:21	Reinspection Photo		Load JPG	☒
61	09/02/18 15:21	Reinspection Photo		Load JPG	☒
62	09/02/18 15:21	Reinspection Photo		Load JPG	☒
63	09/02/18 15:21	Reinspection Photo		Load JPG	☒
64	09/02/18 15:21	Reinspection Photo		Load JPG	☒
65	09/02/18 15:21	Reinspection Photo		Load JPG	☒
66	09/02/18 15:21	Reinspection Photo		Load JPG	☒
67	09/02/18 15:21	Reinspection Photo		Load JPG	☒
68	09/02/18 15:21	Reinspection Photo		Load JPG	☒
69	09/02/18 15:21	Reinspection Photo		Load JPG	☒
70	09/02/18 15:21	Reinspection Photo		Load JPG	☒
71	09/02/18 15:21	Reinspection Photo		Load JPG	☒
72	09/02/18 15:21	Reinspection Photo		Load JPG	☒
73	09/02/18 15:21	Reinspection Photo		Load JPG	☒
74	09/02/18 15:21	Reinspection Photo		Load JPG	☒

75	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
76	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
77	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
78	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
79	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
80	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
81	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
82	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
83	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
84	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
85	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
86	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
87	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
88	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
89	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
90	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
91	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
92	09/02/18 15:21	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/12/17 15:18	TP GIA REPORT	1	Load PDF	
2	09/02/18 16:10	WORKSHOP ESTIMATE	1	Load PDF	
3	27/02/18 11:40	WORKSHOP INVOICE	1	Load PDF	
4	27/02/18 11:40	AUTHORISATION TO ACT FORM	1	Load PDF	
5	27/02/18 11:40	Release Voucher	1	Load PDF	
6	27/02/18 11:40	LTA SEARCH	1	Load PDF	
7	27/02/18 11:40	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFD6068Z (Insd veh)	Model:	TOYOTA COROLLA 1.6 (A)
	SGD2740E (TP veh)		
Date of Accident:	04/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	17,045.19
Final Repair Cost	:	\$	6,800.00
Loss of Use	:	\$	720.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,525.35

12.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100____(%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Sin Hwee Motor Pte Ltd	:	\$ 7,525.35
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

27 Feb
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023448/AYA3Q2

Date: 27/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494286
 Claimant Vehicle No: SGD2740E Insured Vehicle No: SFD6068Z
 Date of Loss: 04/12/2017 Nature of Claim: TP Claim No: 8013870067SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGD2740E
 Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 3ZZ4545625
 Reg. Date: 15/02/2006 (Man. Year: 2006) Chassis No: MR053ZEC107113258
 Colour: Silver Odometer: 0 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,880.19	6,375.30	4,504.89	41.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,165.00	2,210.00	3,955.00	64.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,045.19	8,585.30	8,459.89	49.63
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	17,045.19	6,800.00	10,245.19	60.11
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		7,525.35		

INSPECTION

Date of Assignment: 08/12/2017
 Date Inspected: 08/12/2017 Inspected At: Sin Hwee Motor Pte Ltd (HQ)
 Blk 3023A, Ubi Road 1, #01-59
 Singapore 408717
 Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	486.00 FL	*486.00 FL
2	10		*BUMPER CLIP	Necessary	45.00 FL	*30.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	329.31 FL	*329.31 FL
4	1		*BUMPER SIDE RETAINER	O/S Necessary	78.22 FL	*39.11 FL
5	1		*FRONT FENDER R/H	Distorted	256.33 FL	*256.33 FL
6	1		*FRONT FENDER INNER COVER RH	Torn	87.39 FL	*87.39 FL
7	1		*FOG LAMP COVER R/H	Missing	58.22 FL	*58.22 FL
8	1		*HEADLAMP L/H	Not Necessary	384.62 FL	*- FL
9	1		*HEADLAMP R/H	Smashed	384.62 FL	*384.62 FL
10	1		*CENTER GRILLE	Not Necessary	265.50 FL	*- FL
11	1		*WASHER TANK	Distorted	186.80 FL	*186.80 FL
12	1		*WASHER TANK MOTOR	Damaged	76.78 FL	*76.78 FL
13	1		*ABS PUMP	Not Necessary	2,859.25 FL	*- FL
14	1		*RADIATOR ASSY	Not Necessary	895.50 FL	*- FL
15	1		*SUPPORT PANEL	Buckled	887.66 FL	*887.66 FL
16	1		*WHEEL HOUSE PANEL	Repair	798.54 FL	*- FL
17	1		*FRONT DOOR R/H	Dented	558.14 FL	*558.14 FL
18	1		*FRONT DOOR PROTECTOR R/H	Cut	56.27 FL	*56.27 FL
19	1		*PROTECTOR CHROME	Cut	35.74 FL	*35.74 FL
20	1		*FRONT DOOR HINGE -TOP	Bent	48.57 FL	*48.57 FL
21	1		*FRONT DOOR HINGE -BOTTOM	Bent	48.57 FL	*48.57 FL
22	1		*BATTERY HOLDER	Not Necessary	49.28 FL	*- FL
23	1		*FRONT ABSORBER R/H	Bent	367.25 FL	*367.25 FL
24	1		*ABSORBER TOP MOUNT	Not Necessary	87.54 FL	*- FL
25	1		*LOWER ARM R/H	Bent	240.69 FL	*240.69 FL
26	1		*LOWER ARM BALL JOINT	Bent	84.24 FL	*84.24 FL
27	1		*KNUCKLE ARM R/H	Bent	380.14 FL	*380.14 FL
28	1		*KNUCKLE ARM BEARING	Necessary	95.87 FL	*95.87 FL
29	1		*ABS SENSOR	Not Necessary	248.10 FL	*- FL
30	1		*TIE ROD R/H	Bent	87.20 FL	*87.20 FL
31	1		*STEERING RACK ASSEMBLY	Damaged	1,290.58 FL	*1,290.58 FL
32	1		*ANTI ROLL BAR	Not Necessary	257.41 FL	*- FL
33	1		*ANTI ROLL BAR LINK	Bent	67.14 FL	*67.14 FL
34	1		*FRONT CROSSMEMBER	Bent	780.45 FL	*780.45 FL
35	1		*DRIVE SHAFT	Damaged	764.00 FL	*764.00 FL
36	1		*SPORT RIM	Cut	480.00 FS	*400.00 FS
37	1		*TYRE	Punctured	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,286.92	8,307.07
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,406.73	1,931.77
Total Parts (\$\$)	10,880.19	6,375.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMOUNT RADIATOR /CONDENSER ASSY TO FACILITATE REPAIR WORK .TO SUPPLY AND TOP UP AIR CON GAS	New	280.00	100.00
2	ENGINE COOLANT	New	65.00	20.00
3	TO DISMOUNT AND MOUNT DASHBOARD TO FACILITATE WHEEL HOUSE PANEL REPLACEMENT	New	480.00	0.00
4	TO CARRY ABS SYSTEM SCAN AND RESET FAULT CODE TO SUPPLY BRAKE FLUID AND CARRY OUT ABS SYSTEM FLUSHING/BLEEDING	New	350.00	0.00
5	TO DISMOUNT AND REPLACE FRONT UNDER CARRIAGE INCLUDE CROSSMEMBER ,STEERING RACK ,ARMS ,ABSORBER AND UNKS.TO PRESS AND JACK KNUCKLE ARM BEARING	New	580.00	380.00
6	TO SET UP CAR O LINER TOOLS AND BENCH .TO MOUNT VEHICLE ON BENCH AND MEASURE FRONT CHASSIS FRAME	New	350.00	0.00
7	TO REPLACE FRONT SUPPORT PANEL AND WHEEL HOUSE PANEL.INCLUDING KNOCKING ,CUTTING AND WELDING .TO INSTALL AND ALIGN REPLACED /AFFECTED PARTS TO SYMMETRICAL SPEC	New	2,200.00	800.00
8	TO SPRAY PAINT DOOR ,DOOR PILLAR ,SUPPORT PANEL ,BUMPER FENDER ,WHEEL HOUSE PANEL AND CHASSIS FRAME	New	980.00	600.00
9	TO TRANSFER DOOR MECHANISM ,FITTINGS AND TRIM TO NEW DOOR	New	150.00	80.00
10	TO CARRY OUT COMPUTERIZED 4 WHEELS ALIGNMENT	New	150.00	80.00
11	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA	New	250.00	60.00
12	TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS	New	180.00	30.00
13	TOWING SERVICE	New	150.00	60.00
Gross Labour Cost (S\$)			6,165.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >