

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 513K - AIG**AAD1712-058***Not Authored*
11/12/2017 @ 4250h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF 513K - CANDY
 VF1ABL15AUC278250
 RENAULT
 LATITUDE
 06.12.2017
AIG

PART**LIST**

1	1	BUMPER COVER FRT	\$	Sn	1,259.42	
2	1	BUMPER ABSORBER FRT	\$	Sn	394.68	
3	1	BUMPER BEAM FRT	\$	R	914.08	
4	1	BUMPER SPOILER FRT	\$	Sn	181.75	
5	1	BUMPER UNDERTRAY FRT	\$	Sn	472.83	
6	1	BUMPER GRILLE LOWER FRT	\$	Sn	266.80	
7	1	BUMPER FOG LAMP GRILLE LH	\$	Sn	207.22	
8	1	BUMPER RETAINER FRT LH	\$	Sn	151.41	
9	1	BUMPER BRACKET FRT LH	\$	R	181.75	
10	1	HEADLAMP LH	\$	Sn	1,184.43	
11	1	HEADLAMP PANEL FRT LH	\$	R	152.15	
12	1	FENDER PANEL FRT LH	\$	R	783.83	
13	1	FENDER INSULATOR LH	\$	Sn	130.84	
14	1	FENDER BRACKET FRT LH	\$	R	34.14	
15	1	WHEELARCH FRT LH	\$	Sn	278.84	
16	1	RADAITOR GRILLE	\$	Sn	1,707.78	
17	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	Sn	173.36	
18	1	RADAITOR GRILLE FRAME	\$	Sn	1,353.75	
19	1	FRAME FULL SUPPORT PANEL	\$	R	615.90	
20	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79	
21	1	BONNET	\$	R	1,941.63	
22	1	DOOR MIRROR LH	\$	CRA	1,483.40	✓
23	1	DOOR MIRROR GLASS LH	\$		242.33	✓
24	1	DOOR MIRROR BACK COVER LH	\$		218.46	✓
25	1	DOOR MIRROR LAMP LH	\$		194.18	✓
26	1	DOOR PANEL FRT LH	\$	nd/way	2,844.66	✓
27	1	DOOR FRAME PANEL FRT LH	\$	R	5,550.98	✓
28	1	DOOR HINGE UPPER LH	\$	R	274.50	✓
29	1	DOOR HINGE LOWER LH	\$	R	300.55	✓
30	1	DOOR CHECK FRT LH	\$	Sn	194.77	✓
31	1	DOOR LOCK FRT LH	\$	R	908.75	✓
32	1	DOOR CATCH FRT LH	\$	Sn	131.23	✓
33	1	DOOR GRAB HANDLE FRT LH	\$	Sn	210.96	✓
34	1	DOOR HANDLE OUTER FRT LH	\$	R	477.76	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-058**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 513K - AIG

35	1	DOOR HANDLE CAP FRT LH	\$	Sh	35.52	}
36	1	DOOR HANDLE SEAL FRT LH	\$	Sh	7.89	
37	1	DOOR HANDLE COVER FRT LH	\$	Sh	13.22	
38	1	DOOR HANDLE MODULE FRT LH	\$	Sh	133.60	
39	1	DOOR FINISHER FRT LH	\$	Sh	515.06	
40	1	DOOR MOULDING FRT LH	\$	Sh	176.82	
41	1	DOOR WHETHERSTRIP FRT LH	\$	Sh	410.27	
42	1	DOOR SEAL LOWER FRT LH	\$	Sh	91.17	
43	1	DOOR SEAL FRT LH	\$	Sh	72.82	
44	1	DOOR GLASS RUNNER SEAL FRT LH	\$	Sh	626.36	
45	1	DOOR WAIST SEAL OUTER FRT LH	\$	Sh	291.27	
46	1	ROCKER PANEL OUTER LH	\$	R	987.49	
47	1	DOOR PANEL REAR LH	\$	R	2,844.66	
48	1	DOOR GUIDE REAR LH	\$	Sh	176.82	
49	1	DOOR HINGE UPPER LH	\$	R	274.50	
50	1	DOOR HINGE LOWER	\$	R	300.55	
51	1	DOOR CHECK REAR LH	\$	Sh	203.06	
52	1	DOOR GRAB HANDLE REAR LH	\$	Sh	210.96	
53	1	DOOR HANDLE OUTER REAR LH	\$	Sh	126.49	
54	1	DOOR HANDLE CAP REAR LH	\$	Sh	35.52	
55	1	DOOR HANDLE SEAL REAR LH	\$	Sh	7.89	
56	1	DOOR HANDLE COVER REAR LH	\$	Sh	13.22	
57	1	DOOR HANDLE MODULE REAR LH	\$	Sh	133.60	
58	1	DOOR FINISHER REAR LH	\$	Sh	423.10	
59	1	DOOR MOULDING REAR LH	\$	Sh	176.82	
60	1	DOOR SEAL REAR LH	\$	Sh	162.02	
61	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sh	334.69	
62	1	FENDER PANEL REAR LH	\$	R	3,299.13	

TOTAL	\$	37,593.43
10%	\$	3,759.34
	\$	33,834.09

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	N	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	N	66.00	X
3	1SET	BUMPER SUPPORT FRT CLIP LH	\$	N	9.80	X
4	1SET	BUMEPR RETAINER FRT CLIP LH	\$	N	12.50	X
5	1	RIM LH FRT	\$	Sh	385.00	X
6	1	TYRE LH FRT	\$	Sh	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	N	80.00	60sm
8	1	DOOR STICKER "Classic"	\$	N	30.00	15sm

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-058

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019262G

SHF 513K - AIG

9 1 DOOR STICKER "6555-3333"

\$

nn 80.00 60sn

TOTAL

\$

1,059.30

TOTAL PARTS

\$

34,893.39

To Check Electrical Lighting Concerned.

\$

170.00 20l

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$

4,200.00 500l

Putty and spray painting of the affected portion.

\$

4,500.00 700l

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$

nn 170.00 X

To transfer of tire, rim and on wheel balancing.

\$

nn 170.00 X

To check steering geometry and computer wheel
alignment

\$

nn 220.00 X

To Remove And Refit Front W/Screen Glass To
Facilitate Bodywork Repair.

\$

nn 170.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$

170.00 60l

Towing fees

\$

nn 120.00 X

To rust-proofing of the affected areas.

\$

170.00 30l

TOTAL

\$

10,060.00

Over All Total

\$

44,953.39

(PARTS BY PARTS) Repair Days**15-Days**

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: