

INS. CASE OWNER:

JOWYN

CC 3 / CTI170 234571 K1ca352

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KALVIN

DOI:

08/12/17

Date / Time:

08/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SJZ 3861G
 Name of Insured: MS. RK MOTORING PTE LTD
 Insured Tel No.: _____ HP: 9695 5559
 Excess Sec II :SS _____ D.O.A.: 08/12/17
 Is driver the owner? (YES ☒ NO ☐ Nature of Accident: _____

Claim No.: CNM17D07022C0211
 Policy No.: OMHCEN1716331700
 Make / Model: HONDA CROSSROAD -1.8(A)
 Place of Accident: ALONG TAMPINES AVE 12 TWOS AVE 9

If NO, Driver Name / Age: LOO LIAN JIE, FRANCISOI GIA REPORT: YES ☒ / NO ☐ ; TP GIA REPORT: YES ☒ / NO ☐Driver Tel No.: 8717 5543(V/L: YES ☒ / NO ☐

Insured Liability: % Final? Yes / No

SJZ 3861G
OISHC 6845D
TPSH 7720S

INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP: PRIMA AUTO (CHINA) (with)
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC 6845D - CS/MSG17022317/K1gh DOA: 20/11/17
- N3A/MSG17022670/K DOA: 21/11/17
SJZ 3861G - CCL17613021264/Phh3y DOA: 10/11/17

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/12/17 (Asher)

18/12/17 10:45 CALLED DR. CONFIRMED ACCIDENT. OLD REAR ENDED TP, INFORM TP
 CLAIM AGREED TO SETTLE AND ASKED ABOUT NOO ISMB.

3/1/18

FILE PRESS TO TYPIST TO PREPARE REPORT.

RECEIVED 31 JAN 2018

RECEIVED 28 MAR 2018

PRELIMINARY ADVICE Date/Time: 11/12/17Sent By: Shirley HewConfirm by: AWK

FINALIZATION

Date/Time: 29/12/17Confirm with: GARYConfirm by: AWKRepair Cost: PIP SS\$5,997.10 (4 days) Reduction: 34 %Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 13/3/18Confirm with: GARYEmail ☒ Call ☐Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: 10/151 SS\$6,416.90

OLD REAR ENDED TP

Loss of Rental (LOR): SS 622.77 (5.5 days) x 113.537Loss of Use (LOU): SS - (\$ x days)Loss of Income (LOI): SS - (\$ x days)LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]GIA/LTA Search: SS 2.00Medical: SS -Disbursement: SS - (e.g. Tow/ Independent)Legal Cost: SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP3) Survey fee: 4400Total: SS\$7,041.67

Global Sum SS:

FINAL PAYMENT

Date/Time: 13/3/18Confirm with: GARYEmail ☒ Call ☐Payee 1: SS\$7,041.67Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTDPayee 2: (Strike if N.A.) \$

Name 2:

Payee 3: (Strike if N.A.) \$

Name 3:

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17023457/K1ea3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJZ 3861G	Veh. Inspected	SHC 6845D
Policy No.	DMHCSN1716331700	Coverage (\$)	0.00
Claim No.	SNM17D07022C02/1	Excess (\$)	0.00
Assign From		Assign Date	11/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/12/2017	Inspection Date	08/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D

1 pc	Boot lid — <i>Per</i>	\$	1,119.00
1 pc	Boot lid lock — <i>Paul</i>	\$	99.00
1 pc	Bootlid striker <i>X sun</i>	\$	21.00
1 pc	Bootlid emblem — <i>rec</i>	\$	27.00
1 pc	Bootlid CRDi — <i>rec</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X sun</i>	\$	96.00
1 pc	Boot lid lower garnish <i>X repair</i>	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 — <i>Per</i>	\$	132.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	End panel garnish — <i>rec</i>	\$	74.00
1 pc	Spare tyre clamp <i>X sun</i>	\$	6.00
2 pcs	n/s & o/s reflector @ \$350.00 <i>N/S X sun</i>	\$	700.00
2 pcs	n/s & o/s tail lamp @ \$421.00 <i>o/s ✓ rec</i>	\$	842.00
1 pc	Rear bumper — <i>Per</i>	\$	696.00
1 pc	Rear bumper lower cover — <i>rec</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>Per</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>✓</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>✓</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X sun</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X sun</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>Per</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>N/S X o/s — rec</i>	\$	92.00
		\$	5,633.00
Less 10%		\$	563.80
		\$	5,074.20

S/NETT

1 set	Rear bumper clips — <i>rec</i>	\$	48.00
1 set	End panel inner garnish clips — <i>rec</i>	\$	30.00
1 set	Bootlid lower garnish clips <i>X</i>	\$	60.00
1 set	Bootlid stickers — <i>rec</i>	\$	100.00
1 set	Reverse sensor — <i>still</i>	\$	280.00 <i>200</i>
1 pc	rear bumper top protector — <i>rec</i>	\$	80.00 <i>50</i>

7-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D

Sundry	
To dismantle / replace reverse sensor to new bumper and reset to the same	rec \$ 50.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 120.00 20
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear n/s & o/s chassis member etc	\$ 180.00 X ₂
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s & o/s chassis member.	\$ 1,400.00 800
To apply rustproofing on the repaired and replaced panels.	\$ 1,400.00 720
	\$ 250.00 50
	<u>\$ 9,072.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin CKK

8/12/17 1330 hrs.

4 Days.

P/P

Before Part photo

LKK Auto Consultants to inform notify the Repairer of the following:	
• To resurvey before / after spray painting	
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by:	Signature:
Date:	

29/12/17
checked P/P \$5997.10 / 4 days

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D

1 pc	Boot lid ✓		\$	1,119.00
1 pc	Boot lid lock ✓		\$	99.00
1 pc	Bootlid striker ?		\$	21.00
1 pc	Bootlid emblem ✓		\$	27.00
1 pc	Bootlid CRDi ✓		\$	29.00
1 pc	Boot lid rubber weatherstrip X		\$	96.00
1 pc	Boot lid lower garnish X repair		\$	290.00
2 pcs	Bootlid hinge @ \$66.00 ✓		\$	132.00
1 pc	End panel X repair		\$	250.00
1 pc	End panel garnish ✓		\$	74.00
1 pc	Spare tyre clamp ?		\$	6.00
2 pcs	n/s & o/s reflector @ \$350.00 N/S X o/s ✓		\$	700.00
2 pcs	n/s & o/s tail lamp @ \$421.00 ✓ o/s o/s		\$	842.00
1 pc	Rear bumper ✓		\$	696.00
1 pc	Rear bumper lower cover ✓		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?		\$	58.00
1 pc	Rear bumper inner sponge ?		\$	114.00
1 pc	Rear bumper reinforcement ?		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 N/S X o/s ✓		\$	92.00
				\$ 5,638.00
Less 10%				\$ 563.80
				\$ 5,074.20

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips ✓	\$	30.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	rear bumper top protector ✓	\$	80.00 50

7-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D

Sundry

\$ ~~50.00~~ 20

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ 20

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ X

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear n/s & o/s chassis member etc

\$ ~~1,400.00~~ 800

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s & o/s chassis member.

\$ ~~1,400.00~~ 720

To apply rustproofing on the repaired and replaced panels.

\$ ~~250.00~~ 50

\$ 9,072.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

Kelvin CKK
8/12/17 1330 hrs.

4 Days.

P/P

Before Part photo

LKK Auto Consultants to be notify
the Repairer of the following

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI17023457/K1ea3

Date: 11.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 6845D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report:-

Workshop Estimate Amount	: S\$	9,072.20
Revised Estimate Amount	: S\$	5,296.00
"Check" Items Amount	: S\$	887.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

1119.00	21.00	48.00	60.00
99.00	96.00	30.00	80.00
27.00	290.00	100.00	30.00
29.00	250.00	200.00	30.00
132.00	6.00	50.00	100.00
74.00	350.00	20.00	180.00
350.00	58.00	20.00	600.00
842.00	114.00	800.00	680.00
696.00	607.00	720.00	200.00
206.00	108.00	50.00	
46.00	36.00		
	36.00		
	46.00		

0.00

0.00

0.00

2038.00

1960.00

3620.00 2018.00

5638.00	3998.00	0.00
3620.00	2038.00	0.00
2018.00	1960.00	0.00

3620.00
362.00
3258.00
2038.00

5296.00

21.00
6.00
58.00
114.00
607.00
108.00
36.00
36.00

}

CHECK ITEMS

986.00
98.60
887.40

4/12 @ 4.18%

hmm



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17023457/K1ea3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 3861G	Veh. Inspected	SHC 6845D
Policy No.	DMHCSN1716331700	Coverage (\$)	0.00
Claim No.	SNM17D07022C02/1	Excess (\$)	0.00
Assign From		Assign Date	08/12/2017

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5621885	Colour	SILVER
Odometer	272186	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65R16	MAXXIS	7 mm
L/H Front Tyre	205/65R16	MAXXIS	7 mm
R/H Rear Tyre	205/65R16	MAXXIS	7 mm
L/H Rear Tyre	205/65R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/12/2017	Inspection Date	08/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6845D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	JAMMED	99.00	99.00
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGE @ \$66.00	BENT	132.00	132.00
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	CRACKED	74.00	74.00
1	SPARE TYRE CLAMP	SERVICEABLE	6.00	-
2	N/S & O/S REFLECTOR @ \$350.00	N/S SERVICEABLE / O/S CRACKED	700.00	350.00
2	N/S & O/S TAIL LAMP @ \$421.00	CRACKED	842.00	842.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00	BENT	58.00	58.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @ \$53.00	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @ \$46.00	N/S SERVICEABLE / O/S CRACKED	92.00	46.00
	LESS 10% DISCOUNT		-563.80	-439.90
			5,074.20	3,959.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00

Report Ref No. CC3/CT117023457/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET END PANEL INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			648.00	448.00
	LABOUR			
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD, CUT-OFF THE END PANEL. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, REAR N/S & O/S CHASSIS MEMBER ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL.		1,400.00	800.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, FLOORBOARD COMPARTMENT, END PANEL, REAR N/S & O/S CHASSIS MEMBER.		1,400.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
			3,350.00	1,590.00
GRAND TOTAL			9,072.20	5,997.10
RECOMMENDED COST OF REPAIRS				5,997.10

Report Ref No. CC3/CT117023457/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.