

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

7-Dec-17

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D

1 pc	Boot lid ✓		\$	1,119.00
1 pc	Boot lid lock ✓		\$	99.00
1 pc	Bootlid striker ?		\$	21.00
1 pc	Bootlid emblem ✓		\$	27.00
1 pc	Bootlid CRDi ✓		\$	29.00
1 pc	Boot lid rubber weatherstrip X		\$	96.00
1 pc	Boot lid lower garnish X <i>repa. v</i>		\$	290.00
2 pcs	Bootlid hinge @ \$66.00 ✓		\$	132.00
1 pc	End panel X <i>repa. v</i>		\$	250.00
1 pc	End panel garnish ✓		\$	74.00
1 pc	Spare tyre clamp ?		\$	6.00
2 pcs	n/s & o/s reflector @ \$350.00 N/S X <i>o/s ✓</i>		\$	700.00
2 pcs	n/s & o/s tail lamp @ \$421.00 ✓ <del>o/s</del> <del>o/s</del>		\$	842.00
1 pc	Rear bumper ✓		\$	696.00
1 pc	Rear bumper lower cover ✓		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?		\$	58.00
1 pc	Rear bumper inner sponge ?		\$	114.00
1 pc	Rear bumper reinforcement ?		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 N/S X <i>o/s ✓</i>		\$	92.00
			\$	5,638.00
			Less 10%	\$ 563.80
			\$	5,074.20

### S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips ✓	\$	30.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 <i>200</i>
1 pc	rear bumper top protector ✓	\$	80.00 <i>50</i>

7-Dec-17

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6845 D**

Sundry	\$ <del>50.00</del> 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ <del>120.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ <del>180.00</del> X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear n/s & o/s chassis member etc	\$ <del>1,400.00</del> 800
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s & o/s chassis member.	\$ <del>1,400.00</del> 720
To apply rustproofing on the repaired and replaced panels.	\$ <del>250.00</del> 50
	<u>\$ 9,072.20</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kelvin CKK  
8/12/17 1330 hrs.

4 Days

P/P

Before Paint photo

<p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by _____</p> <p>Signature: _____</p> <p>Date: _____</p>
---