

22/03/2003

ASS. REC. BY:

REF: CS/FCU7023459/Uthbn2

Special Instruction:

Surveyor: Marcus.

ASSIGNMENT (Office)

From (Person): CWS Wrene Teo of FCL Date/Time: 11.12.2017 1:22pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FBH 3641P Insured: SHA 9180D

at Workshop m/s Endia Motor Tel: 9069 6165

of Blk 1 Kaki Bukit Ave 6 #02-62

Policy No: Claim No: D17011171M75H

Sum Insured: Excess:

Make of Veh: D.O.A. 29.11.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

12.12.2017

H.O.D. Endorsement:

Date/Time: 11.12.2017 1:22pm Person Contacted: Mr Teo Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBH 3641P - X
	SHA 9180D - CCU 1AxA170P524 / K1W0392
	DA: 06.10.17

Surveys (Mortgage)

REF: FCL

ASSIGNMENT

From: _____ Date: 12-12-2017

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 3641P

at Workshop m/s: Erofia Motor

of: Blk 1 Kaki Bukit Ave 6 #02-62

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 5200

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBM 3641P Yr Regn: 5 13

Type: M/Car / ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha TTX 114

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 35912 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MLE5E634111699617

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: 80-80-14

R: 110-70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRC

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/11/17 D.O.I. 12/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Body

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction LTA 924 5 yrs bond.

net 4276

29/11/17 4/5 @ 1700 confirmed with un 700 (Red. 2657.70 :-60%)

RECEIVED 20 - 2017

Date/Time, File Pass to? ☐ Preli. Report

1) 28/12 Typist ☒ Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ - RS \$

Photos

Others

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 1700)

TOTAL

135
50
50
62
297

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023459/Utb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9180D	Veh. Inspected	FBH 3641P
Policy No.		Coverage (\$)	0.00
Claim No.	D17011171MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/11/2017	Inspection Date	11/12/2017
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011171MFSH
Accident Date	29-11-2017	Claim Type. Third Party
Insured Vehicle	SHA9180D	Third Party Vehicle. FBH3641P
Survey Location	1 KAKI BUKIT AVE 6 #02-62	
Contact Person.	TEO	
Contact No.	67527740/ 90696165	Fax No. 67528669
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EROFIA MOTOR TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231407)



PRI Documents



Close



PRI Header Details

Claim No	D17011171MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & ER LTD
Workshop Name	EROFIA MOTOR TRADING PTE LTD (Contact Person : TEO)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 #02-62 Mobile: 90696165 , Phone: 67527740 , Fax: EmailId: EROFIA@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9180D	TP Vehicle No	FBH364
PRI Recieved Date	08-12-2017 05:22:13 PM	Surveyor Appointed Date	11-12-2017 11:37:17 AM	Surveyor Accept Date	11-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-12-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAUTO)

To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011171MFSH/1
Attachments: PRELI ADVISED FBH 3641P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FBH 3641P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Monday, 11 December, 2017 1:23 PM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17011171MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Monday, 11 December, 2017 11:37 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17011171MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011171MFSH

Date: 13/12/2017

Our Ref: CS/FCI17023459/Utb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBH 3641P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2017 at the premises of M/s Erofia at and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,357.7</u>
Revised Estimate Amount	: S\$ <u>2,228.50</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At o/s body portion.



Repair days: 4

Yours faithfully

Marcus

Motor Surveyor

REPUBLIC OF SINGAPORE DRIVING LICENCE

S9519996H



CHEW SI YAN

Birth Date: 10 Jun 1995
Issue Date: 18 Jun 2014

002316570J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	MOTORCYCLES NOT EXCEEDING 300 CC	09 Oct 2015
Class 3	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLADEN DOES NOT EXCEED 3500 KILOGRAMS	18 Jun 2014

S / No. 9000228539

NP 428A

Licence No: S9519996H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9519996H



Name

CHEW SI YAN

周 懿 宴

Race

CHINESE

Date of birth

10-06-1995

Sex

F

Country of birth

SINGAPORE

S9519996H

4513943



NRIC No. S9519996H



Date of issue

20-01-2010

Address

APT BLK 76 TELOK BLANGAH DRIVE
#07-268
SINGAPORE 100076

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5085867399-01

Cover : Third Party

1. Index mark and Registration Number of Vehicle : FBH3641P
Chassis Number : MLESE634111699617
2. Name of Policyholder : CHEW SI YAN
3. Effective Date of Insurance : 20 Nov 2017
4. Expiry Date of Insurance : 19 Nov 2018
5. Persons or Classes of Persons entitled to drive#

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: CHEW SI YAN
NAMED DRIVER (2)	: CHEW KAY BOO
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : VV INSURANCE AGENCY PTE. LTD. (00000614878)
Date of Issue : 23 Oct 2017 21:03 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9996H
Vehicle Details	
Vehicle No.	FBH3641P
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	YAMAHA
Vehicle Model	TTX
Primary Colour	Black
Manufacturing Year	2013
Engine No.	E3K3E699617
Chassis No.	MLESE634111699617
Maximum Power Output	-
Open Market Value	\$1,708.00
Original Registration Date	20 May 2013
First Registration Date	20 May 2013
Transfer Count	3
Actual ARF Paid	\$257.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	19 May 2023
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$1,700.00
COE Rebate Amount	\$924.00
Total Rebate Amount	\$924.00

The information contained herein is correct as at 12 Dec 2017

OK



(1)



REVOLUTIONARY?

DISCOVER PHANTOM

Bike model

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH ☐ VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Yamaha TTX115 (/listing/usedbike/yamaha-yamaha-ttx115/3331/)



(/listing/usedbike/yamaha-yamaha-ttx115/3331/)

sop\$5800

Reg : 30/10/2013

Type: Scooters

114cc

229788km

Trade in/Loan of vehicle available. Interested buyers are welcome to neg. Come visit M1 Motoring Serangoon.

Posted on : 03/12/2017

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-TTX115/3331/)

FIRST (?PAGE=1&REG_YEAR_FROM=1970&PRICE_FROM=&PRICE_TO=&BIKE_MODEL=YAMAHA+TTX115&LICENSE_CLASS=&BIKE_TYPE=&REG_YEAR_TO=2017)

1

LAST (?PAGE=1&REG_YEAR_FROM=1970&PRICE_FROM=&PRICE_TO=&BIKE_MODEL=YAMAHA+TTX115&LICENSE_CLASS=&BIKE_TYPE=&REG_YEAR_TO=2017)

WORK AROUND
YOUR SCHEDULE

deliveroo.com.sg/apply

Make the funds to fuel your
passion

Bike Gadgets

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

First

Name : Chew Si Yan

Accident Date : 29-Nov-17

Vehicle No : FBH 3641 P

Vehicle Model : Yamaha TTX

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 85.00
2	Fork inner tubes	\$ 160.00
2	Fork outer tubes	\$ 180.00
1	Fork under bracket	\$ 145.00
1	Front brake disc	\$ 115.00
1	Front rim shaft	\$ 38.00
1	Front rim	\$ 280.00
1	Front rim spooky (1 set)	\$ 60.00
1	Front signal -R/H	\$ 70.00
1	Handle bar	\$ 138.00
1	Handle bar end (1 set)	\$ 40.00
1	Brake lever (1 set)	\$ 68.00
1	Side mirror (1 set)	\$ 120.00
1	Front cowling lamp	\$ 80.00
1	Front cowling inner panel	\$ 150.00
1	Lower cowling	\$ 140.00
1	Front footstep panel	\$ 116.00
1	Exhaust assy	\$ 550.00
1	Exhaust protector	\$ 65.00
1	Main stand	\$ 85.00
1	Rear signal -R/H	\$ 65.00
1	Rear footrest -R/H	\$ 75.00
1	Throttle cable (1 set)	\$ 68.00
1	Fairing cover (1 set)	\$ 600.00
		\$ 3,493.00
	Less 10%	\$ 349.30
		\$ 3,143.70

Not Actual
ru
2/5 1700
telephone At Home
4dy.
12/12/17

Deep

Special Nett Items

1	Number plate (1 set)	\$ 28.00
2	Fork oils	\$ 30.00
2	Fork oil seals	\$ 56.00
1	Steering cone (1 set)	\$ 75.00
1	Rear box	\$ 180.00
1	Rear box bracket	\$ 100.00
1	Sticker (1 set)	\$ 90.00
1	Handphone holder	\$ 50.00
		\$ 609.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chew Si Yan

Accident Date : 29-Nov-17

Vehicle No : FBH 3641 P

Vehicle Model : Yamaha TTX

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 45.00 35
2	To check wiring and reset headlamp focusing.	\$ 11 80.00 x
3	To provide labour.	\$ 480.00 300
		<u>\$ 605.00</u>

224

Grand Total \$ 4,357.70

Dollars: Four Thousand Three Hundred Fifty-Seven And Seventy Cents Only.



EROFIA MOTOR TRADING PTE LTD

LHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To replace damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023459/Utn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9180D	Veh. Inspected	FBH 3641P	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011171MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA TTX	c.c	114	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	MLESE634111699617	Colour	BLACK	
Odometer	35912	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80-90-14	IRC	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110-70-14	IRC	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2017	Inspection Date	12/12/2017	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 3641P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	CUT	85.00	85.00
2	FORK INNER TUBES	TO REPAIR SEE LABOUR	160.00	-
2	FORK OUTER TUBES	NOT NECESSARY	180.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	145.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	115.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	38.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	280.00	-
1	SET FRONT RIM SPOOKY	NOT NECESSARY	60.00	-
1	FRONT SIGNAL-R/H	CUT	70.00	70.00
1	HANDLE BAR	BENT	138.00	138.00
1	SET HANDLE BAR END	SCRATCHED	40.00	40.00
1	SET BRAKE LEVER	SCRATCHED	68.00	68.00
1	SET SIDE MIRROR	CUT	120.00	120.00
1	FRONT COWLING LAMP	CRACKED	80.00	80.00
1	FRONT COWLING INNER PANEL	CRACKED	150.00	150.00
1	LOWER COWLING	CUT	140.00	140.00
1	FRONT FOOTSTEP PANEL	CUT	116.00	116.00
1	EXHAUST ASSY	NOT NECESSARY	550.00	-
1	EXHAUST ROTECTOR	TO REPAIR SEE LABOUR	65.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	85.00	-
1	REAR SIGNAL-R/H	CUT	65.00	65.00
1	REAR FOOTREST-R/H	CUT	75.00	75.00
1	SET THROTTLE CABLE	CUT	68.00	68.00
1	SET FAIRING COVER	DEEP CUT	600.00	600.00
	LESS 10% DISCOUNT		-349.30	-181.50
			3,143.70	1,633.50
SPECIAL NETT ITEMS				
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	20.00

Report Ref No. CS/FCI17023459/Utnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	75.00	-
1	REAR BOX (SN)	CUT	180.00	150.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	100.00	-
1	SET STICKER (SN)	NECESSARY	90.00	90.00
1	HANDPHONE HOLDER (SN)	NOT NECESSARY	50.00	-
			609.00	260.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		45.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FORK INNER TUBES, FRONT RIM, EXHAUST ROTECTOR, MAIN STAND AND REAR BOX BRACKET.		480.00	300.00
			605.00	335.00
GRAND TOTAL			4,357.70	2,228.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/FCI17023459/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.