

REPAIR ESTIMATE*

VEHICLE NO : SH 8925L

DATE 8/12/2017 12:12

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) ✓			\$ 29.20
	Headlamp Support Panel Assy ?			\$ 1,023.00
	Headlamp (RH) ✓			\$ 797.90
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) ✓			\$ 86.00
	Front Fender Retainer ?			\$ 9.20
	Front Wheel Hub Cap (RH) ✓			\$ 145.00
	<i>Front Bumper x repair</i>			
	SUB TOTAL			\$ 3,244.50
	LESS 20%			\$ 648.90
	DISCOUNTED TOTAL			\$ 2,595.60
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 600.00 5% x 600 = 300
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Aircon & Refill Gas			\$ 150.00 ?
	Frt Wheel Alignment			\$ 80.00 x
	TOTAL LABOUR			\$ 1,290.00
	ESTIMATE TOTAL			\$ 3,885.60
<i>Kaluh 12/10/17</i> <i>8/12/17 1420 hrs.</i> <i>3 days</i> <i>4/5</i> <i>After Repair p.h.t.</i> Let the customer know that the repair is not a guarantee. • To return the vehicle to the customer. • To display damaged parts to the surveyor. • Parts prices are subject to confirmation. • Third party survey is on a "Without Prejudice" basis. • No illegal modification(s) is allowed. • Supplementary item(s) must be surveyed and is subject to final approval from insurance company. Acknowledge by the customer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				