

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1209/2017/JT
Date	:	11-Dec-17

Vehicle NOT IN workshop. Kindly arrange for survey.

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Ms. Chong Chen Sian
Address	:	32 Amber Gardens #02-04 Singapore 439965
Telephone	:	HP +65 9459 2900
Type of Claim	:	Third Party Claims
Policy No.	:	2100422592-02000
Vehicle No	:	<b>SGV 7100 A</b>
Model Code	:	Audi A3 Sedan 1.4 TFSI (A)
Model / Year	:	Jul-15
Engine No	:	CZC 261233
Chassis No	:	WAUZZZ8V3F1138424
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Dec-17
Place of Accident	:	Holland Road towards Napier

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGV 7100 A.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function. Reinstall all parts removed.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.	\$ <del>900.00</del> 600	
3	To respray rear bumper.	\$ <del>800.00</del> 600	
4	To carry out diagnostic checks.	S/N \$ <del>192.00</del> ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,172.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGV 7100 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>deboned</i>	\$ 1,567.00	✓
2	REAR BUMPER SPOILER	\$ 193.00	+
3	REAR REINFORCEMENT BEAM	\$ 481.00	+
4	REAR BUMPER BRACKET - LHS/RHS	\$ 20.00	+
5	REAR PARKING AID SENSOR	2 \$ 415.00	+
6	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 2,976.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,148.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King.  
Surveyed Date : 12/12/17.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant