

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5478L - TOKIO**

AAD1712-071

*Not Authored**Recovery Bypass @ 2334.57*

|                       |                         |
|-----------------------|-------------------------|
| Vehicle No.:          | <b>SHC5478L - CANDY</b> |
| Chassis No.:          | VF1ABL15AUC280962       |
| Vehicle Make:         | RENAULT                 |
| Vehicle Model:        | LATITUDE                |
| Date of Accident :    | 07.12.2017              |
| Third Party Insurer : | <b>TOKIO</b>            |

| PART |                                    | LIST                          |
|------|------------------------------------|-------------------------------|
| 1    | 1 BUMPER COVER REAR                | \$ <i>Not Bore</i> 1,108.46 ✓ |
| 2    | 1 BUMPER LOWER REAR                | \$ <i>Not Bore</i> 768.84 ✓   |
| 3    | 1 BUMPER BRACKET CTR REAR          | \$ <i>Sh</i> 113.47           |
| 4    | 1 BUMPER BRACKET SIDE RH REAR      | \$ <i>Sh</i> 135.97           |
| 5    | 1 BUMPER RETAINER RH REAR          | \$ <i>Sh</i> 44.99            |
| 6    | 1 BUMPER REFLECTOR RH              | \$ <i>Sh</i> 43.61            |
| 7    | 1 BUMPER BRACKET SIDE LH REAR      | \$ <i>Sh</i> 135.97           |
| 8    | 1 BUMPER RETAINER LH REAR          | \$ <i>Sh</i> 44.99            |
| 9    | 1 BUMPER REFLECTOR LH              | \$ <i>Sh</i> 43.61            |
| 10   | 1 BUMPER BEAM REAR                 | \$ <i>R</i> 777.52            |
| 11   | 1 BUMPER BEAM BRACKET LH REAR      | \$ <i>R</i> 225.95            |
| 12   | 1 BUMPER BEAM BRACKET RH REAR      | \$ <i>R</i> 225.95            |
| 13   | 1 BOOT REAR                        | \$ <i>R</i> 2,872.68          |
| 14   | 1 BOOT FINISHER                    | \$ <i>Sh</i> 470.06           |
| 15   | 1 BOOT WHEATERSTRIP                | \$ <i>Sh</i> 323.05           |
| 16   | 1 BOOT REFLECTOR LAMP LH           | \$ <i>Sh</i> 493.35           |
| 17   | 1 BOOT REFLECTOR LAMP RH           | \$ <i>Sh</i> 493.35           |
| 18   | 1 BOOT BADGE 'RENAULT'             | \$ <i>na</i> 225.36           |
| 19   | 1 BOOT BADGE                       | \$ <i>na</i> 225.36           |
| 20   | 1 BOOT LOCK                        | \$ <i>R</i> 202.67            |
| 21   | 1 BOOT LOCK CATCH                  | \$ <i>R</i> 74.40             |
| 22   | 2 LICENCE PLATE LAMP               | \$ <i>Sh</i> 50.52            |
| 23   | 2 BOOT RUBBER PLUG                 | \$ <i>Sh</i> 221.81           |
| 24   | 1 FENDER PANEL REAR LH             | \$ <i>R</i> 3,299.13          |
| 25   | 1 FENDER PANEL REAR RH             | \$ <i>R</i> 3,299.13          |
| 26   | 1 TAILLAMP RH                      | \$ <i>Sh</i> 552.55           |
| 27   | 1 TAILLAMP PANEL RH                | \$ <i>R</i> 986.70            |
| 28   | 1 TAILLAMP LH                      | \$ <i>Sh</i> 552.55           |
| 29   | 1 TAILLAMP PANEL LH                | \$ <i>R</i> 986.70            |
| 30   | 1 OUTER PANEL REAR (End Panel)     | \$ <i>R</i> 1,471.77          |
| 31   | 1 OUTER PANEL REAR (End Panel)TRIM | \$ <i>Sh</i> 404.56           |
| 32   | 1 EXHAUST REAR                     | \$ <i>R</i> 7,489.05          |
| 33   | 1 EXHAUST CAP REAR                 | \$ <i>R</i> 230.49            |

X

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1712-071**

N0.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5478L - TOKIO**

|              |    |                  |
|--------------|----|------------------|
| <b>TOTAL</b> | \$ | <b>28,594.59</b> |
| <b>10%</b>   | \$ | <b>2,859.46</b>  |
|              | \$ | <b>25,735.13</b> |

**Specical Nett**

|    |      |                                   |                    |           |                  |     |
|----|------|-----------------------------------|--------------------|-----------|------------------|-----|
| 1  | 1SET | PARKING AID                       | \$                 | <i>Sm</i> | 700.00           | X   |
| 2  | 1SET | REAR BUMPER CLIP                  | \$                 | <i>nn</i> | 66.00            | —   |
| 3  | 1SET | BUMPER BRACKET CTR CLIP           | \$                 | <i>nn</i> | 33.00            | —   |
| 4  | 1SET | BUMEPR BRACKET SIDE CLIP RH RR    | \$                 | <i>nn</i> | 10.00            | X   |
| 5  | 1SET | BUMEPR RETAINER RH CLIP RR        | \$                 | <i>nn</i> | 20.00            | X   |
| 6  | 1SET | BUMEPR BRACKET SIDE CLIP LH RR    | \$                 | <i>nn</i> | 10.00            | X   |
| 7  | 1SET | BUMEPR RETAINER CLIP LH RR        | \$                 | <i>nn</i> | 20.00            | X   |
| 8  | 1SET | BUMPER LOWER REAR RIVET           | \$                 | <i>nn</i> | 22.00            | X   |
| 9  | 1SET | BUMPER LOWER REAR CLIP            | \$                 | <i>nn</i> | 66.00            | —   |
| 10 | 1    | EXHAUST MOUNTING REAR             | \$                 | <i>Sm</i> | 17.82            | } X |
| 11 | 1SET | BOOT FINISHER CLIP                | \$                 | <i>nn</i> | 24.20            |     |
| 12 | 1    | BOOT STICKER "Trans-cab"          | \$                 | <i>nn</i> | 30.00            |     |
| 13 | 1    | BOOT STICKER "6555-3333"          | \$                 | <i>nn</i> | 30.00            |     |
| 14 | 1    | BOOT INNER TRIM CLIP              | \$                 | <i>nn</i> | 45.00            |     |
| 15 | 1    | TAILLAMP CLIP RH                  | \$                 | <i>nn</i> | 5.00             |     |
| 16 | 1    | TAILLAMP CLIP LH                  | \$                 | <i>nn</i> | 5.00             |     |
| 17 | 2    | REAR WINDSCREEN SELANT            | \$                 | <i>nn</i> | 80.00            |     |
| 18 | 1    | WINDSCREEN MOULDING               | \$                 | <i>Sm</i> | 100.00           |     |
| 19 | 1    | REAR WINDSCREEN INNER SPONGE SEAL | \$                 | <i>Sm</i> | 100.00           |     |
| 20 | 1    | SPARE TYRE RIM (ROUE 7J 16H 2547) | \$                 | <i>Sm</i> | 385.00           |     |
| 21 | 1    | SPARE TYRE                        | \$                 | <i>Sm</i> | 330.00           |     |
|    |      |                                   | <b>TOTAL</b>       | \$        | <b>2,099.02</b>  |     |
|    |      |                                   | <b>TOTAL PARTS</b> | \$        | <b>27,834.15</b> |     |

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2201*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,800.00 *2001*

To Rust-Proofing Of The Affected Areas. \$ *nn* 170.00 X

To transfer of bootlid fittings, attachments and perform water seepage test. \$ *nn* 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5478L - TOKIO**

**AAD1712-071**

|  |    |                    |
|--|----|--------------------|
| To reinstall rear bumper parking sensor.   | \$ | 170.00 <i>Soi</i>  |
| To repair and realign rear exhaust pipe.   | \$ | <i>nn</i> 170.00 X |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | <i>nn</i> 170.00 X |
| To transfer of rear end panel fittings, attachment and perform water seepage test.   | \$ | <i>nn</i> 170.00 X |
| To transfer of rear fender fittings, attachment and perform water seepage test.      | \$ | <i>nn</i> 380.00 X |
| Towing Fees  | \$ | <i>nn</i> 120.00 X |
| To transfer of rear windscreen fittings and conduct water seepage test.              | \$ | <i>nn</i> 170.00 X |
| To check steering geometry and computer wheel alignment                              | \$ | <i>nn</i> 220.00 X |

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>TOTAL</b>          | <b>\$</b> | <b>7,710.00</b>  |
| <b>Over All Total</b> | <b>\$</b> | <b>35,544.15</b> |

**(PARTS BY PARTS)  
Repair Days**

*10 Days  
2 days*

LKK Auto Care Centre hereby notify the Repairer of the following:

- To resurvey by the insurer's rating
- To disclose damage and part of the resurvey
- Parts prices are at retail price for station
- Third party survey is on a "No Prejudice" basis
- No illegal amount to be received
- Supplementary to the survey is surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature  
D