

Survey Department Check List (Case Handler)

Reference No.: 23 TMI 17023526 Kvb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **):** Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month, Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 13/12/17
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI17023526/Kvb	
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 12-12-2017	
		Code : TMI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJS 3835U	Veh. Inspected	SHC 5478L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/12/2017	Inspection Date	11/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017		12 Dec 2017 18:13 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	YONG CHONG KIAT, ID: S7702564B		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5478L	Date of Loss:	07/12/2017 22:00 - :59
Claim Type:	TP / M1706291	Policy/Cover Note No.:	MC012178 (Comprehensive) Coverage: 13/08/2017 - 12/08/2018
Vehicle Reg. No. (Insured):	SJS3835U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/12/2017]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete			
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 12 December, 2017 11:06 AM
To: 'Too Joon Hwa'
Cc: SUR; priscilla@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 7/12/2017, SHC 5478L (TP VEHICLE), SJS 3835U(OI VEHICLE)
Attachments: EST.pdf; GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHC 5478L M/s: TRANS-CAB AUTO SERVICES PTE LTD,NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 11/12/2017.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3878K
Vehicle Details	
Vehicle No.	SHC5478L
Vehicle to be Exported	Yes
Intended De-registration Date	08 Dec 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C002388
Chassis No.	VF1ABL15AUC280962
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	18 Dec 2014
First Registration Date	18 Dec 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Dec 2022
PARF Rebate Amount	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date	17 Dec 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$51,668.00
COE Rebate Amount	\$32,448.00
Total Rebate Amount	\$41,821.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/12/2017 11:16
Date Of Accident	07/12/2017 22:10
Exact Location Of Accident	YISHUN AVENUE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5478L
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	WEE KONG HUI STEVEN
NRIC No	S1744139F
Date Of Birth	17/01/1966
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1989
Driving Experience	28 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92261300
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 373 CLEMENTI AVENUE 4 #12-200
Postcode	120373
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 07.12.2017 at about 2210hours, I was stationary straight on the extreme left lane along Yishun Avenue 4 when the traffic light was red. While stationary, suddenly I felt an impact. Vehicle B (SJS3835U) had hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS3835U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	YONG CHONG KIAT
NRIC/Passport Number	
Contact Number	82980292
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


pls see attach G/A Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5478L - TOKIO

AAD1712-071

Not Authorized

Refusing Bygone @ 2334.57

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5478L - CANDY
 VF1ABL15AUC280962
 RENAULT
 LATITUDE
 07.12.2017
TOKIO

PART

LIST

QTY	PART	UNIT	PRICE	TOTAL	REMARKS
1	BUMPER COVER REAR	\$	1,108.46	1,108.46	✓
2	BUMPER LOWER REAR	\$	768.84	1,537.68	✓
3	BUMPER BRACKET CTR REAR	\$	113.47	340.41	} X
4	BUMEPR BRACKET SIDE RH REAR	\$	135.97	543.81	
5	BUMEPR RETAINER RH REAR	\$	44.99	633.79	
6	BUMPER REFLECTOR RH	\$	43.61	682.81	
7	BUMEPR BRACKET SIDE LH REAR	\$	135.97	818.75	
8	BUMEPR RETAINER LH REAR	\$	44.99	863.74	
9	BUMPER REFLECTOR LH	\$	43.61	907.35	
10	BUMPER BEAM REAR	\$	777.52	1,684.87	
11	BUMPER BEAM BRACKET LH REAR	\$	225.95	1,910.82	
12	BUMPER BEAM BRACKET RH REAR	\$	225.95	2,136.77	
13	BOOT REAR	\$	2,872.68	5,009.45	
14	BOOT FINISHER	\$	470.06	5,479.51	
15	BOOT WHEATERSTRIP	\$	323.05	5,802.56	
16	BOOT REFLECTOR LAMP LH	\$	493.35	6,295.91	
17	BOOT REFLECTOR LAMP RH	\$	493.35	6,789.26	
18	BOOT BADGE 'RENAULT'	\$	225.36	7,014.62	
19	BOOT BADGE	\$	225.36	7,239.98	
20	BOOT LOCK	\$	202.67	7,442.65	
21	BOOT LOCK CATCH	\$	74.40	7,517.05	
22	LICENCE PLATE LAMP	\$	50.52	7,567.57	
23	BOOT RUBBER PLUG	\$	221.81	7,789.38	
24	FENDER PANEL REAR LH	\$	3,299.13	11,088.51	
25	FENDER PANEL REAR RH	\$	3,299.13	14,387.64	
26	TAILLAMP RH	\$	552.55	14,940.19	
27	TAILLAMP PANEL RH	\$	986.70	15,926.89	
28	TAILLAMP LH	\$	552.55	16,479.44	
29	TAILLAMP PANEL LH	\$	986.70	17,466.14	
30	OUTER PANEL REAR (End Panel)	\$	1,471.77	18,937.91	
31	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	19,342.47	
32	EXHAUST REAR	\$	7,489.05	26,831.52	
33	EXHAUST CAP REAR	\$	230.49	27,062.01	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-071

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5478L - TOKIO

TOTAL	\$	28,594.59 ¹
10%	\$	2,859.46
	\$	25,735.13

Special Nett

1	1SET	PARKING AID	\$	Sm 700.00 X
2	1SET	REAR BUMPER CLIP	\$	Sm 66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	Sm 33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	Sm 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	Sm 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	Sm 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	Sm 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	Sm 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	Sm 66.00
10	1	EXHAUST MOUNTING REAR	\$	Sm 17.82
11	1SET	BOOT FINISHER CLIP	\$	Sm 24.20
12	1	BOOT STICKER "Trans-cab"	\$	Sm 30.00
13	1	BOOT STICKER "6555-3333"	\$	Sm 30.00
14	1	BOOT INNER TRIM CLIP	\$	Sm 45.00
15	1	TAILLAMP CLIP RH	\$	Sm 5.00
16	1	TAILLAMP CLIP LH	\$	Sm 5.00
17	2	REAR WINDSCREEN SELANT	\$	Sm 80.00
18	1	WINDSCREEN MOULDING	\$	Sm 100.00
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Sm 100.00
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm 385.00
21	1	SPARE TYRE	\$	Sm 330.00

TOTAL	\$	2,099.02
TOTAL PARTS	\$	27,834.15

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 2001
To Rust-Proofing Of The Affected Areas.	\$	Sm 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	Sm 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-071

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5478L - TOKIO

To reinstall rear bumper parking sensor.	\$	170.00 <i>bol</i>
To repair and realign rear exhaust pipe.	\$	<i>~</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~</i> 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00 X
Towing Fees	\$	<i>~</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00 X

TOTAL \$ 7,710.00**Over All Total \$ 35,544.15****(PARTS BY PARTS)
Repair Days**

3

10 Days*2 days*

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before and after repair
- To display damaged parts during resurvey
- Parts prices as a guide to repairer
- Third party claims to be on a "Pro-justice" basis
- No illegal methods to be used
- Supplementary claims to be resurveyed and is subject to the approval of Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI17023526/KVBN2

Date: 21/12/2017

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MC012178
Claimant Vehicle No :	SHC5478L	Insured Vehicle No :	SJS3835U
Date of Loss:	07/12/2017	Nature of Claim:	TP
		Claim No:	M1706291

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5478L	Engine No:	M9R8839C002388
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC280962
Reg. Date:	18/12/2014 (Man. Year: 2014)	Odometer:	545383 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,834.13	1,854.57	25,979.56	93.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	480.00	7,230.00	93.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,544.13	2,334.57	33,209.56	93.43
+ GST 7.00/7.00% (S\$)	2,488.09	163.42	2,324.67	93.43
Nett Amount (S\$)	38,032.22	2,497.99	35,534.23	93.43

INSPECTION

Date of Assignment:	12/12/2017	
Date Inspected:	11/12/2017	Inspected At:
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2017)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5478L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Dented/Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*-FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*-FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*-FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*-FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*-FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*-FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*-FL
20	1		*BOOT LOCK	Repair	202.67 FL	*-FL
21	1		*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
22	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*-FL
23	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*-FL
24	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*-FL
25	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*-FL
26	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
27	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
28	1		*TAILLAMP LH	Serviceable	552.55 FL	*-FL
29	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*-FL
30	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*-FL
31	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*-FL
32	1		*EXHAUST REAR	Repair	7,489.05 FL	*-FL
33	1		*EXHAUST CAP REAR	Repair	230.49 FL	*-FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS
44	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
46	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
47	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
48	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
49	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
50	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
51	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*-FS
52	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	*-FS
53	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*-FS
54	1		*SPARE TYRE	Serviceable	330.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	30,693.59	2,042.30
- List Item Discount on L Items 10.00/10.00% (S\$)	2,859.46	187.73
Total Parts (S\$)	27,834.13	1,854.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
10	TOWING FEES	New	120.00	-
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (S\$)			7,710.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >