



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2017 MITSUBISHI OUTLANDER 2.4L 4WD (SFJ302E)

Date of Loss

5 December 2017

Time of Loss

0.50

Loss Description

SFJ302E HIT AGAINST KERB AND POLE

Comment

Workshop Details

Total Rebate Amount

67581

Nett Loss Amount

\$62,419.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

06/05/2018



Days of work completion *

128



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SFJ302E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

06/06/2017



Mileage

11959

Age of Vehicle

0

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2017

ASSESSMENT INFO...

2017

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

Yeo Benedict En Le

CATEGORY Make

POLICY INFORMAT... MITSUBISHI

ASSESSMENT INFO... MITSUBISHI

CATEGORY Model

POLICY INFORMAT... OUTLANDER 2.4L 4WD

ASSESSMENT INFO... OUTLANDER 2.4 CVT 4WD

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JMYXTGF3WHJ000854

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 2 December 1993

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 24

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JMYXTGF3WHJ000854

CATEGORY Engine No

POLICY INFORMAT... 4B12SY1484

ASSESSMENT INFO... 4B12SY1484

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2360

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 130000

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S9347500C

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 17 October 2014

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI... 1 January 2100

POST SURVEY INF... dd/mm/yyyy

CATEGORY	Address
FNOL INFORMATI...	Singapore
POST SURVEY INF...	

CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	

CATEGORY	Gender
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Marital status
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Identification #
----------	------------------

FNOL INFORMATI... S9347500C

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/12/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

3500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/55R18

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/55R18

Front left side

DUNLOP8mm

Front right side

DUNLOP8mm

Rear left side

DUNLOP8mm

Rear right side

DUNLOP8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			Front grille			Cracked	350				350	Reviewing
☐		2	1			Front grille clips (1 set)			Necessary	18				18	Reviewing
☐		3	1			RH front wheel			Damaged	980				980	Reviewing
☐		4	1			RH front shock absorber			Bent	330				330	Reviewing
☐		5	1			RH front shock absorber top mounting			Bent	95				95	Reviewing
☐		6	1			RH front knuckle arm			Bent	220				220	Reviewing
☐		7	1			RH front knuckle arm wheel bearing			Necessary	110				110	Reviewing
☐		8	1			RH front lower arm			Bent	260				260	Reviewing
☐		9	1			Front stabilizer bar			Damaged	180				180	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		10	1			Front stabilizer bar bush (1 set)			Necessary	20				20	Reviewing
		11	1			RH front stabilizer link			Damaged	90				90	Reviewing
		12	1			RH Steering tie rod			Serviceable	0	0	0	0	0	Deny
		13	1			RH Steering tie rod end			Serviceable	0	0	0	0	0	Deny
		14	1			Steering rack and pinion			Damaged	780				780	Reviewing
		15	1			RH drive shaft			Bent	825				825	Reviewing
		16	1			Front cross member			Buckled	950				950	Reviewing
		17	1			RH front fender wheel cowling			Cracked	115				115	Reviewing
		18	1			RH front fender wheel cowling clips (1 set)			Necessary	25				25	Reviewing
		19	1			RH running board garnish			Damaged	350				350	Reviewing
		20	1			Front bumper			Buckled	950				950	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		21	1			Front bumper clips (1 set)			Necessary	28				28	Reviewing
		22	1			Front bumper bottom cover			Damaged	225				225	Reviewing
		23	1			Front bumper bottom cover clips (1 set)			Necessary	25				25	Reviewing
		24	1			Front bumper air grille			Cracked	195				195	Reviewing
		25	1			RH steering tie rod end			Damaged	65				65	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		To remove, install RH front tyre and perform wheel balancing	18	0	0	Reviewing		
		2		To spray paint affected front and side and inner damaged portion inclusive of preparatory works and material	540	0	0	Reviewing		
		3		To set up vehicle on Car-O-Liner system for chassis work according to original vehicle specifications	0	0	0	Reviewing		
		4		To lift up and reinstall engine and ancillary parts to facilitate repairs	0	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		5		To remove damaged parts, to jack out & straighten RH front chassis member, to reshape and repair front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment	600	0	0	Reviewing		
		6		To remove and check RH & LH front suspension system and replace damaged parts.	280	0	0	Reviewing		
		7		To remove and check steering column, rack & pinion, steering tie rods and reinstall components and refill power steering fluid and check for steering functionality	80	0	0	Reviewing		
		8		To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality	20	0	0	Reviewing		
		9		To perform computer diagnostic on drivetrain, ABS systems and clear fault codes	0	0	0	Deny		
		10		To perform computerised wheel alignment	60	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF REPAIR
: 6 DAYS

Reviewing



2

FRONT RIGHT
FENDER

Reviewing

430

MTG CRACKED
(SUPPLEMENTARY)



3

FRONT RIGHT
HEADLAMP ASSY

Reviewing

650

MTG CRACKED
(SUPPLEMENTARY)



4

AXLE OIL

Reviewing

55

NECESSARY
(SUPPLEMENTARY)



5

GRILLE INNER
REINFORCEMENT

Reviewing

110

BENT
(SUPPLEMENTARY)



6

GRILLE INNER
REINFORCEMENT
RIGHT BRACKET

Reviewing

65

DISTORTED
(SUPPLEMENTARY)



7

FRONT BUMPER
REINFORCEMENT

Reviewing

460

BENT
(SUPPLEMENTARY)



EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		8	CVT FLUID	Reviewing	70	NECESSARY (SUPPLEMENTARY)	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$7,124.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,598.00	\$1,598.00
Spare Parts	\$7,186.00	\$7,186.00
Miscellaneous	\$1,840.00	\$1,840.00
Excess	-\$3,500.00	-\$3,500.00

Submit for Review