COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

ACC

VEHICLE NO: SHA 2846M

MAKE :

DATE 11/12/2017 11:25

MODEL	: HYUNDAI i40	DOA	: 09.12.1	7		
Qty	Parts Description/ Labour	Type	Unit Price	A	mount	
	Rear Bumper /	- 71		\$	603.60	
	Rear Bumper Reinforcement ?			\$	504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) -		\$ 180.00	\$	360.00	
	Rear Bumper Side Bracket ?		100.00	\$	49.00	
	Rear Bumper Clips			\$	22.00	
	Rear Bumper Sponge			\$	143.40	
	Rear Bumper Under Cover			\$	225.00	
	Rear Panel X 1990			\$	592.30	
	Rear Panel Garnish			\$	57.70	
	Rear Panel Lower Panel X Fant;			\$	495.50	
	Real Fallet Lowel Fallet 75				475.50	
	CUD TOTAL			\$	3,052.85	1
	SUB TOTAL LESS 20%			\$	610.57	
	DISCOUNTED TOTAL				2,442.28	1
	DISCOUNTED TOTAL			Φ	2,772.20	
	Rear Bumper Reverse Sensor			\$	135.70	Nett
	Rear Bumper Rubber Mat			\$	50.00	
	Real Bumper Rubber Wat				20.00	
				\$	185.70	1
				_	20011,5	1
	Labour Charge				200	
	Panel Beating			\$	380.00	
	Spray Painting Charge			\$	400.00	360
	Wiring Charge			S		12
	R/Refix Reverse Sensor			\$	50.00 120.00	20
	Record Sensor	2		Ψ	12,000	
	TOTAL LABOUR			\$	950.00	1
	ESTIMATE TOTAL			\$	3,577.98	-
		Residence of the last of the l	I Consult		3,377.70	1
	1 / ////	the Re	o Consultants hence not pairer of the following:			
	Calur (CM9	To resu	Vev Delore/after core			
		Parts pr	la damaged part(s) during resultes are subject to continuation	1	- 1	
Larry	19 // 1/2/07 /415600	• Third pa	Ty Survey son a "Make out Desi	Idico" L	2200	
Lamy		No illega Supplement				
	2 /7"	is subject	nentary '-m(s) must be resurvey of to fine approval from Insurance	ed and	1	
	Kalur ((Kly 1/2/17 1415hr), 2 Pm; pp Belove Pix of pho-	Acknowled	ided by Respises	a comp	pany	
	21 0 1 1	Signature:	ged by Re, airer			
	Before Part pro	Date:				
			-1:-1- T1 C 1 ·			1
	This is an initial estimate based on a visual inspection of t					
	be prepared after the vehicle is surveyed by a motor Surve	eyor appoin	ited by the insurance co	mpan	y.	_