



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS17023555/Avbn2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 11-05-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 3719D	Veh. Inspected	SJT 7679Y
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1700734H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JSAEZC31S00204811	Colour	WHITE
Odometer	189197	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/45 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/45 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/45 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/12/2017	Inspection Date	12/12/2017
Survey held at	Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------