


Signature: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bel. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: 2 days Res: Yes or No
 Lum Sum: 2.8-2% 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA1618L Reg: 22 Dec 2016
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Tr / Prime Mover
 Truck / Trailer or
 Make: Hyundai I40 Yr: 1685
 Colour: B/L A/C: 0 Insur: 0 Std / Nil / NA
 Sp Reading: 120742 T Radio Ins: 0 Std / Nil / NA
 Eng No: _____
 C No: KMHCB414MH4097268
 Gen. Cond: Good / 0 / Poor / Burnt
 Steering: In order / 0 / Jammed / Leaked / Burnt or
 Brake: In order / 0 / Jammed / Leaked / Burnt or
 Mod: Nil / B/Rim / 0 / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI
 TOYO / YOKO or Harok.
 Front: _____ Rear: _____
 R.Bal: 7 mm R.Bal: 7 mm
 L.Bal: 7 mm L.Bal: 7 mm
 D.O.A: 8/2/17 D.O: 11/2/17
 Survey held at: COKE (749)
 Des. of Damages: Fnt / Rear / O/S / NS / U/C / Rooftop or
N/S B/L
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
12/1/18 Confirm 2.8-2 \$3295.00 with 2 working day
EQ
11
Ad- \$170.00
5%)

Date Time File Pass to: ☐ : Prel. Report
☐ : Final Report
 Date Time File Return to: _____
 Report Format: _____
 Lump Sum / I.B. / S: _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ Stamped \$
☐ Transport \$
☐ Tech. Fee \$
☐ Workshop \$
 Survey Fee: _____
 Transcription: _____
 Stamp: _____
 Date: _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC3/EQ117023567/K1wb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110		Date : 12-12-2017		
		Code : EQ1		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 3489Z	Veh. Inspected	SHA 1618L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2017	Inspection Date	11/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

To be kept by Security Guard



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQ117023567/K1wb3

Date: 12.12.2017

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA1618L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.12.2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,465.00
Revised Estimate Amount	: S\$	3,295.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305096303

Date : 17.12.2017

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508959
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHA1618L

Date of Accident: 08/12/17

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ YP3489Z

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,465.00

(b) Labour Charges \$830.00

Total for Part-By-Part Repair Cost \$3,295.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Latry No

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 18/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$5.35			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.12.2017

Time: 15:21:00

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305096303
REGN NO : SHA1618L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 22.12.2016
DATE/TIME IN : 09.12.2017 08:50
ACCIDENT DATE : 08.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0781-A	I40V2 LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40
0002	04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	619.00	20.00	495.20
0003	04-01-0103-0600-G	I40VC MIRROR ASSY-O/S REA	1	980.50	20.00	784.40
0004	28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00		75.00

SUB-TOTAL : 2,465.00

JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	410.00
0002 17-01	WIRING CHARGE	20.00

SUB-TOTAL : 830.00

TOTAL : 3,295.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

IR ESTIMATE*

VEHICLE NO : SHA 1618L

DATE 9/12/2017 11:37

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin - Pbyl
EQ INS

Larry

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) — <i>brake</i>			\$ 1,388.00
	Front Fender (LH) — <i>brake</i>			\$ 619.00
	Front Door Mirror (LH) — <i>va</i>			\$ 980.50
	SUB TOTAL			\$ 2,987.50
	LESS 20%			\$ 597.50
	DISCOUNTED TOTAL			\$ 2,390.00
	Front Door Comfort Logo (LH) <i>* — va</i>			\$ 75.00 Nett
	Labour Charge			<i>400</i>
	Panel Beating			\$ 450.00
	Spray Painting Charge			\$ 500.00 <i>410</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 3,465.00

Kalvin LKK/4
 11/2/17 1615hrs
 2 Pys.
 P/P
 Before Paint p/h

Larry Ng

LKK/4
 the
 • To
 • To
 • Parts
 • Third
 • Sub
 is subject to
 Approved
 Special

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE*

DATE 9/12/2017 11:37

MODEL : HYUNDAI i40

[illegible]

Shu Pei (LKKAuto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Wednesday, 13 December, 2017 10:49 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Vivian Lau (LKKAuto); Zaini (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving YP3489Z (OI : EQI - TBA) AND SHA1618L (TP : LKK REF - CC3/EQI17023567/K1wb3) on 08.12.2017
Attachments: OI - YP3489Z.PDF

Dear Shu Pei,

Attached a copy of our insured's GIA report for your perusal.

Regards,

Elaine Cheong
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MID Complex Singapore 069110
did 65-6500 8772 | tel 65 6223 9433 ext.772 | fax 65-62234190
www.eqinsurance.com.sg

 A Member of Coystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKKAuto) [mailto:shupel@lkkauto.com]
Sent: Tuesday, December 12, 2017 7:08 PM
To: Elaine Cheong
Cc: Admin A; Vivian Lau (LKKAuto); Zaini (LKK Auto)
Subject: Direct Settlement - Accident Involving YP3489Z (OI : EQI - TBA) AND SHA1618L (TP : LKK REF - CC3/EQI17023567/K1wb3) on 08.12.2017

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHA 1618L at M/s ComfortDelGro Engineering Pte Ltd - Loyang.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

COMFORTDELGRO ENGINEERING

Our Ref : T 1217 / SHA1618L /JW(st)
Your ref :
Date : 05-Jan-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 108506048W

EQ Insurance Company Limited
5 Maxwell Road, MND Complex
#17-00 Tower Block
Singapore 069110

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHA1618L YOUR INSURED YP 3489Z
AND OTHER ON 08.12.17**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHA1618L which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving YP 3489Z we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 3,525.65
2	4 days Loss of Rental @ \$ 125.00 per day	\$ 500.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 5.35
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation Fees	-
Sub Total :		\$ 4,031.00

HIRER'S CLAIM

7	4 days Loss of Income @ \$ 80.00 per day	\$ 320.00
Total Claims:		\$ 4,351.00

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 6 pcs.
b) LTA search slip/s of : YP 3489Z
c) GIA / Police report/s of : SHA1618L
d) Letter of authority from owner / hirer / operator
() Witness statement/s () Towing/Medical bill/receipts () Certificate of Insurance
(X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Jim Wong

Deputy Manager

CDGE Claims Department

Tel : 6214 8374 Fax: 6214 1843 Email : jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/EQ117023567/K1wb3

18 December 2017

FortyTwo Pte Ltd
5 Toh Guan Road East
05-01
Singapore 608831

Dear Sir/Madam,

ACCIDENT INVOLVING YP 3489Z AND SHA 1618L ON 08/12/2017

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****I 40 SHA1618L , YP3489Z****ON 08-Dec-17 12:45****CAIRNHILL RD TWDS ORCHARD RD/GRANGE RD BESIDE
CHATSWORTH INTERNATIONAL SCHOOL**

I / We

LIEN FOOK HIN(Hirer) NRIC No.: **S1223363I**

and/or

(Relief) NRIC No.:

Taxi Number

SHA1618L

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

09-Dec-2017

Name of Hirer

LIEN FOOK HIN

Hirer NRIC

S1223363I

Signature :



Address

**503 JELAPANG ROAD #16-366
670503**

Contact No.

83092328

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010325

EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SHA1618L

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
22.12.2016

CHASSIS CODE
KMHLB41UMHU097268

INV. NO/DATE
91348434 28.12.2017

JOB NO.
305096303

ODOMETER READING

DATE/TIME IN
09.12.2017 08:50

Description : 3P 08.12.2017

S/No	Part No.
------	----------

Qty	Unit Price	%Disc	Net
-----	------------	-------	-----

PART REQUISITION

0001	04-01-0103-0781	I40V2 LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40
0002	04-01-0103-0574	I40VC PANEL-FENDER LH#	1	619.00	20.00	495.20
0003	04-01-0103-0600	I40VC MIRROR ASSY-O/S REA	1	980.50	20.00	784.40
0004	28-01-0103-0003	(I40)FRT DOOR LOGO SONATA	1	75.00	0.00	75.00
SUB-TOTAL				:		2,465.00

JOB NATURE

0001	L	PANEL HEATING	400.00	400.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	410.00	410.00
0003	17-01	WIRING CHARGE	20.00	20.00
SUB-TOTAL			:	830.00

ComfortDelGro Engineering Pte Ltd
Member of COMFORTDELGRO

d Office:
Braddell Road
Singapore 570701

ly note that no receipt shall be issued unless requested

STOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91348434	3,525.65	

GST REG. NO. M2-8921817-3

TAX INVOICE

8010325

EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SHA1618L

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
22.12.2016

CHASSIS CODE
KMHLB41UMHU097268

INV. NO/DATE
91348434 28.12.2017

JOB NO.
305096303

ODOMETER READING

DATE/TIME IN
09.12.2017 08:50

Items total		3,295.00
Add GST @	7.000 %	230.65
Invoice amount		3,525.65

Issued by : CHEWBEELENG 28.12.2017 13:21:41
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ
8010325	91348434	3,525.65	

Our Ref: CT17120267

Date: 19 December 2017



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	08/12/2017 @ 12:45 hrs
ALONG	CAIRHILL ROAD TWDS ORCHARD RD
INVOLVING	YP3489Z

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA1618L** (the "Taxi"). The Taxi was hired to **LIEN FOOK HIN IC NO S1223363I** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

VSTA 1618 L

SHA 1618 L

DATE	HOURS OPERATED (TIME)		NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO							FROM	TO
8/12	7am	4.30	REK	120	362	264		7am	5pm	
8/12	8am	3pm	REK	120	697	337		1725	0610	
09.12.17	9am	11.30	ACCIDENT			10		0850	-	
12.12.17	7am	4pm	REPAIR			007		-	1200	
17.10.	7am	0300								
	7am	430								
6	1715	2320								
	7am	440								
	0520	0130								
	7am	5pm								
	5:30pm	3am								

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
YP3489Z	08 Dec 2017 / 12:45:00	Successful	E04	EQ INSURANCE COMPANY LTD

[Previous](#) [OK](#)

SHALIEL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/01/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YP 3489Z (Insd Veh)	Your Ref. No. : DMCPHQ17-003949
	SHA 1618L (TP Veh)	Our Ref. No. : CC3/EQI17023567/K1wb3q2
Date of Accident	8/12/2017	

Liability	100%	
Final Repair Cost	: \$ 3,525.65	
Loss of Income	: \$ 175.00	3.5 days
Rental (If any)	: \$ 437.50	3.5 days
Others:	: \$ 5.35	
	: \$	
	4,143.50	
Final Settlement Sum	: \$ 4,100.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 4,100.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ117023567/K1wb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-01-2018



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3489Z	Veh. Inspected	SHA 1618L
Policy No.	DMCPHQ17-003949	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMHU097268	Colour	BLUE
Odometer	120742	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/12/2017	Inspection Date	11/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1618L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP (LH)	GRAZED	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	619.00	619.00
1	FRONT DOOR MIRROR (LH)	CRACKED	980.50	980.50
	LESS 20% DISCOUNT		-597.50	-597.50
			2,390.00	2,390.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	PANEL BEATING .		450.00	400.00
	SPRAY PAINTING CHARGE .		500.00	410.00
	WIRING CHARGE.		50.00	20.00
			1,000.00	830.00
GRAND TOTAL			3,465.00	3,295.00
RECOMMENDED COST OF REPAIRS				3,295.00

Report Ref No. CC3/EQ117023567/K1wb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.