

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1205/2017/JT  
**Date** : 8-Dec-17

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Vats Aditya  
**Address** : 1 Rhu Cross  
#04-04  
Singapore 437431  
**Telephone** : HP +65 9437 5451  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 210044734-01000  
**Vehicle No** : **SFM 3228 B**  
**Model Code** : Audi A6 C7 2.0 TFSI Mu  
**Model / Year** : Aug-11  
**Engine No** : CHV 003149  
**Chassis No** : WAUZZZ4G1BN021029  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 7-Dec-17  
**Place of Accident** : Costa Rhy Condo - 437431

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SFM 3228 B.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function. Reinstall all parts removed.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper assy. Reorganize rear crash management components. Reinstall all parts removed.	\$ <del>1,050.00</del> 500.	
3	To respray rear bumper.	\$ <del>900.00</del> 550	
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SFM 3228 B.

S/N	Parts Description	<u>Damaged Parts &amp; Prices</u>	
		S/Nett	Remark
1	REAR BUMPER <i>del</i>	\$ 2,131.00	✓
2	REAR BUMPER SPOILER <i>3 new</i>	\$ 283.00	+
3	REAR REINFORCEMENT BEAM	\$ 818.00	+
4	REAR PARKING AID SENSOR <i>3 new</i>	2 \$ 415.00	+
5	PARKING AID SENSOR WIRING SET	\$ 584.00	+
6	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 4,531.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 7,033.00	

All charges are not inclusive of GST.

Legend :      Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Adrian Lj

Surveyed Date

: 12/12/17.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 03 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant