

REF:

CC3 / A2617023569 / Avb2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

2100 447934

Claims No. _____

Sum Insured: _____

Excess: _____

1000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

75K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

3

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SFM3228B

Yr Regn: 2011 August

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Audi A6

C.C. 2773

Colour _____

Black.

A/O: Insured / Std / NI / NA

Sp. Reading _____

89033

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAUZZZ461BN021029.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt or _____Brake: ☒ In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: _____

F: _____

245/45R18

R: _____

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Continental

Front _____

Rear _____

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

7/12/17

D.O.I. _____

12/12/17

Survey held at _____

Premium

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A/G.

SFM 3228B - CC3 / A2617023569 / GVN

DOA: 040112

11/1/18 Email Kee Siang vehicle ex \$1000/2

19/3/18 Final lg \$3340.88 (Red 3692.12, 5270) Confirmed by email

RECEIVED 20 MAR 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 23/3-tylist

Report Format: _____

merimen

Lump Sum / I.B.I.: (\$ _____)

3340.88

Days Of Repair: _____

3

Resurvey No. of Trip: _____

-

Survey Fee: _____

Transportation _____

S - RS _____

Photos _____

Others _____

Add Fee: _____



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Insp (\$ _____)



Weekend (\$ _____)

TOTAL

200

10

210

Survey Department Check List (Case Handler)

Reference No.: C3/A1617023569/Avb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)				
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 19/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17023569/Avb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 12-12-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SFM 3228B
Policy No. 2100447934	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date 07/12/2017	Inspection Date 12/12/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 11 January, 2018 5:44 PM
To: 'Claims Department'
Cc: SUR
Subject: RE: SFM 3228B-DOA: 7/12/2017 (AIG OD):

Dear Kee Siang,

Vehicle excess \$1000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 11 January, 2018 5:19 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SFM 3228B-DOA: 7/12/2017 (AIG OD):

Dear Veron,

Attached LTA for your perusal.

Kindly confirm for excess amount.

Thank you

Best Regards,
Claims Advisor

Kee Siang

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road | Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 m. +65 8777 0600

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 10 January, 2018 3:58 PM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: RE: SFM 3228B-DOA: 7/12/2017 (AIG OD):

Dear Jeffery,

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 December, 2017 10:32 AM
To: claims@premiumauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SFM 3228B-DOA: 7/12/2017 (AIG OD):

Dear Jeffery,

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 13 December, 2017 8:04 AM

To: claims@premiumauto.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: SFM 3228B-DOA: 7/12/2017 (AIG OD):

Dear Jeffery,

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	1624P
Vehicle Details	
Vehicle No.:	SFM3228B
Vehicle to be Exported:	Yes
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.8 FSI MU
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CHV003149
Chassis No.:	WAUZZZ4G1BN021029
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$47,917.00
Original Registration Date:	31 Aug 2011
First Registration Date:	31 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$47,917.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2021
PARF Rebate Amount:	\$31,146.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2021
COE Category:	B - Car (1601cc & above)

11/01/2018

PARF/COE Rebate Enquiry

COE Period(Years):	10
QP Paid:	\$68,501.00
COE Rebate Amount:	\$24,896.00
Total Rebate Amount:	\$56,042.00

The information contained herein is correct as at 11 Jan 2018

OK



CERTIFICATE OF INSURANCE

M.X.1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

AUTOPLAN

CERTIFICATE NO. 2100447934-01000

OWN DAMAGE EXCESS S\$1000.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PAF Yes
SFM3228B

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

VATS ADITYA

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

1 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

28 Feb 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :35 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118)
2. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
3. Ethoz - 30 Bukit Batok Cres(Tel:66547777)
4. DPS Body & Paint (Subsidiary of C & C) - 209 Pandan Gardens (Tel: 65684501)
5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss of Use 10 Days (1600cc) - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 8 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

504398-000
PRIVILEGE CAPITAL PTE LTD
MAPEX BUILDING
37 JALAN PEINIMPIN #01-01
SINGAPORE 577177

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPVKM

REPUBLIC OF SINGAPORE DRIVING LICENCE

Exemption Number **G5931624P**

Name **VATS ADITYA**

Birth Date **05 Jun 1979**

Issue Date **03 Jan 2012**

Valid Till **02 Jan 2017**

002031099D



EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
ORACLE CAPAC SERVICES (SINGAPORE BRANCH)

Name
VATS ADITYA

Occupation
INFORMATION TECHNOLOGY BUSINESS PARTNERING DIRECTOR

FIN
G5931624P

Date of Application
07-02-2017

Date of Issue
28-02-2017

Date of Expiry
28-04-2020





L7677944

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 28 Motorcycles <= 200 cc 03 Jan 2012

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 03 Jan 2012

NP 42BA

Licence No: G5931624P



VISIT PASS
Immigration Regulations

Name
VATS ADITYA

Date of Birth **05-06-1979** Sex **M** Nationality **INDIAN**

FIN **G5931624P** Date of Issue **28-02-2017** Date of Expiry **28-04-2020**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.






**SINGAPORE
POLICE FORCE**

**TRAFFIC POLICE
SINGAPORE POLICE FORCE
10, UBI AVENUE 3
SINGAPORE 408865
Tel : 65470000
www.police.gov.sg**

Private & Confidential

VATS ADITYA

APT BLK 1 RHU CROSS #04-04
COSTA RHU SINGAPORE 437431

You will receive your photocard driving licence by registered post within 10 ~~15~~44 working days from the date of application unless you made a special request to collect at Traffic Police at the time of application

You can drive while awaiting the delivery of your photocard driving licence

Please turn overleaf for important notes.

G5931624P
(2B/3)

C001310860

\$50/-

(Please do not detach)

**YOU CAN DRIVE WHILE AWAITING THE
DELIVERY OF YOUR PHOTOCARD
DRIVING LICENCE**

07/12/2017

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1205/2017/JT
Date	:	8-Dec-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Vats Aditya
Address	:	1 Rhu Cross #04-04 Singapore 437431
Telephone	:	HP +65 9437 5451
Type of Claim	:	Own Damage Claims
Policy No.	:	210044734-01000
Vehicle No	:	SFM 3228 B
Model Code	:	Audi A6 C7 2.0 TFSI Mu
Model / Year	:	Aug-11
Engine No	:	CHV 003149
Chassis No	:	WAUZZZ4G1BN021029
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Dec-17
Place of Accident	:	Costa Rhy Condo - 437431

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFM 3228 B.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function. Reinstall all parts removed.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500 ✓	✓
3	To respray rear bumper.	\$ 900.00 550 ✓	✓
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFM 3228 B.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del</i>	\$ 2,131.00	✓ 1704.50
2	REAR BUMPER SPOILER <i>3 new</i>	\$ 283.00	+
3	REAR REINFORCEMENT BEAM	\$ 818.00	+
4	REAR PARKING AID SENSOR <i>3 new</i>	2 \$ 415.00	+
5	PARKING AID SENSOR WIRING SET	\$ 584.00	+
6	SUNDRIES <i>2 new</i>	\$ 300.00	34.05
TOTAL SPARE PARTS CHARGES		\$ 4,531.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 7,033.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 12/12/17.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 19 March 2018 9:16 AM
To: 'Boo seng yak'; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION SFM3228B - OD AIG - SURVEYED 12 DEC 17

Dear Mr Boo,

Confirm repair cost of \$3,340.88 before excess \$1000 and GST @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Saturday, 17 March 2018 3:41 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION SFM3228B - OD AIG - SURVEYED 12 DEC 17

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3340.88 @ 3 days of repairs.

your early closure is appreciated.

best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1205/2017/JT
Date : 8-Dec-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb 17 mar 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Vats Aditya
Address : 1 Rhu Cross
#04-04
Singapore 437431
Telephone : HP +65 9437 5451
Type of Claim : Own Damage Claims
Policy No. : 210044734-01000
Vehicle No : **SFM 3228 B**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Aug-11
Engine No : CHV 003149
Chassis No : WAUZZZ4G1BN021029
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Dec-17
Place of Accident : Costa Rhy Condo - 437431

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFM 3228 B.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function. Reinstall all parts removed.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
3	To respray rear bumper.	\$	900.00	\$ 550.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,502.00</u>	<u>\$ 1,602.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFM 3228 B.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,131.00	\$ 1,704.80
2	REAR BUMPER SPOILER	\$ 283.00	
3	REAR REINFORCEMENT BEAM	\$ 818.00	
4	REAR PARKING AID SENSOR	2 \$ 415.00	
5	PARKING AID SENSOR WIRING SET	\$ 584.00	
6	SUNDRIES	\$ 300.00	\$ 34.08
TOTAL SPARE PARTS CHARGES :		\$ 4,531.00	\$ 1,738.88
TOTAL LABOUR CHARGES		\$ 2,502.00	\$ 1,602.00
GRAND TOTAL		\$ 7,033.00	\$ 3,340.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFM 3228 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1205/2017/MAS

23 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SFM 3228 B, Audi A6 C7 2.8 FSI MU

With reference to the above-mentioned vehicle, no **SFM 3228 B**, claimant,
Mr. Vats Aditya, please find the related document per attached.

1. A copy of the Original invoice no. 85012266 – S\$2,504.74
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SFM 3228 B

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017		12 Dec 2017 15:48 Edit Adj Rpt	S\$3,340.88 Edit Estimates	S\$3,340.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: VATS ADITYA, ID: G5931624P, Tel: +6594375451, Email: ADITYAVATS11@GMAIL.COM

Vehicle Reg. No.: SFM3228B **Date of Loss:** 07/12/2017 13:00 - :59

Claim Type: OD / 0550736328SG **Policy/Cover Note No.:** 2100447934-01000 (Comprehensive)

Excess: S\$1,000.00

Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing]
TongShing.Loo@aig.com

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/12/2017]

Driver/Custodian: VATS ADITYA (38 / Male), NRIC: G5931624P, Tel: +6594375451

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (13/12/2017): SFM3228B / OD / 07/12/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFM3228B (0550736328SG)**
OD
Dec 7 2017 1:50PM
[VATS ADITYA]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	13/12/17 08:24	General View		Load JPG	☒		
2	13/12/17 08:24	General View		Load JPG	☒		
3	13/12/17 08:24	General View		Load JPG	☒		
4	13/12/17 08:24	General View		Load JPG	☒		
5	13/12/17 08:24	General View		Load JPG	☒		
6	13/12/17 08:24	General View		Load JPG	☒		
7	13/12/17 08:24	General View		Load JPG	☒		
8	13/12/17 08:24	General View		Load JPG	☒		
9	13/12/17 08:24	General View		Load JPG	☒		
10	13/12/17 08:24	General View		Load JPG	☒		
Documentation						1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	13/12/17 08:32	Singapore Accident Statement		Load PDF			
2	13/12/17 08:32	Certificate of Insurance		Load PDF			
3	13/12/17 08:32	ESTIMATE		Load PDF			
4	13/12/17 08:33	Drivers Driving License		Load PDF			
5	26/03/18 16:45	WORKSHOP INVOICE		Load PDF			
6	26/03/18 16:45	DISCHARGE VOUCHER		Load PDF			

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	07/12/17 16:19	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	07/12/17 16:17	Accident Photo		Load JPG
2	07/12/17 16:17	Accident Photo		Load JPG
3	07/12/17 16:17	Accident Photo		Load JPG
4	07/12/17 16:17	Accident Photo		Load JPG
5	07/12/17 16:17	Accident Photo		Load JPG
6	07/12/17 16:17	Accident Photo		Load JPG
7	07/12/17 16:17	Accident Photo		Load JPG
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	07/12/17 16:07	Sketch Plan		Load JPG
2	07/12/17 16:07	Sketch Plan #2		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17023569/AVBN2

Date: 26/03/2018

REFERENCE

Insured/Claimant: VATS ADITYA Policy No: 2100447934-01000
Date of Loss: 07/12/2017 Nature of Claim: OD Claim No: 0550736328SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFM3228B
Make & Model: AUDI A6, 2.8 FSI MU (A) Engine No: CHV003149
Reg. Date: 31/08/2011 (Man. Year: 2011) Chassis No: WAUZZZ4G1BN021029
Colour: Black Odometer: 89033 km
Engine Capacity: 2773 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,531.00	1,738.88	2,792.12	61.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,033.00	3,340.88	3,692.12	52.50
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	6,033.00	2,340.88	3,692.12	61.20
+ GST 7.00/7.00% (S\$)	422.31	163.86	258.45	61.20
Nett Amount (S\$)	6,455.31	2,504.74	3,950.57	61.20

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 12/12/2017 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,131.00 FS	*1,704.80 FS
2	1		*REAR BUMPER SPOILER	Not Necessary	283.00 FS	*- FS
3	1		*REAR REINFORCEMENT BEAM	Not Necessary	818.00 FS	*- FS
4	2		*REAR PARKING AID SENSOR	Not Necessary	415.00 FS	*- FS
5	1		*PARKING AID SENSOR WIRING SET	Not Necessary	584.00 FS	*- FS
6	1		*SUNDRIES	Necessary	300.00 FS	*34.08 FS
Total Parts (S\$)					4,531.00	1,738.88

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.REINSTALL ALL PARTS REMOVED	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY.RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >