

INS. CASE OWNER:

CC 6 /AIG1702 3570, Uluwatu

LKK:

IDAC:

Surveyor:

Marcus

DOI:

ASSIGNMENT

12/12/17

Date / Time:

Registered in Merimen:

12/12/17
12/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJF 7576L

Name of Insured:

NAJEEB OMAR THAB

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A.:

12/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: NAJEEB NAJEEB THAB

Driver Tel No.:

(VA YES / NO)

Claim No.:

6962704154

Policy No.:

2100369456-03000

Make / Model:

MAZDA

Place of Accident:

PIE TWS THAS

OIGIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SR 5404F

INSRS:
WSP:
Tel:
Liability:
RMKS:

pmpms

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US

SS

5,400.00 (7 days)

Reduction:

42 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Total Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

SS

5,783.00

COLD (RENT-ENDED TP)

Loss of Rental (LOR):

SS

—

(days)

Loss of Use (LOU):

SS

—

(\$ x days)

Loss of Income (LOI):

SS

—

(\$ x days)

LOI only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

LTA Search

SS

555

Medical:

SS

—

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

—

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

—

3) Survey fee:

\$ 320.00

Total:

SS

5,783.35

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5,783.35

Name 1:

PERKINS ENGINEERING & TRADING PTB LTD

Payee 2: (Strike if N.A.)

SS

—

Name 2:

Payee 3: (Strike if N.A.)

SS

—

Name 3:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023570/Uhb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-12-2017	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJF 7575L	Veh. Inspected	SLR 8509K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/12/2017	Inspection Date	12/12/2017
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT, WESTVILLE SINGAPORE 648541		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Messrs Grab Rentals Pte Ltd

Estimate To Repair Honda Vezel Hybrid 1.5X Auto
Vehicle No : SLR8509K
Chassis No : RU31253162

Third Party Insurer : AIG
Insured's Veh No : SJF7575L
Date of accident : 09.12.2017

Date: 11.12.2017

req: Lkk marcus.
12.12.2017 @ 0925h

Pages: 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	tailgate lid	\$ 953.30	\$ 953.30
2	1 pc	tailgate lid lock top	\$ 180.00	\$ 180.00
3	1 pc	tailgate lid lock top strike bottom	\$ 24.75	\$ 24.75
4	1 pc	tailgate lid weatherstrip	\$ 135.00	\$ 135.00
5	1 pc	tailgate lid "Vezel" badge	\$ 56.30	\$ 56.30
	1 pc	tailgate lid "hybrid" badge	\$ 66.20	\$ 66.20
7	1 pc	n/s tailgate lid reflector	\$ 43.20	\$ 43.20
8	1 pc	tailgate lid inner trimboard	\$ 225.00	\$ 225.00
9	2 ps	tailgate lid rubber stopper	\$ 22.50	\$ 45.00
10	2 ps	tailgate hinge	\$ 26.00	\$ 52.00
11	1 pc	tailgate lid keyless sensor	\$ 85.60	\$ 85.60
12	2 ps	tailgate lid damper	\$ 18.00	\$ 36.00
13	1 pc	rear windshield glass weatherstrip	\$ 120.00	\$ 120.00
14	1 pc	rear end panel	\$ 514.00	\$ 514.00
15	1 pc	rear end panel inner trim	\$ 92.30	\$ 92.30
16	6 ps	rear end panel inner trim clips	\$ 4.30	\$ 25.80
17	1 pc	rear luggage floor panel	\$ 597.00	\$ 597.00
18	1 pc	rear luggage floor inner trimboard	\$ 190.00	\$ 190.00
19	1 pc	rear luggage floor compartment tray	\$ 1,130.00	\$ 1,130.00
20	1 pc	rear bumper centre	\$ 762.20	\$ 762.20
21	2 ps	rear bumper reflector	\$ 141.00	\$ 282.00
22	2 ps	rear bumper screw spacer	\$ 12.00	\$ 24.00
23	1 pc	n/s rear bumper side	\$ 95.00	\$ 95.00
24	2 ps	rear bumper side retainer	\$ 23.00	\$ 46.00
25	10 ps	rear bumper clips	\$ 3.90	\$ 39.00
26	1 pc	rear bumper diffuser cover	\$ 95.00	\$ 95.00
27	8 ps	rear bumper diffuser cover clips	\$ 3.50	\$ 28.00
28	1 pc	n/s rear lamp	\$ 542.00	\$ 542.00
29	3 ps	rear lamp clip holder	\$ 4.50	\$ 13.50
Less 20%				\$ 6,498.15
				\$ 1,299.63
				\$ 5,198.52
Balance C/F				\$ 5,198.52

Less 20%

Balance C/F

Let's Auto Consultants hence notify the Repaired of the following:

- To resurvey before after spray painting.
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51-Defu Lane-10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date: 11.12.2017

Estimate To Repair : Honda Vezel Hybrid 1.5X Auto
Vehicle No : SLR8509K
Chassis No : RU31253162

2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 5,198.52
		<u>SPECIAL NETT ITEMS</u>		
30	1 pc	rear windshield glass sealant	\$ 180.00	\$ 180.00
31	1 pc	rear windshield glass inner sponge seal	\$ 100.00	\$ 100.00
32	1 set	rear bumper centre parking sensor	\$ 450.00	\$ 450.00
33	1 pc	rear license plate	\$ 80.00	\$ 80.00
34	1 pc	rear luggage floor panel insulation	\$ 200.00	\$ 250.00
				\$ 880.00
		<u>LABOUR & MISC. CHARGES</u>		
1		To check electrical lighting concerned.	30	\$ 40.00
2		To rust-proofing of the affected areas.	80	\$ 120.00
3		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	11	\$ 550.00
4		To reinstall of rear bumper parking sensor.	50	\$ 120.00
5		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	80	\$ 120.00
6		To transfer of tailgate fittings, fixture and perform waterseepage test.	60	\$ 120.00
7		To remove and refit rear windscreen glass.	120	\$ 150.00
8		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	1200	\$ 1,600.00
9		Putty and spray painting of the affected portion.	900	\$ 1,000.00
				\$ 3,820.00
		Grand Total	2790	\$ 9,268.52

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Vic (LKKAUTO)

From: Pegasus Engineering <claims@pegasusengrg.com.sg>
Sent: Tuesday, 3 July, 2018 8:45 AM
To: Vic (LKKAUTO)
Subject: Re: LOD - THIRD PARTY CLAIM - SLR8509K YOUR REF : SJF7575L ON 09.12.2017
Attachments: 03072018084759.pdf

Without Prejudice

Dear Vic,

Enclosed the signed DV for your process of payment.

Thanks & Regards,

Sharon Ow
Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

On Mon, Jul 2, 2018 at 5:53 PM, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Sharon,

We refer to your below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we offer below to settle your client's claim.

Cost of Repair (w/gst)	\$	5,778.00
Loss of Rental (\$66.95 x 6 day)	\$	5.35
TOTAL	\$	5,783.35

If agreeable, kindly chop and sign the attached DV then forward back to us a copy for payment processing.

The above amount is to be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Friday, 4 May, 2018 12:03 PM

To: Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO); Vivian Lau (LKKAUTO)

Subject: LOD - THIRD PARTY CLAIM - SLR8509K YOUR REF : SJF7575L ON 09.12.2017

Dear All,

Refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

Please reply.

Thanks & Regards,

Sharon Ow

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

**GREAT AMERICAN INSURANCE COMPANY**

UEN: T15FC00298 GST REG. NO.: M90370081T
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: +65 6804 6000
FAX: +65 6235 2616

MOTOR COVER NOTE: MTGRAB20172143

The Insured mentioned in this Covernote, having proposed for insurance in respect of the Motor Vehicle described, is hereby HELD COVERED under the terms of the Insurer's usual form of Motor Policy applicable thereto for the period mentioned unless the cover be terminated by the Insurer by notice in writing in which case the Insurance will thereupon cease and a proportionate part of the annual premium payable for such Insurance will be charged for the time the Company has been on risk.

The Insurer	: GREAT AMERICAN INSURANCE COMPANY
The Insured	: Grab Rentals Pte. Ltd.
Insured Nric/Passport No/ RoC	: 201617200G
Policy Coverage	: Comprehensive
Make And Description Of Vehicle	: Honda Vezel 1.5 X Hybrid
Vehicle Registration No.	
Year Of Manufacture	: 2017
Engine No.	: LEB5953170
Chassis No.	: RU31253162
Engine Capacity/ Tonnage/ Seater	: 1496 cc
Hire Purchase	: Malayan Banking Berhad
Value (\$\$)	: Market Value of Insured Vehicle at Time of Loss
Period Of Insurance	: From 02/08/2017 to 01/08/2018
Excess (\$\$)	: All Claims Excess - S\$2,000.00 Windscreen Excess - S\$100.00
Great American Authorised Workshop	: Authorised Workshop

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA)

Note: This Cover Note is only valid for 60 days from the date of issuance unless replaced by the Certificate of Insurance issued by the Company.

For and on behalf of Great American Insurance Company

Great American Insurance Company
Authorised Signatory

Date of Issue : 01/08/2017

Intermediary : Citrine Systems (S) Pte Ltd (Grab Leasing)

MTR/COVERNOTE/V02/16



9A Lok Yang Singapore 628628
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508
Fax: 6858 0877

Our Ref SM 14612 2017
Your Ref SJF 7575L

Date 04/05/2018

WITHOUT PREJUDICE

Claims Department -Executive In Charge
AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SLR 8509K / SJF 7575L ON 09.12.2017
(Pte Hire)

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/ _____ copies of photographs _____
☒ Original Tax-invoice number 1118/04-1163 ☐ police report / police result
☒ Certificate Of Insurance _____ ☒ Vehicle search result
☒ Authorization To Act - Owner/Hirer ☐ _____

*Survey under insurance instruction / Independent surveyor / No survey.

a)	Cost of repair (inclusive GST)	\$ <u>5,778.00</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>5.35</u>
d)	Loss of rental _____ days @ \$ _____	\$ <u>-</u>
e)	Loss of earnings /rental fees _____ days @ \$ _____	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>500.00</u>
g)	_____	\$ <u>-</u>
	Total	\$ <u>6,283.35</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Ouw

Email: claims@pegasusengng.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

19 DECEMBER 2017

**NAJEEB OMAR TALIB
257 ARCADIA ROAD
#02-03
SINGAPORE 289851**

By Post and By Email

Dear Sir/Madam,

**OUR REF : CC6/AIG17023570/Uhb3
YOUR REF : SJF 7575L
ACCIDENT INVOLVING SJF 7575L AND SLR 8509K ALONG PIE TOWARDS TUAS
ON 09.12.2017**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLR 8509K against your motor insurance policy.

Based on the accident report and accident scenario and all available information at hand, it was reported that your vehicle had rear-ended to the Third-Party vehicle SLR 8509K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

c.c. notalib@singnet.com.sg / zaktalib@yahoo.com.sg
(By Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 19 December, 2017 9:57 AM
To: notalib@singnet.com.sg
Cc: zaktalib@yahoo.com.sg; Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SJF 7575L_ACCIDENT INVOLVING SJF 7575L AND SLR 8509K ALONG PIE TOWARDS TUAS ON 09.12.2017



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

19 DECEMBER 2017

NAJEEB OMAR TALIB
257 ARCADIA ROAD
#02-03
SINGAPORE 289851

By Post and By Email

Dear Sir/Madam,

OUR REF : CC6/AIG17023570/Uhb3
YOUR REF : SJF 7575L
ACCIDENT INVOLVING SJF 7575L AND SLR 8509K ALONG PIE TOWARDS TUAS ON 09.12.2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLR 8509K against your motor insurance policy.

Based on the accident report and accident scenario and all available information at hand, it was reported that your vehicle had rear-ended to the Third-Party vehicle SLR 8509K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLR 8509K

ACCIDENT INVOLVING SJF 7575L

ALONG/AT PTE towards Tuas ON 09.12.2017

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 2016172006

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 03.05.2018

Signature



Owner

3/27 - 2017 Vic

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PEGASUS ENGINEERING & TRADING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$5,778.00** (Repair Cost), **S\$-** (Loss of Rental/Use), **S\$5.35** (Disbursement), for vehicle no. **SLR 8509K** that was damaged pursuant to the accident which occurred on **09/12/2017** (date) along **PIE TOWARDS TUAS** (location) involving vehicle no/s **SJF 7575L**. This is pursuant to the inspection conducted on **12/12/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRAB RENTALS PTE LTD** ("the third-party claimant") of vehicle no. **SLR 8509K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLR 8509K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 05 (day) of July (month) **2018** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Vehicle Model : HONDA VEZEL HYBRID 1.5X AUTO
Vehicle No : SLR8509K
Chassis No : RU3-1253162

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : SJF7575L
Date of accident : 09.12.2017

Tax Invoice No : IV18/04-1163
Invoice Date : 21.04.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 5,400.00
Sub Total	\$ 5,400.00
GST (7.00%)	\$ 378.00
Total	\$ 5,778.00

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD



Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusengrg.com.sg

Enquire Vehicle & Owner Information (Vehicle No. SJF7575L As At 09 Dec 2017 / 18:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SLR8509K

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1024913I

Owner Name: NAJEEB OMAR TALIB

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 257

Registered Street Name: ARCADIA ROAD

Registered Unit No.: # 02 - 03

Registered Building Name: -

Registered Postal Code: 289851

Current Vehicle Details

Vehicle No.: SJF7575L

Make Description/Model: MAZDA / MX5 2LA RHT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Print

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017 Edit Reg		12 Dec 2017 00:00 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NAJEEB OMAR TALIB , ID: -									
Main Claimant: GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G									
Vehicle Reg. No.: SLR8509K		Date of Loss: 09/12/2017 16:00 - :59 [3 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6962370412SG		Policy/Cover Note No.: 2100369956-03000 (Comprehensive)							
Vehicle Reg. No. (Insured): SJF7575L		Policy No. (Claimant):							
		Excess:							
Repairer: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: Great American Insurance Company (HQ) - Tel: 6804 6047									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/12/2017]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (14/12/2017): Re: Confirmation of Vehicle number AIG_SG (13/12/2017): Confirmation of Vehicle number 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR8509K (6962370412SG)**
[SJF7575L]

































TP











































GRAB RENTALS PTE LTD

Dec 9 2017 6:00PM

[NAJEEB OMAR TALIB]

Pegasus Engineering & Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/12/17 11:54	Accident Statement <small>From: SC - Reg. No: SJF7575L, Claimant: NAJEEB OMAR TALIB</small>	 Load HTM	
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 20:17	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 20:18	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/12/17 20:18	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/17 20:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 09:20	TP ESTIMATE- MARKED	 Load PDF	
2	14/12/17 09:20	TP GIA REPORT	 Load PDF	
3	19/12/17 10:01	LETTER TO OI	 Load PDF	
4	19/12/17 10:01	EMAIL TO OI	 Load PDF	
5	05/07/18 08:46	WORKSHOP INVOICE	 Load PDF	
6	05/07/18 08:46	AUTHORISATION TO ACT FORM	 Load PDF	
7	05/07/18 08:46	Release Voucher	 Load PDF	
8	05/07/18 08:46	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJF7575L (Insd veh)	Model:	HONDA VEZEL 1.5 X (A)
	SLR8509K (TP veh)		
Date of Accident:	09/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	10,784.02	
Final Repair Cost	: \$	5,778.00	
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	5.35	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	5,783.35	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	: \$	5,783.35
2)		: \$	

JOANNE LEE KHANG MIN

05 Jul
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023570/UHB3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100369956-03000

Claimant Vehicle No : SLR8509K

Insured Vehicle No : SJF7575L

Date of Loss: 09/12/2017

Nature of Claim: TP

Claim No: 6962370412SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8509K

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: LEB5953170

Reg. Date: 29/08/2017 (Man. Year: 2017)

Chassis No: RU31253162

Colour: Black

Odometer: 22734 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,258.52	4,271.12	1,987.40	31.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,520.00	1,300.00	34.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,078.52	6,791.12	3,287.40	32.62
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	10,078.52	5,400.00	4,678.52	46.42
+ GST 7.00/7.00% (S\$)	705.50	378.00	327.50	46.42
Nett Amount (S\$)	10,784.02	5,778.00	5,006.02	46.42
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		5,783.35		

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 12/12/2017 Inspected At:

Pegasus Engineering & Trading Pte Ltd (HQ)

51 DEFU LANE 10

Singapore 539216

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE LID	Badly Dented	953.30 FL	*953.30 FL
2	1	*TAILGATE LID LOCK TOP	Twisted	180.00 FL	*180.00 FL
3	1	*TAILGATE LID LOCK TOP STRIKE BOTTOM	Not Necessary	24.75 FL	*- FL
4	1	*TAILGATE LID WEATHERSTRIP	Twisted	135.00 FL	*135.00 FL
5	1	*TAILGATE LID VEZEL BADGE	Necessary	56.30 FL	*56.30 FL
6	1	*TAILGATE LID HYBRID BADGE	Necessary	66.20 FL	*66.20 FL
7	1	*N/S TAILGATE LID REFLECTOR	Not Necessary	43.20 FL	*- FL
8	1	*TAILGATE LID INNER TRIMBOARD	Not Necessary	225.00 FL	*- FL
9	2	*TAILGATE LID RUBBER STOPPER	Not Necessary	45.00 FL	*- FL
10	2	*TAILGATE HINGE	Not Necessary	52.00 FL	*- FL
11	1	*TAILGATE LID KEYLESS SENSOR	Not Necessary	85.60 FL	*- FL
12	2	*TAILGATE LID DAMPER	Not Necessary	36.00 FL	*- FL
13	1	*REAR WINDSHIELD GLASS WEATHERSTRIP	Necessary	120.00 FL	*120.00 FL
14	1	*REAR END PANEL	Badly Dented	514.00 FL	*514.00 FL
15	1	*REAR END PANEL INNER TRIM	Twisted	92.30 FL	*92.30 FL
16	6	*REAR END PANEL INNER TRIM CLIPS	Not Necessary	25.80 FL	*- FL
17	1	*REAR LUGGAGE FLOOR PANEL	Crumpled / Buckled	597.00 FL	*597.00 FL
18	1	*REAR LUGGAGE FLOOR INNER TRIMBOARD	Deformed / Cracked	190.00 FL	*190.00 FL
19	1	*REAR LUGGAGE FLOOR COMPARTMENT TRAY	Deformed	1,130.00 FL	*395.10 FL
20	1	*REAR BUMPER CENTRE	Dented	762.20 FL	*762.20 FL
21	1	*REAR BUMPER REFLECTOR	N/S Cracked	282.00 FL	*141.00 FL
22	2	*REAR BUMPER SCREW SPACER	Not Necessary	24.00 FL	*- FL
23	1	*N/S REAR BUMPER SIDE	Dented / Deformed	95.00 FL	*95.00 FL
24	2	*REAR BUMPER SIDE RETAINER	Not Necessary	46.00 FL	*- FL
25	10	*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
26	1	*REAR BUMPER DIFFUSER COVER	Distorted	95.00 FL	*95.00 FL
27	8	*REAR BUMPER DIFFUSER COVER CLIPS	Necessary	28.00 FL	*28.00 FL
28	1	*N/S REAR LAMP	Cracked	542.00 FL	*542.00 FL
29	4	*REAR LAMP CLIP HOLDER	Not Necessary	13.50 FL	*- FL
30	1	*REAR WINDSHIELD GLASS SEALANT	Necessary	180.00 FS	*40.00 FS
31	1	*REAR WINDSHIELD GLASS INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
32	1	*SET REAR BUMPER CENTRE PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
33	1	*REAR LICENSE PLATE	Not Necessary	80.00 FS	*- FS
34	1	*REAR LUGGAGE FLOOR PANEL INSULATION	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,558.15	5,271.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,299.63	1,000.28
Total Parts (\$\$)	6,258.52	4,271.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	30.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	80.00
3	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURE SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	550.00	0.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	80.00
6	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	60.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	1,200.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	900.00
Gross Labour Cost (S\$)			3,820.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >