

Messrs Grab Rentals Pte Ltd

Estimate To Repair Honda Vezel Hybrid 1.5X Auto  
Vehicle No : SLR8509K  
Chassis No : RU31253162

*Not Authorised  
12/12/17  
to be done before painting  
7 day.  
L/S @ 5400*

Third Party Insurer : AIG  
Insured's Veh No : SJF7575L  
Date of accident : 09.12.2017

Date: 11.12.2017

*req: Lkk Marcus  
12-12-2017 @ 0925hrs*

Pages : 1 of 2

| S/No              | Quantity | Description                         | Unit price  | Amount      |
|-------------------|----------|-------------------------------------|-------------|-------------|
| <b>LIST ITEMS</b> |          |                                     |             |             |
| 1                 | 1 pc     | tailgate lid                        | \$ 953.30   | \$ 953.30   |
| 2                 | 1 pc     | tailgate lid lock top               | \$ 180.00   | \$ 180.00   |
| 3                 | 1 pc     | tailgate lid lock top strike bottom | \$ 24.75    | \$ 24.75    |
| 4                 | 1 pc     | tailgate lid weatherstrip           | \$ 135.00   | \$ 135.00   |
| 5                 | 1 pc     | tailgate lid "Vezel" badge          | \$ 56.30    | \$ 56.30    |
|                   | 1 pc     | tailgate lid "hybrid" badge         | \$ 66.20    | \$ 66.20    |
| 7                 | 1 pc     | n/s tailgate lid reflector          | \$ 43.20    | \$ 43.20    |
| 8                 | 1 pc     | tailgate lid inner trimboard        | \$ 225.00   | \$ 225.00   |
| 9                 | 2 ps     | tailgate lid rubber stopper         | \$ 22.50    | \$ 45.00    |
| 10                | 2 ps     | tailgate hinge                      | \$ 26.00    | \$ 52.00    |
| 11                | 1 pc     | tailgate lid keyless sensor         | \$ 85.60    | \$ 85.60    |
| 12                | 2 ps     | tailgate lid damper                 | \$ 18.00    | \$ 36.00    |
| 13                | 1 pc     | rear windshield glass weatherstrip  | \$ 120.00   | \$ 120.00   |
| 14                | 1 pc     | rear end panel                      | \$ 514.00   | \$ 514.00   |
| 15                | 1 pc     | rear end panel inner trim           | \$ 92.30    | \$ 92.30    |
| 16                | 6 ps     | rear end panel inner trim clips     | \$ 4.30     | \$ 25.80    |
| 17                | 1 pc     | rear luggage floor panel            | \$ 597.00   | \$ 597.00   |
| 18                | 1 pc     | rear luggage floor inner trimboard  | \$ 190.00   | \$ 190.00   |
| 19                | 1 pc     | rear luggage floor compartment tray | \$ 1,130.00 | \$ 1,130.00 |
| 20                | 1 pc     | rear bumper centre                  | \$ 762.20   | \$ 762.20   |
| 21                | 2 ps     | rear bumper reflector               | \$ 141.00   | \$ 282.00   |
| 22                | 2 ps     | rear bumper screw spacer            | \$ 12.00    | \$ 24.00    |
| 23                | 1 pc     | n/s rear bumper side                | \$ 95.00    | \$ 95.00    |
| 24                | 2 ps     | rear bumper side retainer           | \$ 23.00    | \$ 46.00    |
| 25                | 10 ps    | rear bumper clips                   | \$ 3.90     | \$ 39.00    |
| 26                | 1 pc     | rear bumper diffuser cover          | \$ 95.00    | \$ 95.00    |
| 27                | 8 ps     | rear bumper diffuser cover clips    | \$ 3.50     | \$ 28.00    |
| 28                | 1 pc     | n/s rear lamp                       | \$ 542.00   | \$ 542.00   |
| 29                | 3 ps     | rear lamp clip holder               | \$ 4.50     | \$ 13.50    |
| Less 20%          |          |                                     |             | \$ 6,498.15 |
| Balance C/F       |          |                                     |             | \$ 1,299.63 |
|                   |          |                                     |             | \$ 5,198.52 |
|                   |          |                                     |             | \$ 5,198.52 |

Lkk Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To inspect damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary dam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date: **11.12.2017**

Estimate To Repair **Honda Vezel Hybrid 1.5X Auto**  
Vehicle No : **SLR8509K**  
Chassis No : **RU31253162**

2 of 2

| S/No | Quantity | Description                                                                                                                                     | Unit price  | Amount             |
|------|----------|-------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
|      |          | Balance B/F                                                                                                                                     |             | \$ 5,198.52        |
|      |          | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                |             |                    |
| 30   | 1 pc     | rear windshield glass sealant                                                                                                                   | \$ 180.00   | \$ 180.00          |
| 31   | 1 pc     | rear windshield glass inner sponge seal                                                                                                         | \$ 100.00   | \$ 100.00          |
| 32   | 1 set    | rear bumper centre parking sensor                                                                                                               | \$ 450.00   | \$ 450.00          |
| 33   | 1 pc     | rear license plate                                                                                                                              | \$ 80.00    | \$ 80.00           |
| 34   | 1 pc     | rear luggage floor panel insulation                                                                                                             | \$ 200.00   | \$ 250.00          |
|      |          |                                                                                                                                                 |             | \$ 880.00          |
|      |          | <b><u>LABOUR &amp; MISC. CHARGES</u></b>                                                                                                        |             |                    |
| 1    |          | To check electrical lighting concerned.                                                                                                         | 30          | \$ 40.00           |
| 2    |          | To rust-proofing of the affected areas.                                                                                                         | 80          | \$ 120.00          |
| 3    |          | To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack. | 11          | \$ 550.00          |
| 4    |          | To reinstall of rear bumper parking sensor.                                                                                                     | 50          | \$ 120.00          |
| 5    |          | To remove and refit interior fittings, trimmings, garnish and other, to enable repair.                                                          | 80          | \$ 120.00          |
| 6    |          | To transfer of tailgate fittings, fixture and perform waterseepage test.                                                                        | 60          | \$ 120.00          |
| 7    |          | To remove and refit rear windscreen glass.                                                                                                      | 120         | \$ 150.00          |
| 8    |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.                         | 1200        | \$ 1,600.00        |
| 9    |          | Putty and spray painting of the affected portion.                                                                                               | 900         | \$ 1,000.00        |
|      |          |                                                                                                                                                 |             | \$ 3,820.00        |
|      |          | <b>Grand Total</b>                                                                                                                              | <b>2790</b> | <b>\$ 9,268.52</b> |

Please conduct the survey at

**Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216**