

RALLY PITSTOP
176 SIN MING DRIVE
#04-17 SIN MING AUTOCARE
SINGAPORE 575721
TEL: 64516985 FAX: 68540685

FACSIMILE TRANSMITTAL SHEET

TO: Motor Claims Department	FROM: Terrence Lim
COMPANY: EQ Insurance	DATE: 11-Dec-17
FAX NUMBER: 62234190	TOTAL NO. OF PAGES INCLUDING COVER:
PHONE NUMBER: 62239433	SENDER'S REFERENCE NUMBER: SLF2409Z
RE: Estimate repair cost of SLF2409Z	YOUR REF NUMBER: SLR9476P

☐ URGENT
 ☐ FOR REVIEW
 ☐ PLEASE COMMENT
 ☒ PLEASE REPLY
 ☐ PLEASE RECYCLE

Dear Sir/Madam,

Vehicle No : SLF2409Z
 Make & Model : Toyota Harrier
 Date of accident : 08/12/2017

We are pleased to quote you the repair cost for above-mentioned vehicle:

QTY	PARTS DESCRIPTION	UNIT PRICE	TOTAL
1	Front bumper <i>deformed</i>		1235.90
5	Front bumper clips <i>hec</i>	3	15.00
1	Front left bumper retainer <i>hec</i>		67.90
1	Front bumper grille <i>dis.</i>		689.50
1	Towing cover <i>dis.</i>		78.60
1	Front bumper lower grille		325.40
1	Left head lamp <i>avg.</i>		1696.30
1	Right head lamp lower bracket		45.90
1	Front reinforcement		526.90
1	Front bumper right sponge		48.60
1	Front bumper center sponge		68.90
1	Front radiator panel <i>R.</i>	<i>R.</i>	523.80
	Sub-total before discount		5322.70
	Parts percentage discount 25%		1330.68
	PARTS TOTAL		3992.02

	LABOUR CHARGES & MISC		
1	Labour to dismantle, panel beat, change front bumper And all necessary parts.	600.00	500.
2	To putty and spray paint	600.00	400.
3	To provide undercoating	40.00	20.
	LABOUR TOTAL	1240.00	
	LABOUR & PARTS TOTAL	5232.02	

Thanks & Regards,

Terrence Lim

91005500

Not Authorised
PIP Repair
Before PUA Push
Lab And (MA)
Hw/days.
11/12/2017